

```

00001      *****
00002      ** DL Register Area - 120Word
00003      **
00004      ** DW00000 - DW00009 (PLS Use)
00005      ** DW00010 - DW00039 (Bit Use)
00006      ** DW00040 - DW00089 (Word Use)
00007      ** DW00090 - DW00119 (Timer)
00008      *****
00009
00010      "# Program Name   : [Step.11] Last Break Pusher Bar 1 Cycle
00011      "# Functior      :
00012      "# Call Program   :
00013      "# Sub Program    :
00014      "# Func Program   :
00015
00016      VAR;
00017
00018      END_VAR;
00019
00020 00000      PFORK CUTX TBL;
00021      " Cutter X Waiting Position
00022      CUTX:
00023
00024      " Cutter X Cutting After Escape Position
00025 00001      IF MB045741 == 0;
00026 00002      MW04514 = 11;
00027 00003      ing
00028 00004      it ON
00029 00005      Bit ON
00030 00006      it OFF
00031 00007      Bit ON
00032
00033 00008      IEND;
00034      JOINTO LabelX;
00035      TBL:
00036
00037      " [Action] Cutting Table Vacuum Off
00038 00009      IF !MB09023F == 1;
00039      " Cutting Table Vacuum Off
00040 00010      MB09053F = 1;
00041 00011      IEND;
00042 00012      MB09057F = 1;
00043 00013      IOW !MB09019F | MB00800 | MB000808 ==
00044 00014      IOW MB09027F | MB00800 | MB000808 ==
00045 00015      TIM TMW26216;
00046
00047      " Table Break Receive Position
00048 00016      IF MB045137 == 0
00049 00017      mplete Check
00050      IOW (MB000004 & MB030036) | !MB000004 == 1;
00051 00018      " [Action] Break Table Vacuum On
00052      IF !MB05684F == 1
00053 00019      " Break Table Vacuum On
00054 00020      MB05584F = 1;
00055 00021      IOW MB05684F | MB00800 == 1
00056 00022      TIM TMW26202;
00057 00023      IEND;
00058      IOW MB05684F | MB00800 == 1
00059
00060      " Transfer Z Home Position Check
00061      // IOW MB071020 == 1;
00062
00063 00024      " [ SC Int TBL ] Motion InterFace
00064 00025      IOW MW04522 == 0
00065 00026      MW04522 = 3;
00066 00027      MB045230 = 1;
00067 00028      IOW MB045231 == 1
00068 00029      MB045230 = 0;
00069 00030      IOW MB045231 == 0
00070 00031      MW04522 = 0;
00071 00032      IOW MB04572B == 0
00072
00073 00033      MB045137 = 1;
00074      Set
00075 00034      IEND;
00076      JOINTO LabelX;
00077 00035      LabelX: PJOINT,

```

```

00079
00080 00036      IOW MB045741 == 1                                " [ All ] Cutter X Waiting Positi
00081
00082      " Break Table Start Position
00083 00037      IF !MB56002 | !MB56022 | !MB56050 ==              " [ SC Req TBL ] Command Code ID S
00084          " [ SC Int TBL ] Motion InterFace
00085 00038          IOW MW04522 == 0                                " [ SC Req TBL ] Command Code ID Set
00086 00039          MW04522 = 3;                                    " [ SC Req TBL ] Command Code ID Set
00087 00040          MB045230 = 1;                                       " [ SC Req TBL ] Command Se
00088 00041          IOW MB045231 == 1                                " [ SC Res TBL ] Command Complete
00089 00042          MB045230 = 0;                                    " [ SC Req TBL ] Command Se

00090 00043          IOW MB045231 == 0                                " [ SC Res TBL ] Command Complete
00091 00044          MW04522 = 0;                                    " [ SC Req TBL ] Command Code ID Set
00092
00093 00045          IOW MB04572B == 0                                " TBL Moving Flag OF
00094 00046      IEND;
00095
00096 00047      IOW MB56003 & MB56023 == 1                        " TBL Start Position Check
00097
00098 00048      IF MB048921 == 1;
00099 00049          IF (MB051000 & MB051020) | (MB05102A & MB05100A) == 0;
00100              " [ SC ↔ BCHK ] Motion InterFace
00101 00050              MW04520 = 10;                                " [ SC Req BCHK ] Command Code ID Se
t
00102 00051              MB045210 = 1;                                " [ SC Req BCHK ] Command Se
00103 00052              IOW MB045211 == 1                            " [ SC Res BCHK ] Command Complete
00104 00053              MB045210 = 0;                                " [ SC Req BCHK ] Command Se

00105 00054              IOW MB045211 == 0                            " [ SC Res BCHK ] Command Complete
00106 00055              MW04520 = 0;                                " [ SC Req BCHK ] Command Code ID Se
t
00107
00108 00056              IOW MB04572A == 0                            " BCHK Moving Flag OFF
00109 00057      IEND;
00110 00058      ELSE;
00111          " Break Pusher Bar Waiting Position
00112 00059          IF !MB051000 | !MB051020 == 1;
00113              " [ SC ↔ BCHK ] Motion InterFace
00114 00060              MW04520 = 10;                                " [ SC Req BCHK ] Command Code ID Se
t
00115 00061              MB045210 = 1;                                " [ SC Req BCHK ] Command Se
00116 00062              IOW MB045211 == 1                            " [ SC Res BCHK ] Command Complete
00117 00063              MB045210 = 0;                                " [ SC Req BCHK ] Command Se

00118 00064              IOW MB045211 == 0                            " [ SC Res BCHK ] Command Complete
00119 00065              MW04520 = 0;                                " [ SC Req BCHK ] Command Code ID Se
t
00120
00121 00066              IOW MB04572A == 0                            " BCHK Moving Flag OFF
00122 00067      IEND;
00123 00068      IEND;
00124
00125 00069      IOW (MB051000 & MB051020) | (MB05102A & MB05100A) ==  " Break Pusher Bar Waiting Position
00126
00127 00070      IOW MB055696 & MB056003 == 1                        " Break Table Start Position
00128
00129      " Break Pusher Bar Clean 1 Cycle
00130 00071      IF MB048921 == 1;
00131          " Break Pusher Bar Clean Start Position
00132 00072          IF !MB5100A | !MB05102A == 1;
00133              " [ SC ↔ BCHK ] Motion InterFace
00134 00073              MW04520 = 11;                                " [ SC Req BCHK ] Command Code ID Se
t
00135 00074              MB045210 = 1;                                " [ SC Req BCHK ] Command Se
00136 00075              IOW MB045211 == 1                            " [ SC Res BCHK ] Command Complete
00137 00076              MB045210 = 0;                                " [ SC Req BCHK ] Command Se

00138 00077              IOW MB045211 == 0                            " [ SC Res BCHK ] Command Complete
00139 00078              MW04520 = 0;                                " [ SC Req BCHK ] Command Code ID Se
t
00140
00141 00079              IOW MB04572A == 0                            " BCHK Moving Flag OFF
00142 00080      IEND;
00143
00144      " Break Pusher Bar Clean End Position
00145 00081      IF !MB5100B | !MB05102A == 1;
00146          " [ SC ↔ BCHK ] Motion InterFace
00147 00082              MW04520 = 12;                                " [ SC Req BCHK ] Command Code ID Se
t
00148 00083              MB045210 = 1;                                " [ SC Req BCHK ] Command Se
00149 00084              IOW MB045211 == 1                            " [ SC Res BCHK ] Command Complete
00150 00085              MB045210 = 0;                                " [ SC Req BCHK ] Command Se

00151 00086              IOW MB045211 == 0                            " [ SC Res BCHK ] Command Complete
00152 00087              MW04520 = 0;                                " [ SC Req BCHK ] Command Code ID Se
t

```

```

00153
00154 00088          IOW MB04572A == 0          " BCHK Moving Flag OFF
00155 00089          IEND;
00156 00090          MB048901 = 1;
00157 00091          IEND;
00158
00159          // IF !MB090142 | !MB090143 == 1;
00160          //      " Cutting Table Brush Brush Up Stat
00161          //      MB090402 = 0;
00162          //      MB090403 = 0;
00163          //      TIM T100;
00164          //      MB090442 = 1;
00165          //      MB090443 = 1;
00166          //      TIM T300;
00167          //
00168          //      IOW (MB090142 & MB090143) | (MB090442 & MB090443) == 1;
00169          // IEND;
00170          " Cutting Table Brush Up Status
00171 00092          IF !MB09014E == 1;
00172          " Cutting Table Brush Brush Up Status
00173 00093          MB09040E = 0;
00174 00094          MB09044E = 1;
00175 00095          IOW MB09014E == 1;
00176 00096          IEND;
00177
00178 00097          IF !MB045139 & !MB050748 == 1          " [Last Pitch] Start Position Moving Com
plete Check
00179          " [ SC ↔ BCHK ] Motion InterFace
00180 00098          IOW MW04520 == 0          " [ SC Req BCHK ] Command Code ID Set
00181 00099          MW04520 = 7;          " [ SC Req BCHK ] Command Code ID Set
00182 00100          MB045210 = 1;          " [ SC Req BCHK ] Command Se
00183 00101          IOW MB045211 == 1          " [ SC Res BCHK ] Command Complete
00184 00102          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00185 00103          IOW MB045211 == 0          " [ SC Res BCHK ] Command Complete
00186 00104          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID Set
00187
00188 00105          IOW MB04572A == 0          " BCHK Moving Flag OFF
00189 00106          IOW MB050748 == 1          " Last Dummy Start Position
00190 00107          MB045139 = 1;          " [Last Pitch] Start Position Moving Com
plete Set
00191 00108          IEND;
00192
00193
00194 00109          IF MB04513A == 0          " [Last Pitch] Breaking Execute Moving C
omplete Check
00195          " [ SC ↔ BCHK ] Motion InterFace
00196 00110          IOW MW04520 == 0          " [ SC Req BCHK ] Command Code ID Set
00197 00111          MW04520 = 8;          " [ SC Req BCHK ] Command Code ID Set
00198 00112          MB045210 = 1;          " [ SC Req BCHK ] Command Se
00199 00113          IOW MB045211 == 1          " [ SC Res BCHK ] Command Complete
00200 00114          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00201 00115          IOW MB045211 == 0          " [ SC Res BCHK ] Command Complete
00202 00116          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID Set
00203
00204 00117          IOW MB04572A == 0          " BCHK Moving Flag OFF
00205
00206          " Breaking Execute Moving Complete
00207 00118          MB04513A = 1;          " [Last Pitch] Breaking Execute Moving C
omplete Set
00208 00119          MB05572F = 1;          " [Last Pitch] Breaking Executing Comple
te
00209
00210 00120          IEND;
00211
00212 00121          IF MB04513B == 0          " [Last Pitch] Standby Pos Moving Comple
te Check
00213          " Last Break Pusher Bar Waste Bit Set
00214 00122          MB050731 = 1;          " Last Break Pusher Bar Waste Bit Set
00215
00216          " [ SC ↔ BCHK ] Motion InterFace
00217 00123          IOW MW04520 == 0          " [ SC Req BCHK ] Command Code ID Set
00218 00124          MW04520 = 10;          " [ SC Req BCHK ] Command Code ID Set
00219 00125          MB045210 = 1;          " [ SC Req BCHK ] Command Se
00220 00126          IOW MB045211 == 1          " [ SC Res BCHK ] Command Complete
00221 00127          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00222 00128          IOW MB045211 == 0          " [ SC Res BCHK ] Command Complete
00223 00129          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID Set
00224
00225 00130          IOW MB04572A == 0          " BCHK Moving Flag OFF
00226
00227          " Standby Pos Moving Complete
00228 00131          MB04513B = 1;          " [Last Pitch] Standby Pos Moving Comple
te Set
00229

```

```
00230 00132      IEND;
00231
00232      " [Table Break] Carry Out Position Moving Complete
00233 00133      IF MB04513E == 0;
00234
00235      " [ SC Int TBL ] Motion InterFace
00236 00134      IOW MW05508 == 0          " TBL Command Code ID Check
00237 00135      IOW MW04522 == 0          " [ SC Req TBL ] Command Code ID Check
00238 00136      MW04522 = 5;                " [ SC Req TBL ] Command Code ID Set
00239 00137      MB045230 = 1;          " [ SC Req TBL ] Command Se
00240      //      IOW MB045231 == 1      " [ SC Res TBL ] Command Complete
00241 00138      IOW MB04572B == 1          " BKT Moving Flag ON
00242 00139      MB045230 = 0;          " [ SC Req TBL ] Command Se

00243      //      IOW MB045231 == 0      " [ SC Res TBL ] Command Complete
00244      //      MW04522 = 0;          " [ SC Req TBL ] Command Code ID Set
00245
00246      " Carry Out Position Moving Complete
00247 00140      MB04513E = 1;
00248 00141      IEND;
00249
00250      " InterFace Before Ready Complete
00251 00142      MB045724 = 1;
00252 00143      RET;
```