

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : [Step.12] Break Table 1 Cycle
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 00000 PFORK TBLU CUTX SCHY;
00021
00022 " Break Pusher Bar 1 Cycle & Cutter X Waiting Position
00023 TBLU:
00024 " Break Pusher Bar is Not Commar
00025 DW00010 = 0;
00026 WHILE DB000100 == 0;
00027 00003 IF MW04522 == 0 " [ SC Req BCHK ] Command Code ID Set
00028 00004 DB000101 = 1;
00029 00005 IEND;
00030 00006 IF MW05508 == 0 " [ SC Req BCHK ] Command Code ID Copy
00031 00007 DB000102 = 1;
00032 00008 IEND;
00033 00009 IF MB04572B == 0 " TBL Moving Flag Off Check
00034 00010 DB000103 = 1;
00035 00011 IEND;
00036 00012 IF MB051000 "& MB045741" == 1 " Break Pusher Bar Y Waiting Position, A
11 Cutter X Wait Position
00037 00013 DB000104 = 1;
00038 00014 IEND;
00039
00040 00015 IF (DB000101 & DB000102 & DB000103 & DB000104) == 1;
00041 00016 DB000100 = 1;
00042 00017 IEND;
00043 00018 EOX;
00044 00019 WEND;
00045
00046 " [Table Break] Start Position Moving Complete
00047 00020 IF !MB04513C | !MB055743 == 1;
00048 00021 IF !MB056003 | !MB056023 == 1;
00049 " [ SC Int TBL ] Motion InterFace
00050 00022 IOW MW04522 == 0 " [ SC Req TBL ] Command Code ID Set
00051 00023 MW04522 = 3; " [ SC Req TBL ] Command Code ID Set
00052 00024 MB045230 = 1; " [ SC Req TBL ] Command Se
00053 00025 IOW MB045231 == 1 " [ SC Res TBL ] Command Complete
00054 00026 MB045230 = 0; " [ SC Req TBL ] Command Se

00055 00027 IOW MB045231 == 0 " [ SC Res TBL ] Command Complete
00056 00028 MW04522 = 0; " [ SC Req TBL ] Command Code ID Set
00057
00058 " Table Break Motion Complete Checking
00059 00029 IOW MB04572B == 0;
00060 00030 IEND;
00061
00062 " Start Position Moving Complete
00063 00031 MB04513C = 1;
00064 00032 IEND;
00065
00066 " [Table Break] Breaking Execute Complete
00067 00033 IF MB04513D == 0;
00068
00069 00034 IOW MB046084 == 1 " Scribe Chuck Y Break Position Check
00070 00035 IOW MW04518 == 0 " [ SC Req SCHK ] Command Code ID S

00071 " [ SC Int TBL ] Motion InterFace
00072 00036 IOW MW04522 == 0 " [ SC Req TBL ] Command Code ID Set
00073 00037 MW04522 = 4; " [ SC Req TBL ] Command Code ID Set
00074 00038 MB045230 = 1; " [ SC Req TBL ] Command Se
00075 00039 IOW MB045231 == 1 " [ SC Res TBL ] Command Complete
00076 00040 MB045230 = 0; " [ SC Req TBL ] Command Se

00077 00041 IOW MB045231 == 0 " [ SC Res TBL ] Command Complete
00078 00042 MW04522 = 0; " [ SC Req TBL ] Command Code ID Set
00079
00080 " Breaking Execute Complete
00081 00043 MB04513D = 1;
00082 00044 MB05572F = 1; " Table Breaking Executing Comple

```

```

00083 00045      IEND;
00084
00085      " [Table Break] Carry Out Position Moving Complete
00086 00046      IF MB04513E == 0;
00087
00088      " [ SC Int TBL ] Motion InterFace
00089 00047      IOW MW05508 == 0          " TBL Command Code ID Check
00090 00048      IOW MW04522 == 0          " [ SC Req TBL ] Command Code ID Check
00091 00049      MW04522 = 5;              " [ SC Req TBL ] Command Code ID Set
00092 00050      MB045230 = 1;              " [ SC Req TBL ] Command Se
00093 00051      IOW MB04572B == 1;
00094
00095      //IOW MB045231 == 1          " [ SC Res TBL ] Command Complete
00096 00052      MB045230 = 0;          " [ SC Req TBL ] Command Se

00097      //IOW MB045231 == 0          " [ SC Res TBL ] Command Complete
00098      //MW04522 = 0;              " [ SC Req TBL ] Command Code ID Set
00099
00100
00101      " Carry Out Position Moving Complete
00102 00053      MB04513E = 1;
00103 00054      IEND;
00104
00105 00055      JOINTO LabelX;
00106
00107      CUTX:
00108      " Cutter X, Cutter Shift Y Next Alignment Position
00109 00056      IF MB045741 == 0;
00110 00057      IOW MW04514 == 0;
00111 00058      IF MB262800 == 1          " ML26280 : Align, Table Break Head
                                " Head Align Pos.
00112 00059      Move Same Time(0:Unuse/1:Odd Use/2:Even Use/3:All Use)
                                " Head Escape Pos.
00113 00060      MW04514 = 2;
00114 00061      ELSE;
00115 00062      MW04514 = 11;
00116 00063      IEND;
                                " Scribe → Scribe Cutter Command Ex
                                " Scribe ← Scribe Cutter Command Co
00117 00064      ecute Bit ON      IOW MB045151 == 1
                                " Scribe → Scribe Cutter Command Ex
                                " Scribe ← Scribe Cutter Command Co
00118 00065      mplete Bit ON   MB045150 = 0;
00119 00066      ecute Bit OFF      IOW MB045151 == 0
                                " Scribe → Scribe Cutter Command Ex
                                " Scribe ← Scribe Cutter Command Co
                                mplete Bit OFF

00120
00121      // Temporary Add by kkw, will change Condition
00122      // IOW ML16064 == ML01656
                                " 미리 얼라이먼트 위치 간 상태를 인터락으
                                " 샘플 양산 대응 임시 조치, 인텍스 자동
00123      로 확인하고 있음, CW00009 해제시 필요 여부 판단 필요

00124 00067      투입 정상화시 주석 해제 요망
00125      IEND;
00126 00068      JOINTO LabelX;
00127
00128      SCHY:
00129
00130      " Scribe Y Break Position
00131 00069      IOW (MB056003 & MB056023) | MB045013 ==          " Break Table Start Position Moving Complete

00132 00070      IF !MB046084 & !MB045013 == 1          " Scribe Chuck Y Break Position Check
00133 00071      IOW MW04518 & MW04522 == 0          " Scribe Chuck & Break Table No Command
00134 00072      MW04518 = 14;          " Scribe → Scribe Chuck Command Code Settin

00135 00073      g      MB045190 = 1;          " Scribe → Scribe Chuck Command Execute Bit
                                On
00136 00074      IOW MB045191 == 1          " Scribe ← Scribe Chuck Command Complete Bi
                                t On
00137 00075      MB045190 = 0;          " Scribe → Scribe Chuck Command Execute Bit
                                Reset
00138 00076      IOW MB045191 == 0          " Scribe ← Scribe Chuck Command Complete Bi
                                t Resedt

00139
00140 00077      IOW MB046084 == 1          " Scribe Chuck Y Break Position Check
00141 00078      IEND;
00142
00143 00079      JOINTO LabelX;
00144
00145 00080      LabelX: PJOINT,
00146
00147 00081      RET;

```