

```

00001      "*****
00002      "** DL Register Area - 120Word
00003      "**
00004      "** DW00000 - DW00009 (PLS Use)
00005      "** DW00010 - DW00039 (Bit Use)
00006      "** DW00040 - DW00089 (Word Use)
00007      "** DW00090 - DW00119 (Timer)
00008      "*****
00009
00010      "# Program Name   :   Camera Start/End Move
00011      "# Functionior   :
00012      "# Call Program   :
00013      "# Sub Program    :
00014      "# Func Program   :
00015
00016      VAR;
00017
00018      END_VAR;
00019
00020      " Index Calc
00021      " Cutter Z All Waiting Pos
00022 00000      IF MB045740 | MB045743 == 0;
00023 00001          IOW MW04842 == 0;
00024 00002          MW4842 = 41;
00025 00003          MSEE MPS198;
00026 00004          MW4842 = 0;
00027 00005          IOW MW4842 == 0;
00028 00006      IEND;
00029
00030      " Camera Cutter X, L-Camera Y Move:
00031 00007      IOW MW04514 == 0;
00032 00008      MW04514 = 6;
00033 00009      Setting
te Bit ON
00034
00035 00010      PLD [LCAMY];
00036 00011      IF MW00051 == 85;
00037 00012          ML16074 = ML43730 + ML15218;
00038 00013      IEND;
00039 00014      IF MW00051 == 86;
00040 00015          ML16074 = ML43730 + ML15222;
00041 00016      IEND;
00042 00017      MOV [LCAMY]ML16074
00043
00044 00018      IOW MB045151 == 1
ete Bit ON
00045 00019      MB045150 = 0;
te Bit OFF
00046 00020      IOW MB045151 == 0
ete Bit ON
00047
00048 00021      RET;

```

" Scribe Req Scribe Cutter Command Code

" Scribe Req Scribe Cutter Command Execu

" Scribe Res Scribe Cutter Command Compl

" Scribe Req Scribe Cutter Command Execu

" Scribe Res Scribe Cutter Command Compl