

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : Alignment Position Move
00011 "# Functior :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017 " Scribe Cutter
00018 00000 LONG IDX_CX = 32;
00019 00001 LONG IDX_CAMX = 33;
00020 " Scribe Shift
00021 00002 LONG IDX_CS = 35;
00022 " Scribe Chuck
00023 00003 LONG IDX_SCHY1 = 48;
00024 00004 LONG IDX_SCHY2 = 49;
00025 " Scribe Camera
00026 00005 LONG IDX_LCAMY = 37;
00027 00006 LONG IDX_LCAMZ = 38
00028 00007 LONG IDX_RCAMY = 39
00029 00008 LONG IDX_RCAMZ = 40;
00030 END_VAR;
00031
00032 " Scribe Chuck Y
00033 00009 IF MB030035 == 1;
00034 00010 IF MB09018E | MB000800 == 1 " [Sensor] SCT Scribe Chuck All Vacuum On
00035 " [Request] Moving Position
00036 00011 IF !MB04574C == 1;
00037 00012 MW04820 = 40;
00038 00013 MSEE MPS256;
00039 00014 IOW MB04574C == 1 " All SCHZ Moving Pos Check
00040 00015 IEND;
00041 00016 ELSE;
00042 " [Request] Vacuum Position
00043 00017 MW04820 = 41;
00044 00018 MSEE MPS256;
00045 00019 IOW MB04574B == 1 " All SCHZ Vacuum Pos Check
00046
00047 00020 MB09048E = 1;
00048 00021 IOW MB09018E == 1 " [Sol] SCT Scribe Chuck All Vacuum On
00049 " [Sensor] SCT Scribe Chuck All Vacuum On
00050 " [Request] Moving Position
00051 00022 MW04820 = 40;
00052 00023 MSEE MPS256;
00053 00024 IOW MB04574C == 1 " All SCHZ Moving Pos Check
00054 00025 IEND;
00055 00026 ELSE;
00056 00027 MB09052E = 1;
00057 00028 MB090560 = 1;
00058 00029 IOW MB09022E & MB090260 == 1 " [Sol] SCT Scribe Chuck All Vacuum Off
00059 " [Sol] SCT Scribe Chuck 1,2,3,4 Blow On
00060 00030 TIM TMW26214;
00061 00031 MB090600 = 1;
00062 00032 IOW MB090300 == 1 " [Sensor] SCT Scribe Chuck 1,2,3,4 Blow On
00063 " Scribe Chuck Vacuum Break Complete Timer
00064 " [Request] Standby Position
00065 00033 MW04820 = 39;
00066 00034 MSEE MPS256;
00067 00035 IOW MB04574A == 1 " All SCHZ Standby Pos Check
00068 00036 IEND;
00069
00070 " [Parameter] Chuck Y - Cutter X Interference Escape 30 m
00071 " Chuck Interference Check
00072 00037 DL00026 = ML04874 - ML26324;
00073 00038 IF !MB046082 & !MB046083 == 1;
00074 00039 IOW ILA816 < DL00026;
00075 00040 IEND;
00076
00077 " Cutter Z Waiting Position
00078 00041 IF MB045740 | MB045743 == 0;
00079 00042 IOW MW04842 == 0;
00080 00043 MW04842 = 41;
00081 00044 MSEE MPS198;
00082 00045 MW04842 = 0;
00083 00046 IOW MW04842 == 0;
00084 00047 IEND;
00085
00086 " Cutter Z Waiting Position Check
00087 00048 IOW MB045740 | MB045743 == 1;

```

```

00088
00089      " Last Scribe Pitch Check
00090 00049      DB00020 = 0;
00091 00050      IF GL21158 <= MW15411;
00092 00051          DB00020 = 1;
00093 00052      IEND;
00094
00095 00053      IF MB000004 == 1;
00096 00054          IF DB00020 == 1;
00097              " [Chuck Y Orign Position ↔ Camera Lens Center] - Chuck Y Escape Parameter

00098 00055          IF !MB046082 & !MB046083 == 1;
00099 00056              IOW ILA816 < ML04874 - ML26324;
00100 00057          IEND;
00101 00058          IOW MW04514 <> 1;
00102
00103      " Cutter X, Cutter Shift Y Waiting Position
00104 00059      IF MB045741 == 0;
00105 00060          MW04514 = 1;          " Scribe Req Scribe Cutter Command Code

00106 00061      Setting          MB045150 = 1;          " Scribe Req Scribe Cutter Command Execu
te Bit On
00107 00062          IOW MB045151 == 1          " Scribe Res Scribe Cutter Command Compl
ete Bit On
00108 00063          MB045150 = 0;          " Scribe Req Scribe Cutter Command Execu
te Bit Off
00109 00064          IOW MB045151 == 0          " Scribe Res Scribe Cutter Command Compl
ete Bit On

00110 00065          IEND;
00111 00066          IEND;
00112 00067          IEND;
00113
00114 00068      TIM TMW26210;
00115
00116      " Interference Step Bit Reset
00117 00069      DW000030 = 0;
00118 00070      PFORK ChuckY CutterX CamY PusherZ;
00119
00120      ChuckY:
00121          " Scribe Chuck Y
00122
00123 00071      IF MB04524A == 0;
00124          " Scribe Chuck Y Alignment Position
00125 00072          IOW MW04518 == 0;
00126 00073          IF MB047361 == 1          " Dummy Align Seach Fla
00127 00074          MW04518 = 13;          " Scribe Req Scribe Chuck Command Code A
lignment Position

00128
00129 00075          MB045190 = 1;          " Scribe Req Scribe Chuck Command Execut
e Bit On
00130 00076          IOW MB045191 == 1          " Scribe Res Scribe Chuck Command Comple
te Bit On
00131 00077          MB045190 = 0;          " Scribe Req Scribe Chuck Command Execut
e Bit Off
00132 00078          IOW MB045191 == 0          " Scribe Res Scribe Chuck Command Comple
te Bit Or

00133 00079      ELSE;
00134 00080          IF MB046083 == 0;          " Scribe Chuck Trasfer Y Alignment Posit
ion
00135 00081          MW04518 = 4;          " Scribe Req Scribe Chuck Command Code A
lignment Position
00136 00082          MB045190 = 1;          " Scribe Req Scribe Chuck Command Execut
e Bit On
00137 00083          IOW MB045191 == 1          " Scribe Res Scribe Chuck Command Comple
te Bit On
00138 00084          MB045190 = 0;          " Scribe Req Scribe Chuck Command Execut
e Bit Off
00139 00085          IOW MB045191 == 0          " Scribe Res Scribe Chuck Command Comple
te Bit Or

00140 00086      ELSE;
00141 00087          IOW MB49440 == 0;
00142 00088          MB49440 = 1;
00143 00089          EOX;
00144 00090          IF MB00201D == 1          " P Work : Dumm
00145 00091          MW04846 = 10;
00146 00092          MW04848 = 6;
00147 00093          IF MB030034 | (MB071023 & MB045281 & MB070271) == 1;
00148 00094              MW04946 = 1;          " [Fix] Table Vacuum On
00149 00095              MW04948 = 2;          " [Fix] Table Blow Off
00150 00096          ELSE;
00151 00097              MW04946 = 2;          " [Fix] Table Vacuum Off
00152 00098              MW04948 = 1;          " [Fix] Table Blow On
00153 00099          IEND;
00154 00100          MSEE MPS259;          " Table Vacuum & Floatin
00155 00101      ELSE;
00156 00102          MW04846 = 1;
00157 00103          MW04848 = 6;

```

```

00158 00104          IF MB030034 | (MB071023 & MB045281 & MB070271) == 1;
00159 00105          MW04946 = 1;          " [Fix] Table Vacuum On
00160 00106          MW04948 = 2;          " [Fix] Table Blow Off
00161 00107          ELSE;
00162 00108          MW04946 = 2;          " [Fix] Table Vacuum Off
00163 00109          MW04948 = 1;          " [Fix] Table Blow On
00164 00110          IEND;
00165 00111          MSEE MPS259;          " Table Vacuum & Floatin
00166 00112          IEND;
00167 00113          MB49440 = 0;
00168 00114          IEND;
00169 00115          IEND;
00170 00116          IEND;
00171
00172          " Last Scribe Pitch
00173 00117          IF DB00020 == 1
00174              " Last Dummy Panel
00175 00118              IF MB030035 & !MB030036 == 1;
00176 00119                  IF CW00099 == 1;
00177 00120                      IF MB048920 == 1          " Fix Table Brush Action
00178 00121                          IF !MB090140 | !MB090141 == 1;
00179 00122                              " Fix Table Brush Up Status
00180 00122                                  MB090400 = 0;
00181 00123                                  MB090401 = 0;
00182 00124                                  EOX;
00183 00125                                  MB090440 = 1;
00184 00126                                  MB090441 = 1;
00185 00127                                  MB09061D = 1;          " Fix Table Brush Blow Off
00186 00128                                  IEND;
00187 00129                                  IEND;
00188 00130                                  IEND;
00189
00190              " [Request] Vacuum Position
00191 00131              MW04820 = 41;
00192 00132              MSEE MPS256;
00193 00133              IOW MB04574B == 1          " All SCHZ Vacuum Pos Check
00194
00195              " Break Table Vacuum On, Cutting Table Vacuum On
00196 00134              IOW MB49440 == 0;
00197 00135              MB49440 = 1;
00198 00136              MW04846 = 5;
00199 00137              MW04848 = 6;
00200 00138              EOX;
00201          //          IF MB030034 == 1;
00202          //              MW04946 = 1;          " [Fix] Table Vacuum On
00203          //              MW04948 = 2;          " [Fix] Table Blow Off
00204          //          ELSE;
00205          //              MW04946 = 2;          " [Fix] Table Vacuum Off
00206          //              MW04948 = 1;          " [Fix] Table Blow On
00207          //          IEND;
00208 00139              MW04946 = 10;          " [Fix] Table Vacuum Off
00209 00140              MW04948 = 10;          " [Fix] Table Blow On
00210 00141              MSEE MPS259;          " Table Vacuum & Floating
00211 00142              MB49440 = 0;
00212
00213 00143              MB09052E = 1;          " [Sol] SCT Scribe Chuck All Vacuum Off
00214 00144              MB090560 = 1;          " [Sol] SCT Scribe Chuck 1,2,3,4 Blow On
00215 00145              IOW MB09022E & MB090260 == 1          " [Sensor] SCT Scribe Chuck All Vacuum Off
00216              " [Sensor] SCT Scribe Chuck 1,2,3,4 Blow On
00217 00146              TIM TMW26214;          " Scribe Chuck Vacuum Break Complete Timer
00218
00219 00147              IF CW00099 == 1;
00220 00148              ELSE;
00221 00149                  MB090600 = 1;          " [Sol] SCT Scribe Chuck 1,2,3,4 Blow Off
00222 00150                  IOW MB090300 == 1          " [Sensor] SCT Scribe Chuck 1,2,3,4 Blow Off
00223 00151              IEND;
00224
00225 00152              IF MB048920 == 1          " Fix Table Brush Action
00226                  " Fix Table Brush Up Status
00227 00153                      IF !MB090140 | !MB090141 == 1;
00228 00154                          MB090400 = 0;
00229 00155                          MB090401 = 0;
00230 00156                          IF CW00099 == 1;
00231 00157                              EOX;
00232 00158                              ELSE;
00233 00159                                  TIM T100;
00234 00160                                  IEND;
00235 00161                                  MB090440 = 1;
00236 00162                                  MB090441 = 1;
00237 00163                                  MB09061D = 1;          " Fix Table Brush Blow Off
00238 00164                                  IEND;
00239 00165                                  IF CW00099 == 1;
00240 00166                                  ELSE;
00241 00167                                      IOW MB090140 & MB090141 == 1;
00242 00168                                      MB048900 = 1;          " Fix Table Brush Action Comp
00243 00169                                      IEND;
00244 00170                                      IEND;

```

```

00245
00246 00171      IF CW00099 == 1;
00247             "→ Glass Data Move
00248 00172             MB002484 = 1;
00249 00173      IEND;
00250
00251             " [Request] Standby Position
00252 00174      MW04820 = 39;
00253 00175      MSEE MPS256;
00254 00176      IOW MB04574A == 1              " All SCHZ Standby Pos Check
00255
00256 00177      IF CW00099 == 1;
00257 00178             IOW MB090140 & MB090141 == 1;
00258 00179             MB048900 = 1;              " Fix Table Brush Action Comp
00259 00180      IEND;
00260
00261             "→ Glass Data Move
00262 00181      IF CW00099 == 1;
00263 00182             IF !MB030036 == 1;
00264 00183                 MB002484 = 1;
00265 00184             IEND;
00266 00185      ELSE;
00267 00186                 MB002484 = 1;
00268 00187             IEND;
00269 00188      IOW MB030036 == 1;
00270 00189      IOW MB030035 == 0;
00271 00190      IEND;
00272
00273             " Last Dummy Alignment Position Move Permission
00274 00191      DB00300 = 1;
00275             " Last Dummy Chuck Receive Poition
00276 00192      MB045707 = 1;              " Conveyor Not Sync Mode
00277
00278 00193      IF CW00017 == 1;
00279 00194          DB000030 = 0;
00280 00195          IF ML26288 == 1              " [EQ]Scirbe Chuck Brush Mode (0:Unuse 1:Use
)
00281             " Table Brush Position Move
00282 00196             IF MB030032 == 1;
00283
00284             ELSE;
00285 00198                 DB000030 = 1;
00286 00199             IEND;
00287
00288 00200             IF DB000030 & !MB030034 & !MB030035 & MB046083 == 1;
00289 00201                 IOW MW04518 == 0
00290 00202                 IOW MB045190 == 0;
00291 00203                 MW04518 = 16;
00292 00204                 MB045190 = 1;
00293 00205                 IOW MB045191 == 1;
00294 00206                 MB045190 = 0;
00295 00207                 IOW MB045191 == 0;
00296
00297 00208                 MB090400 = 1;              " Fix Table Brush Down
00298 00209                 MB090401 = 1;
00299 00210                 MB090440 = 0;
00300 00211                 MB090441 = 0;
00301
00302 00212                 IOW MB090100 & MB090101 == 1;
00303 00213             IEND;
00304 00214             IEND;
00305 00215      IEND;
00306             " Lower Safety Position Move
00307 00216      IF MB071003 & !MB071020 == 1;
00308 00217          IOW MW04518 == 0
00309 00218          IOW MB045190 == 0;
00310 00219          MW04518 = 15;
00311 00220          MB045190 = 1;
00312 00221          IOW MB045191 == 1;
00313 00222          MB045190 = 0;
00314 00223          IOW MB045191 == 0;
00315 00224      IEND;
00316
00317             " Scribe Chuck Y Receive Position.
00318 00225      IF !MB046080 | !MB046081 == 1;
00319 00226          IOW MW04518 == 0;
00320 00227          IF MB030034 == 1;
00321 00228              MW04518 = 2;              " Scribe Req Scribe Chuck Command Code Setti
ng
00322 00229      ELSE;
00323 00230          MW04518 = 1;
00324 00231      IEND;
00325 00232      MB045190 = 1;              " Scribe Req Scribe Chuck Command Execute Bi
t On
00326 00233      IEND;
00327
00328             " [Chuck Y Orign Position ↔ Camera Lens Center] - Chuck Y Escape Parameter

```

```

00329 00234      IOW ILA816 < ML04874 - ML26324;
00330      //IOW ILA816 < ML26336 - 500;
00331
00332 00235      IF !MB000004 & MB045013 == 1;
00333 00236      IOW MB045191 == 1      " Scribe Res Scribe Chuck Command Complete B
it On
00334 00237      MB045190 = 0;      " Scribe Req Scribe Chuck Command Execute Bi
t Off
00335 00238      IOW MB045191 == 0      " Scribe Res Scribe Chuck Command Complete B
it On
00336 00239      IEND;
00337
00338      //MB045190 = 0;      " Scribe Req Scribe Chuck Command Execute Bi
t Off
00339
00340 00240      IEND;
00341
00342 00241      JOINTO Label3X,
00343
00344      CutterX:
00345      " Scribe Cutter X
00346      " Scribe Chuck ↔ Cutter X Escape Position Waiting
00347 00242      IF DB00020 == 1;
00348      " [Parameter] Chuck Y - Cutter X Interference Escape 30 m
00349 00243      IOW DB00300 == 1;
00350      " [Chuck Y Orign Position ↔ Camera Lens Center] - Chuck Y Escape Parameter

00351 00244      IOW ILA816 < ML04874 - ML26324;
00352 00245      ELSE;
00353 00246      IF ML26280 <> 3      " Align Head Move Same Time(0:Unuse/
1:Odd Use/2:Even Use/3:All Use)
00354 00247      DW00020 = MW12513;
00355 00248      DW00021 = MOD;
00356 00249      IF ML26280 == 1;
00357 00250      IF DW00021 == 1;
00358 00251      IOW MB046083 == 1;
00359 00252      IOW MB09019F | MB00800 | MB000808 ==      " Cutting Table Vacuum On Check
00360 00253      IEND;
00361 00254      IEND;
00362 00255      IF ML26280 == 2;
00363 00256      IF DW00021 == 0;
00364 00257      IOW MB046083 == 1;
00365 00258      IOW MB09019F | MB00800 | MB000808 ==      " Cutting Table Vacuum On Check
00366 00259      IEND;
00367 00260      IEND;
00368 00261      IF ML26280 == 0;
00369 00262      IOW MB046083 == 1;
00370 00263      IOW MB09019F | MB00800 | MB000808 ==      " Cutting Table Vacuum On Check
00371 00264      IEND;
00372 00265      IEND;
00373 00266      IEND;
00374
00375 00267      IF MB047361 == 1      " Dummy Align Seach Flag
00376      " Scribe Cutter X Dummy Alignment Position Movi
00377 00268      IOW MW04514 == 0;
00378 00269      MW04514 = 21;      " Scribe Req Scribe Cutter Command Code
Setting
00379 00270      MB045150 = 1;      " Scribe Req Scribe Cutter Command Execu
te Bit On
00380 00271      IOW MB045151 == 1      " Scribe Res Scribe Cutter Command Compl
ete Bit On
00381 00272      MB045150 = 0;      " Scribe Req Scribe Cutter Command Execu
te Bit Off
00382 00273      IOW MB045151 == 0      " Scribe Res Scribe Cutter Command Compl
ete Bit On
00383 00274      ELSE;
00384 00275      IF (MB046001 & MB046011) == 0;      " Cutter X Alignment Positic
00385      " Scribe Cutter X Alignment Position Movi
00386 00276      IOW MW04514 == 0;
00387 00277      MW04514 = 2;      " Scribe Req Scribe Cutter Command Code
Setting
00388 00278      MB045150 = 1;      " Scribe Req Scribe Cutter Command Execu
te Bit On
00389 00279      IOW MB045151 == 1      " Scribe Res Scribe Cutter Command Compl
ete Bit On
00390 00280      MB045150 = 0;      " Scribe Req Scribe Cutter Command Execu
te Bit Off
00391 00281      IOW MB045151 == 0      " Scribe Res Scribe Cutter Command Compl
ete Bit Or
00392 00282      IEND;
00393 00283      IEND;
00394 00284      JOINTO Label3X;
00395
00396      CamY:
00397
00398 00285      DL00040 = (MW15410 - 1) * 5(      " Break Pitch Data Block Offset

```

```

00399 00286      DL00042 = (MW15410 - 1) * 10(           " Scribe Pitch Data Block Offset
00400 00287      DL00044 = GL500054[DL00040] - ML26340;
00401 00288      DL00050 = GL100024[DL00042] - GL100036[DL00042;   " Scirbe Start Y Pitch
00402 00289      DL00052 = GL100032[DL00042] - GL100036[DL00042   " Scirbe End Y Pitch
00403 00290      ML16074 = ML43730 - DL00044 - DL00050;
00404 00291      ML16076 = ML43830 - DL00044 - DL0005
00405
00406 00292      PLD [LCAMY][RCAMY];
00407 00293      MOV [LCAMY]ML16074 [RCAMY]ML16074;
00408
00409 00294      JOINTO Label13X;
00410
00411      PusherZ:
00412 00295          IF ML26274 == 1;
00413 00296          IF DB00020 == 1;
00414 00297              IOW MB046083 | MB046080 | MB046081 == 1;
00415                  " [Chuck Y Orign Position ↔ Camera Lens Center] - Chuck Y Escape Parameter

00416 00298          IOW ILA816 < ML27820 - ML27826;
00417
00418 00299          IF MB048921 == 1;
00419              " Break Pusher Bar Clean Start Position
00420 00300          IF !MB5100A | !MB05102A == 1;
00421              " [ SC ↔ BCHK ] Motion InterFace
00422 00301              MW04520 = 11;           " [ SC Req BCHK ] Comman

00423 00302          d Code ID Set              MB045210 = 1;           " [ SC Req BCHK ] Comman
00424 00303          d Set                      IOW MB045211 == 1       " [ SC Res BCHK ] Comman
00425 00304          d Complete                MB045210 = 0;           " [ SC Req BCHK ] Comman
00426 00305          d Set                      IOW MB045211 == 0       " [ SC Res BCHK ] Comman
00427 00306          d Complete                MW04520 = 0;           " [ SC Req BCHK ] Comman
00428          d Code ID Set
00429 00307          IOW MB04572A == 0           " BCHK Moving Flag OFF
00430 00308          IEND;
00431 00309          IEND;
00432 00310          IEND;
00433 00311          IEND;
00434 00312          JOINTO Label13X;
00435
00436 00313          Label13X: PJOINT;
00437
00438 00314          RET;

```