

```

00001      ** DL Register Area - 120Word
00002      **
00003      ** DW00000 - DW00009 (PLS Use)
00004      ** DW00010 - DW00039 (Bit Use)
00005      ** DW00040 - DW00089 (Word Use)
00006      ** DW00090 - DW00119 (Timer)
00007      ****
00008
00009      "# Program Name      : [Loading] Alignment Before 1 Cycle
00010      "# Function      :
00011      "# Call Program    :
00012      "# Sub Program     :
00013      "# Func Program    :
00014
00015      VAR;
00016
00017      END_VAR;
00018
00019 00000      IF !MB045123 | !MB030035 == 1                                " Scribe Chuck Close Complete Bit Check
00020 00001      IF MB000004 & (MB046080 | MB046081) & MB030034 & !MB045013 == 1;
00021 00002      MW04518 = 2;                                                " Scribe Req Scribe Chuck Command Code A
                                lignment Position
00022 00003      MB045190 = 1;                                            " Scribe Req Scribe Chuck Command Execut
                                e Bit On
00023 00004      IOW MB045191 == 1                                        " Scribe Res Scribe Chuck Command Comple
                                te Bit On
00024 00005      MB045190 = 0;                                          " Scribe Req Scribe Chuck Command Execut
                                e Bit Off
00025 00006      IOW MB045191 == 0                                        " Scribe Res Scribe Chuck Command Comple
                                te Bit On
00026
00027 00007      IF MB030034 & MB046081 "& MB04512F" == 1;
00028 00008      IF !MB09018E == 1                                          " [Request] Vacuum Position
00029 00009      MW04820 = 41;
00030 00010      MSEE MPS256;
00031 00011      IOW MB04574B == 1                                        " All SCHZ Vacuum Pos Check
00032
00033 00012      MB09048E = 1;                                            " [Sol] SCT Scribe Chuck All Vacuum
                                On
00034
00035 00013      IOW MB49440 == 0;
00036 00014      MB49440 = 1;
00037 00015      MW04846 = 10;
00038 00016      MW04848 = 10;
00039 00017      MW04946 = 2;                                            " [Fix] Table Vacuum Off
00040 00018      MW04948 = 1;                                            " [Fix] Table Blow On
00041 00019      MSEE MPS259;                                          " Table Vacuum & Floating
00042 00020      MB49440 = 0;
00043
00044 00021      IOW MB09018E == 1                                        " [Sensor] SCT Scribe Chuck All Vacu
                                um On
00045
00046      //      IOW MB49440 == 0;
00047      //      MB49440 = 1;
00048      //      MW04846 = 10;
00049      //      MW04848 = 10;
00050      //      MW04946 = 2;                                            " [Fix] Table Vacuum Off
00051      //      MW04948 = 2;                                            " [Fix] Table Blow Off
00052      //      MSEE MPS259;                                          " Table Vacuum & Floating
00053
00054      //      MB49440 = 0;
00055 00022      TIM T200;
00056      " [Request] Moving Position
00057 00023      MW04820 = 40;
00058 00024      MSEE MPS256;
00059 00025      IOW MB04574C == 1                                        " All SCHZ Moving Pos Check
00060 00026      IOW MB09018E == 1                                        " [Sensor] SCT Scribe Chuck All Vacu
                                um On
00061 00027      IEND;
00062
00063      " Motion Code Don't Reset_Break Complete Waiti
00064 00028      IOW !MB030036 | (MB030036 & MB05572F) | MB045013 == 1;
00065
00066      " Glass Data Managerment
00067 00029      IOW MB09018E == 1;
00068 00030      IF MB09018E & !MB045013 == 1;
00069 00031      MB002483 = 1;                                                " Scribe Feed → Scribe
00070 00032      IOW MB030035 == 1                                        " Scribe Glass Data OK
00071 00033      IEND;
00072
00073 00034      IF MB000004 & !MB030034 == 1
00074 00035      MB045123 = 1;                                            " Chcuk Close Complete Bit
00075 00036      MW04510 = 2;                                            " Glass Receive Code Set
00076 00037      IEND;
00077      " Need Every Glass Transfer Pitch Data
00078 00038      IF MB030035 == 1;
00079 00039      MB21462B = 1;                                            " Parameter Update Request (Scribe P

```

P00002 MPS232 : [Loading] Alignment Before 1 Cycle

00080 00040

itch)

IOW MB20522B == 1

" Parameter Update Reply (Scribe Pit

00081 00041

ch)

IEND;

00082 00042

IEND;

00083 00043

IEND;

00084 00044

IEND;

00085

00086 00045

RET;