

```

00001      ** DL Register Area - 120Word
00002      **
00003      ** DW00000 - DW00009 (PLS Use)
00004      ** DW00010 - DW00039 (Bit Use)
00005      ** DW00040 - DW00089 (Word Use)
00006      ** DW00090 - DW00119 (Timer)
00007      ****
00008
00009      "# Program Name      : Camera All Waiting Position
00010      "# Functionior      :
00011      "# Call Program     :
00012      "# Sub Program      :
00013      "# Func Program     :
00014
00015      VAR;
00016
00017      END_VAR;
00018
00019 00000      PLD [LCAMZ][RCAMZ];
00020 00001      VEL [LCAMZ] ML43912 [RCAMZ] ML44012;
00021
00022      " Camera Z Waiting Position
00023 00002      MOV [LCAMZ]ML43930 [RCAMZ]ML44030      " Camera Z Moving
00024
00025      " [ Scribe ] Cutter Z All Waiting Position
00026 00003      IOW MW04842 == 0;
00027 00004      MW04842 = 41;      " Scribe Cutter Z Command Code Setting
00028 00005      MSEE MPS198;      " Scribe Cutter Z Move
00029 00006      MW04842 = 0;
00030 00007      IOW MW04842 == 0;
00031
00032      " [ Scribe ] Cutter X All Waiting Position
00033 00008      IOW MW04514 == 0;
00034 00009      MW04514 = 1;      " Scribe → Scribe Cutter Command Code S
00035 00010      etting      " Scribe → Scribe Cutter Command Execut
00036 00011      MB045150 = 1;
00037 00012      e Bit ON      IOW MB045151 == 1      " Scribe ← Scribe Cutter Command Comple
00038 00013      te Bit ON      MB045150 = 0;      " Scribe → Scribe Cutter Command Execut
00039 00014      e Bit OFF      IOW MB045151 == 0      " Scribe ← Scribe Cutter Command Comple
00040 00015      te Bit ON
00041      " [ Scribe ] Cutter Shift All Waiting Position
00042 00016      IOW MW04514 == 0;
00043 00017      MW04514 = 17;      " Scribe → Scribe Cutter Command Code S
00044 00018      etting      " Scribe → Scribe Cutter Command Execut
00045 00019      MB045150 = 1;
00046 00020      e Bit ON      IOW MB045151 == 1      " Scribe ← Scribe Cutter Command Comple
00047 00021      te Bit ON      MB045150 = 0;      " Scribe → Scribe Cutter Command Execut
00048 00022      e Bit OFF      IOW MB045151 == 0      " Scribe ← Scribe Cutter Command Comple
00049 00023      te Bit ON
00050 00024      RET;

```