

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : [Manual]Last Dummy Scribe Ready
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017 " Scribe Cutter
00018 00000 LONG IDX_CX = 32;
00019 00001 LONG Axis_Pos_CX = 0;
00020 END_VAR;
00021
00022 00002 Axis_Pos_CX = IDX_CX * 50;
00023
00024 00003 IF MB045390 == 0;
00025 00004 MB15422A = 0; " 0 Level Search Running(Table to Table)
00026 00005 IF MB045740 == 0 " Cutter Z Stand By Pos Check
00027 00006 MW04842 = 41;
00028 00007 MSEE MPS198;
00029 00008 MW04842 = 0;
00030 00009 IOW MW04842 == 0;
00031 00010 IEND;
00032
00033 00011 MSEE MPS257; " Scribe/Break Home Origin Position Move
00034 00012 MB154227 = 1; " 0 Level Search Execute On
00035
00036 00013 MSEE MPS246; " 0 Level Search Position
00037
00038 00014 CLR DW00060 W300;
00039
00040 00015 MSEE MPS248; " 0 LevelSearch TorqueScanding
00041
00042 00016 MW04812 = 0; " 0 Point Level Search
00043 00017 DB000100 = 0;
00044 00018 WHILE DB000100 == 0;
00045 00019 MB049365 = 0; " 0 Point Detect Upper Cutter Comp
00046 00020 MB049367 = 1; " 0 Point Detect Upper Roller Comp (Unus
e)
00047
00048 00021 IF !MB045748 == 1 " Head1 Select Check
00049 " Upper Cutter Z / Lower Cutter Z 0 Point Level Search
00050 00022 IF !MB049365 == 1 " 0 Point Detect UPCZ Comp, LOCZ Unuse
00051 00023 MB154219 = 0; " UPCX 0 Level Search [0:Cutter 1:Roller
]
00052 00024 EOX;
00053
00054 " Cutter X, Cutter Shift Y 0 Point Position
00055 00025 IOW MW04514 == 0;
00056 00026 MW04514 = 7; " Scribe Req Scribe Cutter Command Code
Setting
00057 00027 MB045150 = 1; " Scribe Req Scribe Cutter Command Execu
te Bit ON
00058 00028 IOW MB045151 == 1 " Scribe Res Scribe Cutter Command Compl
ete Bit ON
00059 00029 MB045150 = 0; " Scribe Req Scribe Cutter Command Execu
te Bit OFF
00060 00030 IOW MB045151 == 0 " Scribe Res Scribe Cutter Command Compl
ete Bit ON
00061
00062 " Cutting Table Vacuum ON
00063
00064 00031 IOW MB49440 == 0;
00065 00032 MB49440 = 1;
00066 00033 MW04846 = 1;
00067 00034 MW04848 = 6;
00068 00035 MW04946 = 10; " [Fix] Table Vacuum Non
00069 00036 MW04948 = 10; " [Fix] Table Blow Non
00070 00037 MSEE MPS259; " Table Vacuum & Floating
00071 00038 MB49440 = 0;
00072
00073 00039 MSEE MPS247; " Cutter Z 0 Level Operation
00074 00040 IEND;
00075
00076 " Upper Roller Z 0 Point Level Search
00077 00041 IF !MB049367 == 1;
00078 00042 MB154219 = 1; " UPCX 0 Level Search [0:Cutter 1:Roller
]
00079 00043 IF CW00001 == 1 " Scribe Direction (0: Forward / 1: Reve

```

```

rse)
00080 00044          ML16064 = ML16064 + ML23746;
00081 00045          ELSE;
00082 00046          ML16064 = ML16064 - ML23746;
00083 00047          IEND;
00084 00048          EOX;
00085
00086 00049          PLD [CX];
00087 00050          VEL [CX]ML43212[Axis_Pos_CX];
00088 00051          MOV [CX]ML16064          " Left Lower Cutter X Moving
00089
00090 00052          IOW IBA00C1 == 1;
00091
00092 00053          MSEE MPS247;          " Cutter Z 0 Level Operation
00093 00054          IEND;
00094 00055          IEND;
00095
00096 00056          DL00060[MW04812] = ML23800          " UPCZ 0 Level Result Save
00097 00057          ML25120[MW04812] = DL00060[MW04812          " UPCZ 0 Level Result Save
00098 00058          DL00140[MW04812] = ML23824          " UPRZ 0 Level Result Save
00099 00059          EOX;
00100
00101 00060          MW04812 = MW04812 + 1;
00102
00103 00061          IF ML01230 <= MW04812;
00104 00062          DB00100 = 1;
00105 00063          MB045748 = 1;          " 0 Level Search Head1 Complete
00106 00064          IEND;
00107 00065          EOX;
00108 00066          WEND;
00109
00110 00067          DB000200 = 0;
00111 00068          DW00004 = 0;
00112 00069          WHILE DB000200 == 0
00113 00070          DL000300 = DL000300 + DL00060[DW00004          " UPCZ 0 Level Result Save
00114 00071          DL000304 = DL000304 + DL00140[DW00004          " UPRZ 0 Level Result Save
00115
00116 00072          DW00004 = DW00004 + 1;
00117 00073          IF DW00004 >= ML01230;
00118 00074          DB000200 = 1;
00119 00075          IEND;
00120 00076          EOX;
00121 00077          WEND;
00122
00123 00078          ML23800 = DL000300 / ML01230          " UPCZ 0 Level Result Save
00124 00079          ML23824 = DL000304 / ML01230          " UPRZ 0 Level Result Sav
00125
00126 00080          MB049365 = 0;          " 0 Point Detect Upper Cutter Comp
00127 00081          MB049367 = 0;          " 0 Point Detect Upper Roller Comp
00128
00129 00082          IF MB045748 == 1;
00130          " Cutter / Roller Z Waiting Position Movi g
00131 00083          IF MB045740 == 0;
00132 00084          MW04842 = 41;
00133 00085          MSEE MPS198;
00134 00086          MW04842 = 0;
00135 00087          IOW MW04842 == 0;
00136 00088          IEND;
00137 00089          IEND;
00138
00139          " 0 Point Level Search (Table to Table)
00140 00090          IF GL21080 <> 0          " Head 0 Detect Point Y Table to Table
00141 00091          MB15422A = 1;          " 0 Level Search Running(Table to Table)
00142
00143 00092          MSEE MPS246;          " 0 Level Search Position
00144
00145 00093          CLR DW00060 W300;
00146
00147          " UPCX Waiting Position
00148 00094          PLD [CX];
00149 00095          ML16064 = ML40030[Axis_Pos_CX]          " UPCX Waiting Position
00150 00096          IOW MB45760 == 1          " UPCX Moving Permission
00151 00097          VEL [CX]ML40012[Axis_Pos_CX];
00152 00098          MOV [CX]ML16064;
00153 00099          IOW MB046000 == 1          " UPCX Waiting Position Chec
00154
00155 00100          MSEE MPS248;          " 0 LevelSearch TorqueScanding
00156
00157 00101          MW04812 = 0;          " 0 Point Level Search
00158
00159          "Upper Cutter Z 0 Point Level Search
00160 00102          IF !MB049365 == 1
00161 00103          MB154219 = 0;          " UPCX 0 Level Search [0:Cutter 1:Roller
00162 00104          ]
00163          EOX;
00164          "Cutter X, Cutter Shift Y 0 Point Position

```

```

00165 00105      IOW MW04514 == 0;
00166 00106      MW04514 = 7;          " Scribe Req Scribe Cutter Command Code

Setting
00167 00107      MB045150 = 1;          " Scribe Req Scribe Cutter Command Execu
te Bit ON
00168 00108      IOW MB045151 == 1      " Scribe Res Scribe Cutter Command Compl
ete Bit ON
00169 00109      MB045150 = 0;          " Scribe Req Scribe Cutter Command Execu
te Bit OFF
00170 00110      IOW MB045151 == 0      " Scribe Res Scribe Cutter Command Compl
ete Bit ON

00171
00172      "Cutting Table Vacuum ON
00173
00174 00111      IOW MB49440 == 0;
00175 00112      MB49440 = 1;
00176 00113      MW04846 = 1;
00177 00114      MW04848 = 6;
00178 00115      MW04946 = 10;
00179 00116      MW04948 = 10;
00180 00117      MSEE MPS259;          " Table Vacuum & Floating
00181 00118      MB49440 = 0;

00182
00183 00119      MSEE MPS247;          " Cutter Z 0 Level Operation
00184 00120      IEND;
00185
00186 00121      MB049365 = 0;          " 0 Point Detect Upper Roller Comp
00187 00122      MB049367 = 0;          " 0 Point Detect Upper Cutter Coi
00188
00189 00123      IF MB045748 == 1;
00190      "Cutter / Roller Z Waiting Position Movi
00191 00124      IF MB045740 == 0;
00192 00125      MW04842 = 41;
00193 00126      MSEE MPS198;
00194 00127      MW04842 = 0;
00195 00128      IOW MW04842 == 0;
00196 00129      IEND;
00197 00130      IEND;
00198
00199 00131      MB15422A = 0;          " 0 Level Search Running(Table to Table)
00200 00132      ELSE;
00201 00133      ML23802 = 0;          " UPCZ 0 Level Result Save
00202 00134      ML23826 = 0;          " UPRZ 0 Level Result Sav
00203 00135      IEND;
00204
00205      //      IF !MB00009F == 1
00206      //      "Cutting Table Floating C
00207      //
00208      //      IOW MB49440 == 0;
00209      //      MB49440 = 1;
00210      //      MW04846 = 6;
00211      //      MW04848 = 5;
00212      //      MW04946 = 10;
00213      //      MW04948 = 10;
00214      //      MSEE MPS259;          " Table Vacuum & Floating
00215      //      MB49440 = 0;
00216      //
00217      //      "Cutting Table Floating OF `
00218      //
00219      //      IOW MB49440 == 0;
00220      //      MB49440 = 1;
00221      //      MW04846 = 6;
00222      //      MW04848 = 6;
00223      //      MW04946 = 10;
00224      //      MW04948 = 10;
00225      //      MSEE MPS259;          " Table Vacuum & Floating
00226      //      MB49440 = 0;
00227      //
00228      //      IEND;
00229
00230 00136      IOW MB214620 == 0
00231 00137      IOW MB205220 == 0
00232 00138      MB214620 = 1;
00233 00139      IOW MB205220 == 1
00234 00140      MB214620 = 0;
00235 00141      IOW MB205220 == 0
00236
00237 00142      MSEE MPS257;          " Scribe/Break Home Origin Position Move
00238
00239 00143      MB154227 = 0;          " 0 Level Search Execute Off
00240 00144      IEND;
00241
00242 00145      RET;

```