

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : Chuck,Break Table Escape Position
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 " Axis Current Position Update
00021 00000 MSEE MPS150;
00022
00023 " Cutter X, Cutter Shift Y Waiting Position
00024 00001 MW04514 = 1; " Scribe Req Scribe Cutter Command C
ode Setting
00025 00002 MB045150 = 1; " Scribe Req Scribe Cutter Command E
xecute Bit ON
00026 00003 IOW MB045151 == 1 " Scribe Res Scribe Cutter Command C
omplete Bit ON
00027 00004 MB045150 = 0; " Scribe Req Scribe Cutter Command E
xecute Bit OFF
00028 00005 IOW MB045151 == 0 " Scribe Res Scribe Cutter Command C
omplete Bit ON
00029
00030 00006 IOW MB49440 == 0;
00031 00007 MB49440 = 1;
00032 00008 EOX;
00033 " Break Table Glass Data Not Exi:
00034 00009 IF !MB030036 == 1;
00035 00010 MW04846 = 6; " Cutting, Break Table Vacuum Off
00036 00011 MW04848 = 5; " Cutting, Break Table Floating On
00037 00012 IF MB09019F == 1;
00038 00013 MW04846 = 4;
00039 00014 MW04848 = 3;
00040 00015 IEND;
00041 00016 IF MB030034 | (MB071023 & MB045281 & MB070271) == 1;
00042 00017 MW04946 = 1; " [Fix] Table Vacuum On
00043 00018 MW04948 = 2; " [Fix] Table Blow Off
00044 00019 ELSE;
00045 00020 MW04946 = 2; " [Fix] Table Vacuum Off
00046 00021 MW04948 = 1; " [Fix] Table Blow On
00047 00022 IEND;
00048 00023 MSEE MPS259; " Table Vacuum & Floating
00049 00024 ELSE;
00050 00025 IF !MB04524A == 1;
00051 " Break Table Glass Data Exi:
00052 00026 IF MB030036 & !MB030035 == 1;
00053 00027 MW04846 = 2; " Cutting Table Vacuum Off
00054 00028 MW04848 = 1; " Cutting Table Floating On
00055 00029 IEND;
00056 00030 IF MB030034 | (MB071023 & MB045281 & MB070271) == 1;
00057 00031 MW04946 = 1; " [Fix] Table Vacuum On
00058 00032 MW04948 = 2; " [Fix] Table Blow Off
00059 00033 ELSE;
00060 00034 MW04946 = 2; " [Fix] Table Vacuum Off
00061 00035 MW04948 = 1; " [Fix] Table Blow On
00062 00036 IEND;
00063 00037 MSEE MPS259; " Table Vacuum & Floating
00064 00038 ELSE;
00065 00039 IF ML05310 == 1
00066 " [Action] Break Table Vaccum ON
00067 00040 MW04846 = 3; " Cutting Table Vacuum Off
00068 00041 MW04848 = 4; " Cutting Table Floating On
00069 00042 MW04946 = 10; " [Fix] Table Vacuum Off
00070 00043 MW04948 = 10; " [Fix] Table Blow On
00071 00044 MSEE MPS259; " Table Vacuum & Floating
00072 00045 IEND;
00073 00046 IEND;
00074 00047 IEND;
00075 00048 MB49440 = 0;
00076
00077 " Scribe Chuck Y
00078 00049 IF (MB030034 & MB04574E) | MB030035 == 1;
00079 00050 IF MB09018E == 1 " [Sensor] SCT Scribe Chuck All Vacu
um On
00080 " [Request] Moving Position
00081 00051 MW04820 = 40;

```

```

00082 00052          MSEE MPS256;
00083 00053          IOW MB04574C == 1          " All SCHZ Moving Pos Check
00084 00054      ELSE;
00085          " [Request] Vacuum Position
00086 00055          MW04820 = 41;
00087 00056          MSEE MPS256;
00088 00057          IOW MB04574B == 1          " All SCHZ Vacuum Pos Check
00089
00090 00058          MB09048E = 1;          " [Sol] SCT Scribe Chuck All Vacuum
On
00091 00059          IOW MB09018E == 1          " [Sensor] SCT Scribe Chuck All Vacu
um On
00092
00093          " [Request] Moving Position
00094 00060          MW04820 = 40;
00095 00061          MSEE MPS256;
00096 00062          IOW MB04574C == 1          " All SCHZ Moving Pos Check
00097 00063      IEND;
00098 00064      ELSE;
00099 00065          MB09052E = 1;          " [Sol] SCT Scribe Chuck All Vacuum
Off
00100 00066          MB090560 = 1;          " [Sol] SCT Scribe Chuck 1,2,3,4 Blo
w On
00101 00067          IOW MB09022E & MB090260 == 1          " [Sensor] SCT Scribe Chuck All Vacu
um Off
00102          " [Sensor] SCT Scribe Chuck 1,2,3,4
Blow On
00103 00068          TIM TMW26214;          " Scribe Chuck Vacuum Break Complete
Timer
00104 00069          MB090600 = 1;          " [Sol] SCT Scribe Chuck 1,2,3,4 Blo
w Off
00105 00070          IOW MB090300 == 1          " [Sensor] SCT Scribe Chuck 1,2,3,4
Blow Off
00106
00107          " [Request] Standby Position
00108 00071          MW04820 = 39;
00109 00072          MSEE MPS256;
00110 00073          IOW MB04574A == 1          " All SCHZ Standby Pos Check
00111 00074      IEND;
00112
00113          " [Scribe Chuck] Command Set
00114 00075          MW04518 = 1;          " Scribe Req Scribe Chuck Command Co
de Setting
00115 00076          MB045190 = 1;          " Scribe Req Scribe Chuck Command Ex
ecute Bit ON
00116 00077          IOW MB045191 == 1          " Scribe Res Scribe Chuck Command Co
mplete Bit ON
00117 00078          MB045190 = 0;          " Scribe Req Scribe Chuck Command Ex
ecute Bit OFF
00118 00079          IOW MB045191 == 0          " Scribe Res Scribe Chuck Command Co
mplete Bit OI
00119
00120          " Break Table Carry Out Position 1 Cycle
00121 00080      IF !MB04524A == 1;
00122 00081          IOW MW04522 == 0          " [ SC Req BKT ] Command Code ID Set
00123 00082          MW04522 = 7;          " [ SC Req BKT ] Command Code ID Set
00124 00083          MB045230 = 1;          " [ SC Req BKT ] Command Se
00125 00084          IOW MB045231 == 1          " [ SC Res BKT ] Command Complete
00126 00085          MB045230 = 0;          " [ SC Req BKT ] Command Se
00127 00086          IOW MB045231 == 0          " [ SC Res BKT ] Command Complete
00128 00087          MW04522 = 0;          " [ SC Req BKT ] Command Code ID Set
00129 00088      IEND;
00130
00131          " Break Table Motion Complete Checking
00132 00089      IOW !MB04572B == 1          " BKT Moving Flag OFF
00133
00134 00090      IF MB04524A == 0;
00135          " Chuck Break Waiting Position 1 Cycle
00136 00091          IOW MW04520 == 0          " [ SC Req BKPb ] Command Code ID Se
t
00137 00092          MW04520 = 10;          " [ SC Req BKPb ] Command Code ID Se
t
00138 00093          MB045210 = 1;          " [ SC Req BKPb ] Command Se
00139 00094          IOW MB045211 == 1          " [ SC Res BKPb ] Command Complete
00140 00095          MB045210 = 0;          " [ SC Req BKPb ] Command Se
00141 00096          IOW MB045211 == 0          " [ SC Res BKPb ] Command Complete
00142 00097          MW04520 = 0;          " [ SC Req BKPb ] Command Code ID Se
t
00143 00098      IEND;
00144
00145          " Chuck Break Motion Complete Checking
00146 00099      IOW MB04572A == 0          " BCHK Moving Flag OFF
00147
00148 00100      RET;

```