

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : Break Pusher Bar Waiting Positon
00011 "# Functior :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017 00000 LONG IDX_BKPB1 = 64;
00018 00001 LONG IDX_BKPB2 = 65;
00019 00002 LONG IDX_BKPBZ1 = 66;
00020 00003 LONG IDX_BKPBZ2 = 67;
00021 END_VAR;
00022
00023 00004 MSEE MPS270; " Break Pusher Bar Speed, Position Updat
e Set
00024
00025 " Head X Wait
00026 00005 IF MW04511 <> 3;
00027 00006 IF !MB051000 | !MB051000 == 1;
00028 00007 IOW MB045741 == 1;
00029 00008 IEND;
00030 00009 IEND;
00031
00032 // IF !MB090142 | !MB090143 == 1;
00033 // " Cutting Table Brush Brush Up Status
00034 // MB090402 = 0;
00035 // MB090403 = 0;
00036 // TIM T100;
00037 // MB090442 = 1;
00038 // MB090443 = 1;
00039 // IOW MB090142 & MB090143 == 1;
00040 // IEND;
00041 " Cutting Table Brush Up Status
00042 00010 IF !MB09014E == 1;
00043 " Cutting Table Brush Brush Up Status
00044 00011 MB09040E = 0;
00045 00012 MB09044E = 1;
00046 00013 IOW MB09014E == 1;
00047 00014 IEND;
00048
00049 " Inner Bit Reset
00050 00015 DW00001 = 0;
00051
00052 00016 PFORK BKC_Y1 BKC_Z1;
00053
00054 BKC_Y1:
00055 " Break Pusher Bar Y Receive Before Step.1 Position
00056
00057 00017 DL00020 = ML27820 + ML72802 - ML27826;
00058 00018 IF ILA816 > DL00020;
00059 00019 IF CW00099 == 1;
00060 00020 DL00030 = ML73202 + CW00218;
00061 00021 IOW ILB116 < DL00030;
00062 00022 ELSE;
00063 00023 IOW DB00011 == 1;
00064 00024 IEND;
00065 00025 IEND;
00066
00067 00026 IF !MB51000 == 1
00068 00027 ML16128 = ML72802 " Break Pusher Bar Y Moving Position Wri
te
00069 00028 IOW MB50760 == 1 " Break Pusher Bar Y Receive Before Posi
tion Move Permission
00070 00029 MOV [BKPBY1]ML16128 [BKPBY2]ML1612 " Break Pusher Bar Y Pos. Moving
00071 00030 IOW MB051000 == 1 " Break Pusher Bar Y Receive Before Posi
tion
00072 00031 IEND;
00073 00032 DB00010 = 1; " Break Pusher Bar Y Receive Before Ste
p.1 Position Moving Complet
00074 00033 JOINTO Label8X;
00075
00076 BKC_Z1:
00077 " Break Pusher Bar Z Waiting Position
00078 00034 IF !MB51020 == 1;
00079 00035 ML16132 = ML73202 " Break Pusher Bar Z Moving Position Wri
te
00080 00036 IOW MB050770 == 1 " Break Pusher Bar Z Moving Permission
00081 00037 MOV [BKPBY1]ML16132 [BKPBY2]ML1613 " Break Pusher Bar Z Pos. Movin

```

```
00082 00038          IOW MB51020 == 1          " Break Pusher Bar Z Waiting Position Ch
eck
00083 00039          IEND;
00084 00040          DB00011 = 1;          " Break Pusher Bar Z Waiting Position Mo
ving Complet;
00085 00041          JOINTO Label18X;
00086
00087 00042          Label18X: PJOINT;
00088
00089 00043          RET;
```

			MPS265 : Break Pusher Bar Waiting Positon	P00002
--	--	--	---	--------