

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : Break Table Carry O
00011 "# Function :
00012 "# Call Program : MPM05
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017 00000 LONG IDX_BKTY1 = 69;
00018 00001 LONG IDX_BKTY2 = 70;
00019 00002 LONG IDX_BKTZ1 = 72;
00020 00003 LONG IDX_BKTZ2 = 73;
00021 00004 LONG IDX_BKTZ3 = 74;
00022 00005 LONG IDX_BKTT1 = 75;
00023 00006 LONG IDX_BKTT2 = 76;
00024 END_VAR;
00025
00026 00007 MSEE MPS310; " Break Table Speed, Position Update
Set
00027
00028 " Stick Transfer Interference Check
00029 00008 IF MB030036 == 1;
00030 " Break Table Vacuum On
00031 00009 IF !MB05684F == 1
00032 00010 MB05584F = 1; " Break Table Vacuum On
00033 00011 IOW MB05684F | MB00800 == 1 " Break Table Vacuum On Check
00034 00012 TIM TMW26202; " Break Table Vacuum On Delay Time
00035 00013 IEND;
00036 00014 IOW MB05684F | MB00800 == 1 " Break Table Vacuum On Check
00037 00015 IEND;
00038
00039 " Break Table Cleaning Brush1 Up Status
00040 00016 IF !MB05682E == 1;
00041 " Break Table Cleaning Brush1 Up Stat
00042 00017 MB05582E = 1;
00043 00018 IEND;
00044 " Break Table Cleaning Brush2 Up Status
00045 00019 IF !MB05682F == 1;
00046 " Break Table Cleaning Brush2 Up Stat
00047 00020 MB05582F = 1;
00048 00021 IEND;
00049
00050 " Break Cleaning Brush Up Stat
00051 00022 IOW MB05682E & MB05682F == 1;
00052
00053 00023 IF MB000023 == 1;
00054 00024 MB045159 = 1; " Step Mode Next Fla
00055 00025 IOW (!MB21684D | MB20544E) | MB045013 == " Step Mode
00056 00026 MB045159 = 0; " Step Mode Next Fla
00057 00027 IEND;
00058
00059 " Inner Bit Reset
00060 00028 DW00001 = 0;
00061 00029 PFORK TBL_Y4 TBL_Z4 TBL_T4;
00062
00063 TBL_Y4:
00064 00030 IF MB030036 == 1;
00065 00031 IOW MB05684F | MB00800 == 1 " Break Table Vacuum On Check
00066 00032 IEND;
00067 " Break Table Y
00068 // IOW DB000011 & DB000012 == 1 " Break Table Z, T Position Moving C
omplete
00069 00033 IF MB59600 == 1;
00070 00034 ML16138 = ML05962;
00071 00035 ELSE;
00072 00036 ML16138 = ML73822 " Break Table Y Moving Position Writ
e
00073 00037 IEND;
00074 // ML16138 = ML73822 " Break Table Y Moving Position Writ
e
00075 00038 IOW MB55765 == 1 " Break Table Y Carry Out Position M
oving Permission
00076 00039 IF !MB56005 == 1;
00077 00040 MOV [BKTY1]ML16138 [BKTY2]ML16138; " Break Table Y Pos. Moving
00078 00041 IOW MB56005 == 1 " Break Table Y Carry Out Position
00079 00042 IEND;
00080 00043 IF MB030036 == 1;
00081 00044 IOW MB05684F | MB00800 == 1 " Break Table Vacuum On Check
00082 00045 IEND;

```

```

00083 00046          DB00010 = 1;                " Break Table Y Carry Out Position M
              oving Complete
00084
00085 00047          JOINTO LabelX;
00086
00087          TBL_Z4:
00088              " Break Table :
00089 00048          ML16144 = ML74422                " Break Table Z Moving Position Writ
              e
00090 00049          IOW MB55775 == 1                " Break Table Z Carry Out Position M
              oving Permission
00091 00050          IF !MB56025 == 1;
00092 00051              MOV [BKTZ1]ML16144 [BKTZ2]ML16144 [BKTZ3]ML16144 " Break Table Z Pos. Moving
00093 00052              IOW MB56025 == 1                " Break Table Z Carry Out Position
00094 00053              IEND;
00095 00054          DB00011 = 1;                " Break Table Z Carry Out Position M
              oving Complete
00096
00097 00055          JOINTO LabelX;
00098
00099          TBL_T4:
00100              " Break Table :
00101 00056          ML16150 = ML75002                " Break Table T Moving Position Writ
              e
00102 00057          IOW MB55780 == 1                " Break Table T Standby Position Mov
              ing Permission
00103 00058          IF !MB56050 == 1;
00104 00059              MOV [BKTT1]ML16150 [BKTT2]ML16150, " Break Table T Pos. Moving
00105 00060              IOW MB56050 == 1                " Break Table T Standby Position
00106 00061              IEND;
00107 00062          DB00012 = 1;                " Break Table T Standby Position Mov
              ing Complete
00108
00109 00063          JOINTO LabelX,
00110 00064          LabelX: PJOINT;
00111
00112 00065          RET;

```