

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name      :
00011 "# Function          :
00012 "# Call Program      : MPM073
00013 "# Sub Program       :
00014 "# Func Program      :
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 00000 IF !MB000026 == 1 " Load Stop
00021 00001 IF !MB0002001 == 1 " P Work : Main Buffer Table
00022 00002 IF !MB000800 == 1 " Dummy Run
00023 00003 IF MB1341005 == 1 " SCT -> tU1 Rcv Start
00024 00004 MB0002000 = 1; " P Work : SCT Carry In
00025 00005 IOW MB066900 == 1 " Main Buffer Table Glass Sensor On
00026 00006 IOW MB1340006 == 1 " tU1 -> Scribe Send Complete
00027 00007 MB002480 = 1; " Work Move : SCT Carry In -> Main Buffe
r Table
00028 00008 IOW MB1341006 == 1 " SCT -> tU1 Rcv Complete
00029 00009 IOW MB0002001 == 1 " P Work:Pre Align
00030 00010 MW06508 = 2; " Next Step
00031 00011 IEND;
00032 00012 ELSE;
00033 00013 MB0002001 = 1; " P Work:Main Buffer Table
00034 00014 MW06508 = 2; " Next Step
00035 00015 IEND;
00036 00016 ELSE;
00037 00017 MW06508 = 2; " Next Step
00038 00018 IEND;
00039 00019 IEND;
00040
00041 00020 RET;

```