

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name      :
00011 "# Function          :
00012 "# Call Program      :
00013 "# Sub Program       :
00014 "# Func Program      :
00015
00016 VAR;
00017     CONST LONG Axis_MTRY1 = 3;
00018     CONST LONG Axis_MTRY2 = 4;
00019     CONST LONG Axis_MTRX  = 5;
00020     CONST LONG Axis_MTRZ1 = 6;
00021     CONST LONG Axis_MTRZ2 = 7;
00022     CONST LONG Axis_MTRT  = 8;
00023 END_VAR;
00024
00025 00000     PLD [MTRY1][MTRY2][MTRX][MTRZ1][MTRZ2][MTRT];
00026
00027 00001     DW00000 = 0;
00028 00002     DL00010 = 5000;
00029
00030 00003     IF ILAE96 > ML46130;
00031 00004         DL00020 = ILAE96 - ML46130;
00032 00005     ELSE;
00033 00006         DL00020 = ML46130 - ILAE96;
00034 00007     IEND;
00035
00036 00008     IF DL00020 > DL00010
00037 00009         DB000000 = 1;
00038 00010     IEND;
00039
00040 00011     IF !MB071020 == 1                                " Main Transfer Z Standby Pc
00041
00042 00012         MW07344 = 1;
00043 00013         MSEE MPS412;
00044 00014     IEND;
00045
00046 00015     IF !MB071030 == 1                                " Main Transfer T Standby Pos
00047 00016         IF DB000000 == 1
00048 00017             MSEE MPS416;                                " Main Transfer Turn Pos
00049 00018         IEND;
00050 00019     IEND;
00051
00052 00020     PFORK MTRY MTRX MTRT;
00053
00054     MTRY:
00055
00056 00021         IF !MB071000 == 1                                " Main Transfer Y StandBy Pos
00057
00058             "IF !DB000000 == 1;
00059 00022             IOW MB070760 == 1                                " Main Transfer Y StandBy Pos Enable
00060             "IEND;
00061 00023             ML16006 = ML60602                                " Move Data:Main Transfer Y StandBy Pos
00062 00024             MOV [MTRY1]ML16006 [MTRY2]ML16006 ;
00063
00064 00025             IOW MB071000 == 1                                " Main Transfer Y StandBy Pos Moving Com
00065 00026 p Check         IEND;
00066
00067 00027         JOINTO Label0X;
00068
00069     MTRX:
00070
00071         //IOW MB071030 == 1                                " Main Transfer T Standby Pos Check
00072
00073 00028         IF !MB071010 == 1                                " Main Transfer X StandBy Pos
00074 00029             IOW MB070770 == 1                                " Unit7 Motor IL:Main Transfer X Standby
00075 Pos Enable
00076 00030             ML16010 = ML40530                                " Axis2 Move Data:Main Transfer X StandB
00077 00031 y Pos         MOV [MTRX]ML16010;
00078
00079 00032             IOW MB071010 == 1                                " Main Transfer X Pos Moving Comp Check
00080 00033         IEND;
00081
00082 00034         JOINTO Label0X;
00083

```

```

00084          MTRT:
00085
00086 00035      IF !MB071030 == 1          " Main Transfer T StandBy Pc
00087 00036          IOW MB070780 == 1      " Main Transfer T Standby Pos Enable
00088
00089 00037          ML16016 = ML46130          " Move Data:Main Transfer T StandBy Pos
00090 00038          MOV [MTRT]ML16016;
00091
00092 00039          IOW MB071030 == 1          " Main Transfer T Pos Moving Comp Check
00093 00040          IEND;
00094
00095 00041          JOINTO Label10X,
00096
00097 00042      Label10X: PJOINT;
00098
00099
00100
00101 00043      MB071370 = 0;          " Unit7 Cycle1 Move Check
00102
00103 00044      RET;

```

			MPS415 : MTR Cycle 1 (MTR Standby Pos)	P00002
--	--	--	--	--------