

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name      :
00011 "# Function          :
00012 "# Call Program      :
00013 "# Sub Program       :
00014 "# Func Program      :
00015
00016 VAR;
00017     CONST LONG Axis_MTRY1 = 3;
00018     CONST LONG Axis_MTRY2 = 4;
00019     CONST LONG Axis_MTRX  = 5;
00020     CONST LONG Axis_MTRZ1 = 6;
00021     CONST LONG Axis_MTRZ2 = 7;
00022     CONST LONG Axis_MTRT  = 8;
00023 END_VAR;
00024
00025 00000     PLD [MTRY1][MTRY2][MTRX][MTRZ1][MTRZ2][MTRT];
00026
00027 00001     DW00000 = 0;
00028 00002     DL00010 = 10000;
00029
00030 00003     DW00000 = 0;
00031 00004     DL00010 = 5000;
00032
00033 00005     IF ILAE96 > ML72206;
00034 00006         DL00020 = ILAE96 - ML72206;
00035 00007     ELSE;
00036 00008         DL00020 = ML72206 - ILAE96;
00037 00009     IEND;
00038
00039 00010     IF DL00020 > DL00010
00040 00011         DB000000 = 1;
00041 00012     IEND;
00042
00043 00013     IF !MB071020 == 1                                " Main Transfer Z Standby Pc
00044 00014         MW07344 = 1;
00045 00015         MSEE MPS412;
00046 00016     IEND;
00047
00048 00017     IF !MB071010 == 1                                " Main Transfer X Standby Pos
00049 00018         MW07342 = 1;
00050 00019         MSEE MPS411;
00051 00020     IEND;
00052
00053 00021     IF !MB071032 == 1                                " Main Transfer T Carry In Pos
00054 00022         IF DB000000 == 1
00055 00023             MSEE MPS416;                                " Main Transfer Turn Pos
00056 00024         IEND;
00057 00025     IEND;
00058
00059 00026     PFORK MTRY MTRX MTRT;
00060
00061     MTRY:
00062
00063 00027         IOW MB071032 == 1                                " Main Transfer T Carry In Pos
00064
00065 00028         IF !MB071002 == 1                                " Main Transfer Y Carry In Pos
00066
00067 00029             IOW MB070762 == 1                                " Main Transfer Y Carry In Pos Enable
00068
00069 00030             ML16006 = ML60606                                " Move Data:Main Transfer Y Carry In Pos
00070 00031             MOV [MTRY1]ML16006 [MTRY2]ML16006;
00071
00072 00032             IOW MB071002 == 1                                " Main Transfer Y Carry In Pos Moving Co
00073 00033 mp Check         IEND;
00074
00075 00034             JOINTO Label0X;
00076
00077     MTRX:
00078
00079 00035             IOW MB071032 == 1                                " Main Transfer T Carry In Pos Check
00080
00081 00036             IF !MB071012 == 1                                " Main Transfer X Carry In Pc
00082 00037                 IOW MB070772 == 1                                " Main Transfer X Carry In Pos Enable
00083
00084 00038                 ML16010 = ML61006                                " Move Data:Main Transfer X Carry In Pos
00085 00039                 MOV [MTRX]ML16010;

```

```
00086
00087 00040      IOW MB071012 == 1      " Main Transfer X Carry In Pos Moving Co
      mp Check
00088 00041      IEND;
00089
00090 00042      JOINTO Label0X,
00091
00092      MTRT:
00093
00094 00043      IF !MB071032 == 1      " Main Transfer T Carry In Pos
00095 00044      IOW MB070782 == 1      " Main Transfer T Carry In Pos Enable
00096
00097 00045      ML16016 = ML72206      " Move Data:Main Transfer T Carry In Pos
00098 00046      MOV [MTRT]ML16016;
00099
00100 00047      IOW MB071032 == 1      " Main Transfer T Carry In Pos Moving Co
      mp Check
00101 00048      IEND;
00102
00103 00049      JOINTO Label0X;
00104
00105 00050      Label0X: PJOINT;
00106
00107
00108 00051      MB071372 = 0;      " Unit7 Cycle1 Move Check
00109
00110 00052      RET;
```