

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name      :
00011 "# Function          :
00012 "# Call Program      :
00013 "# Sub Program       :
00014 "# Func Program      :
00015
00016 VAR;
00017     CONST LONG Axis_MTRY1 = 3;
00018     CONST LONG Axis_MTRY2 = 4;
00019     CONST LONG Axis_MTRX  = 5;
00020     CONST LONG Axis_MTRZ1 = 6;
00021     CONST LONG Axis_MTRZ2 = 7;
00022     CONST LONG Axis_MTRT  = 8;
00023 END_VAR;
00024
00025 00000     PLD [MTRY1][MTRY2][MTRX][MTRZ1][MTRZ2][MTRT];
00026
00027 00001     MW07028 = 0;                                " Main Transfer PIO Data Clear
00028 00002     DW00000 = 0;
00029
00030 00003     IF MB065270 == 1                                " [Main Buffer Table -> Main Transfer] S
00031 00004     end Possible                                     " [Main Transfer -> Main Buffer Table] R
00032 00005     MB070280 = 1;
00033 00006     eceive Possible
00034 00007     IOW MB065271 == 1                                " [Main Buffer Table -> Loader Transfer]
00035 00008     Send Start
00036 00009     MB070281 = 1;                                     " [Main Transfer -> Main Buffer Table] R
00037 00010     eceive Start
00038
00039 00007     WHILE DW00000 <= GL49100                        " Main Transfer Vacuum Retry Count
00040 00008     DW00001 = 0;
00041 00009     IF GL49106 <> 0                                " Main Transfer 2 Pos Carry In Distance
00042 00010     IF DW00000 <> 0;
00043 00011     IF GL49106 < GL49102;
00044 00012     MW07344 = 9;                                    " Main Transfer Z 2 Pos Carry In Before
00045
00046 Pos
00047     MSEE MPS412;
00048     IEND;
00049     MW07344 = 10;                                       " Main Transfer Z 2 Pos Carry In Pos
00050     MSEE MPS412;
00051     ELSE;
00052     MW07344 = 9;                                       " Main Transfer Z 2 Pos Carry In Before
00053
00054 Pos
00055     MSEE MPS412;
00056
00057     MW07344 = 10;                                       " Main Transfer Z 2 Pos Carry In Pos
00058     MSEE MPS412;
00059     IEND;
00060     ELSE;
00061     IF DW00000 <> 0
00062     MW07344 = 10;                                       " Main Transfer Z 2 Pos Carry In Pos
00063     MSEE MPS412;
00064     ELSE;
00065     MW07344 = 3;                                       " Main Transfer Z Carry In Pos
00066     MSEE MPS412;
00067     IEND;
00068     IEND;
00069
00070 "MB070286 = 1,                                         "" [Main Transfer -> Main Buffer Table]
00071 Vacuum Off Request On
00072
00073 IF !MB000800 == 1
00074     MB070888 = 1;                                       " Main Transfer Vacuum On
00075     "IOW MB071888 | MB000800 == 1                    "" Main Transfer Vacuum On Check
00076     TIM TMW30208;                                       " Main Transfer Vacuum Confirm Timer
00077     ELSE;
00078     TIM TMW30208;
00079     IEND;
00080
00081 IF !MB071888 & !MB00800 == 1
00082     DW00000 = DW00000 + 1;                               " Main Transfer Vacuum On Chec
00083     MB070898 = 1;                                       " Main Transfer Vacuum Off
00084     IOW MB07189C == 1                                   " Main Transfer Vacuum Off Che
00085
00086 "TIM T50;
00087 MB07088C = 1;
00088 IOW MB07188C == 1
00089
00090 "Main Transfer Vacuum Break On
00091 "Main Transfer Vacuum Break On Check

```

```

00080          "TIM TMW30010;'" Main Transfer Vacuum Break Confirm Tim
er
00081 00044      MB07089C = 1;      " Main Transfer Vacuum Break Off
00082 00045      IOW MB07189C | MB00800 == 1      " Main Transfer Vacuum Break Off Check
00083
00084 00046      MW07344 = 13;      " Main Transfer Z Vacuum Retry Pos
00085 00047      MSEE MPS412;
00086 00048      IF DW00000 > GL49100;
00087 00049          DB000010 = 1;      " Vacuum Retry Count Over
00088 00050          IEND;
00089 00051      ELSE;
00090 00052          IF MB000800 == 1      " Dummy Run
00091 00053              TIM T100;
00092 00054          IEND;
00093 00055          DW00000 = 999;
00094 00056      IEND;
00095 00057      EOX;
00096 00058      WEND;
00097
00098 00059      IF !DB000010 == 1;
00099 00060          MB002481 = 1;      " Work Move : Main Buffer Table → Main
Transfer
00100 00061      IOW MB002002 == 1      " P Wokr : Main Transfer
00101 00062      IOW MB065272 == 1      " [Main Buffer Table -> Main Transfer] S
end Complete
00102          "MB070286 = 0,      "" [Main Transfer -> Main Buffer Table]
Vacuum Off Request On
00103
00104 00063      IF GL49106 <> 0      " Main Transfer 2 Pos Carry In Distance
00105 00064          MW07344 = 9;      " Main Transfer Z 2 Pos Carry In Before
Pos
00106 00065          MSEE MPS412;
00107 00066          IEND;
00108
00109 00067      MW07344 = 1;      " Main Transfer Z Standby Pos
00110 00068      MSEE MPS412;
00111 00069      MB070282 = 1;      " [Main Transfer -> Main Buffer Table] R
eceive Complete
00112 00070      IOW MB65272 == 0;
00113 00071      MW07028 = 0;      " Main Transfer PIO Data Clear
00114 00072      ELSE;
00115 00073          MW07344 = 1;      " Main Transfer Z Standby Pos
00116 00074          MSEE MPS412;
00117 00075          MB070380 = 1,      " Main Transfer Vacuum Retry Over Alarm
00118 00076          IEND;
00119 00077      IEND;
00120 00078      RET;

```