

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name      :
00011 "# Function          :
00012 "# Call Program      :
00013 "# Sub Program       :
00014 "# Func Program      :
00015
00016 VAR;
00017     CONST LONG Axis_MTRY1 = 3;
00018     CONST LONG Axis_MTRY2 = 4;
00019     CONST LONG Axis_MTRX  = 5;
00020     CONST LONG Axis_MTRZ1 = 6;
00021     CONST LONG Axis_MTRZ2 = 7;
00022     CONST LONG Axis_MTRT  = 8;
00023 END_VAR;
00024
00025 00000     PLD [MTRY1][MTRY2][MTRX][MTRZ1][MTRZ2][MTRT]
00026
00027 00001     DW00000 = 0;
00028 00002     DL00010 = 5000;
00029
00030 00003     IF ILAE96 > ML72210;
00031 00004         DL00020 = ILAE96 - ML72210;
00032 00005     ELSE;
00033 00006         DL00020 = ML72210 - ILAE96;
00034 00007     IEND;
00035
00036 00008     IF DL00020 > DL00010
00037 00009         DB000000 = 1;
00038 00010     IEND;
00039
00040 00011     IF !MB071020 == 1                                " Main Transfer Z Standby Pc
00041
00042 00012         MW07344 = 1;
00043 00013         MSEE MPS412;
00044 00014     IEND;
00045
00046 00015     IF !MB071010 == 1                                " Main Transfer X Standby Pos
00047 00016         MW07342 = 1;
00048 00017         MSEE MPS411;
00049 00018     IEND;
00050
00051 00019     IF !MB071033 == 1                                "Main Transfer T Carry Out Pc
00052 //         IF GL49058 <> 0,
00053 //         MSEE MPS416;                                " Main Transfer Turn Pos
00054 //         ELSE;
00055 //             IF DB000000 == 1;
00056 //                 MSEE MPS416;
00057 //             IEND;
00058 //         IEND;
00059
00060 00024     PFORK MTRY MTRX MTRT;
00061
00062     MTRY:
00063
00064 00025         IF !MB071003 == 1                                " Main Transfer Y Carry Out Pos
00065
00066 00026             IOW MB070763 == 1                                " Main Transfer Y Carry Out Pos Enable
00067
00068 00027             ML16006 = ML60610                                " Move Data:Main Transfer Y Carry Out Po
00069 s
00070             MOV [MTRY1]ML16006 [MTRY2]ML16006;
00071 00029             IOW MB071003 == 1                                " Main Transfer Y Carry Out Pos Moving C
00072 omp Check
00073             IEND;
00074 00031             JOINTO Label0X;
00075
00076     MTRX:
00077
00078 00032             IOW MB071033 == 1                                " Main Transfer T Carry Out Pos Check
00079
00080 00033             IF !MB071013 == 1                                " Main Transfer X Carry Out Pc ;
00081 00034                 IOW MB070773 == 1                                " Main Transfer X Carry Out Pos Enable
00082
00083 00035                 ML16010 = ML61010                                " Move Data:Main Transfer X Carry Out Po
00084 s

```

```
00084 00036          MOV [MTRX]ML16010;
00085
00086 00037          IOW MB071013 == 1          " Main Transfer X Carry Out Pos Moving C
omp Check
00087 00038          IEND;
00088
00089 00039          JOINTO Label10X,
00090
00091          MTRT:
00092
00093 00040          IF !MB071033 == 1          " Main Transfer T Carry Out Pos
00094 00041          IOW MB070783 == 1          " Main Transfer T Carry Out Pos Enable
00095
00096 00042          ML16016 = ML72210          " Move Data:Main Transfer T Carry Out Po
s
00097 00043          MOV [MTRT]ML16016;
00098
00099 00044          IOW MB071033 == 1          " Main Transfer T Carry Out Pos Moving C
omp Check
00100 00045          IEND;
00101
00102 00046          JOINTO Label10X;
00103
00104 00047          Label10X: PJOINT;
00105
00106
00107 00048          MB071372 = 0;          " Unit7 Cycle1 Move Check
00108
00109 00049          RET;
```