

```

00001      *****
00002      ** DL Register Area - 120Word
00003      **
00004      ** DW00000 - DW00009 (Pls Use)
00005      ** DW00010 - DW00039 (Bit Use)
00006      ** DW00040 - DW00089 (Word Use)
00007      ** DW00090 - DW00119 (Timer)
00008      *****
00009
00010      "# Program Name      :
00011      "# Function      :
00012      "# Call Program      :
00013      "# Sub Program      :
00014      "# Func Program      :
00015
00016      VAR;
00017
00018      END_VAR;
00019
00020 00000  IF MB000181 == 1;
00021 00001      PLD [STR1Y1][STR1Y2][STR1Z1][STR1Z2];
00022
00023
00024 00002      PFORK STRY STRZ;
00025
00026      STRY:
00027
00028 00003          IF !MB076000 == 1                                " Stick Transfer 1 Y StandBy Pos
00029
00030 00004              IOW MB075760 == 1                                " Stick Transfer 1 Y StandBy Pos Enable
00031
00032 00005              ML16032 = ML63202                                " Move Data:Stick Transfer 1 Y StandBy P
00033 os
00034              MOV [STR1Y1]ML16032 [STR1Y2]ML16032 ;
00035 00007              IOW MB076000 == 1                                " Stick Transfer 1 Y StandBy Pos Moving
00036 00008  Comp Check
00037              IEND;
00038 00009      JOINTO Label0X,
00039
00040
00041      STRZ:
00042
00043 00010          IF !MB76010 == 1;
00044 00011              IOW MB075770 == 1                                " Stick Transfer 1 Z Standby Pos Ena
00045 ble
00046 00012              ML16036 = ML63602                                " Move Data:Stick Transfer 1 Z Stand
00047 00013  By Pos
00048              MOV [STR1Z1]ML16036 [STR1Z2]ML16036;
00049 00014              IOW MB076010 == 1                                " Stick Transfer 1 Z Pos Moving Comp
00050 Check
00051 00015              IEND;
00052
00053 00016      JOINTO Label0X,
00054
00055
00056 00017      Label0X: PJOINT;
00057 00018      IEND;
00058
00059 00019      MB076370 = 0;                                " Unit8 Cycle1 Move Check
00060
00061 00020      RET;

```