

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name      :
00011 "# Function          :
00012 "# Call Program      :
00013 "# Sub Program       :
00014 "# Func Program      :
00015
00016 VAR;
00017     CONST LONG Axis_SBTY = 21;
00018     CONST LONG Axis_SBT  = 22;
00019 END_VAR;
00020
00021 00000     PLD [SBTY][SBT].
00022
00023 00001     DW00000 = 0;
00024 00002     DL00010 = 10000;
00025 00003     DL00020 = 0;
00026 00004     DL00022 = 0;
00027
00028     "SBT Brush Up Status
00029 00005     IF !MB081820 == 1;
00030 00006         MB080800 = 0;
00031 00007         TIM T100;
00032 00008         MB080820 = 1;
00033 00009     IEND;
00034
00035     " SBT AirKin Off Status
00036     //IF !MB81871 == 1;
00037 00010         MB0080871 = 1;
00038         //IOW MB081871 == 1;
00039     //IEND;
00040
00041 00011     IF !MB002007 == 1;
00042         " SBT Blow Off Status
00043 00012         IF !MB081870 == 1;
00044 00013             MB080870 = 1;
00045 00014             IOW MB081870 == 1;
00046 00015         IEND;
00047         " SBT Vacuum Off Status
00048 00016         IF !MB081850 == 1
00049 00017             MB080850 = 1;
00050 00018             IOW MB081850 | MB000800 == 1;
00051 00019         IEND;
00052 00020     ELSE;
00053         " SBT Blow Off Status
00054 00021         IF !MB081870 == 1;
00055 00022             MB080870 = 1;
00056 00023             IOW MB081870 == 1;
00057 00024         IEND;
00058         " SBT Vacuum On Status
00059 00025         IF !MB081840 == 1
00060 00026             MB080840 = 1;
00061 00027             IOW MB081840 | MB000800 == 1;
00062 00028         IEND;
00063 00029     IEND;
00064
00065 00030     IF MW08362 == 1;
00066 00031         DL00022 = ML72410
00067 00032     ELSE;
00068 00033         IF MW08362 == 2;
00069 00034             DL00022 = ML72414
00070 os
00071 00035         ELSE;
00072 00036             DL00022 = ML46254
00073 os
00074         IEND;
00075 00037     IEND;
00076 00038
00077 00039     IF ILAF16 > DL00022;
00078 00040         DL00020 = ILAF16 - DL00022;
00079 00041     ELSE;
00080 00042         DL00020 = DL00022 - ILAF16;
00081 00043     IEND;
00082 00044
00083 00045     IF DL00020 > DL00010
00084 00046         DB000000 = 1;
00085 00047     IEND;
00086
00087 00048     IF DB000000 == 1;

```

```

00086 00048      MW08340 = 2;
00087 00049      MSEE MPS500;
00088 00050      IEND;
00089
00090 00051      PFORK SBTY SBTT;
00091
00092      SBTY:
00093
00094 00052      IF !MB081003 == 1
00095
00096 00053      IOW MB075293 & MB07529B == 1
00097
00098 00054      IOW MB080763 == 1
00099
00100 00055      Enable
00101 00056      ry Out Pos ML16042 = ML64210
00102
00103 00057      MOV [SBTY]ML16042;
00104 00058      IOW MB081003 == 1
00105
00106 00059      Moving Comp Check
00107      IEND;
00108
00109      JOINTO Label0X;
00110
00111      SBTT:
00112
00113 00060      IOW MB080775 == 1
00114 //      IOW MW08362 <> 0;
00115 00061      IF MW08362 == 1;
00116 00062      ML16044 = ML72410
00117
00118 00063      os
00119 00064      ELSE;
00120 00065      IF MW08362 == 2;
00121      ML16044 = ML72414
00122
00123 00066      os
00124 00067      ELSE;
00125      ML16044 = ML46254
00126
00127 00068      os
00128 00069      IEND;
00129 00070      IEND;
00130
00131 00071      MOV [SBTT]ML16044;
00132 //      IF MW08362 == 1;
00133 00072      IOW MB081013 == 1
00134
00135 00073      Comp Check
00136 //      ELSE;
00137 00074      IF MW08362 == 2;
00138 //      IOW MB081014 == 1
00139
00140 00075      Comp Check
00141 //      ELSE;
00142 00076      IOW MB081017 == 1
00143
00144 00077      Comp Check
00145 //      IEND;
00146 //      IEND;
00147
00148 00078      JOINTO Label0X;
00149
00150 00079      Label0X: PJOINT;
00151
00152 00080      MB081372 = 0;
00153
00154 00081      RET;

```

" Stick Buffer Y Table Turn Pos

" Stick Buffer Table Y Carry Out Pos

" Stick Transfer 2 Z Standby Position

" Stick Buffer Table Y Carry Out Pos

" Move Data:Stick Buffer Table Y Car

" Stick Buffer Table Y Carry Out Pos

" Stick Buffer Table T Carry Out Pos Enable

" Move Data:Stick Buffer Table T Carry Out P

" Move Data:Stick Buffer Table T Carry Out P

" Move Data:Stick Buffer Table T Carry Out P

" Stick Buffer Table T Carry Out Pos Moving

" Stick Buffer Table T Carry Out Pos Moving

" Stick Buffer Table T Carry Out Pos Moving

" Unit9 Cycle1 Move Check