

Full family list in hand (60-odd families). Here's the best-judgement pass, keyed off the supplier's three grades and each family's material class:

JF25UF-h6 (default — steel, stainless, other metals): every metal-cutting family. All aluminium (A, AF, AR, ARV, AV, AVX, AX, BA, BLA1-3, BLAT1-3), all steel/general (B, BC, C, CD, CR, D, DT, E, EV, ED, F, FD, HF, RE, R, T, U, V, V2, VX, VX2, X), ball/hardened (BH, BL1-3, BLT1-3), Hard Cut (H), ISO M/S (M), titanium (S).

JU09 (carbon fibre, composite, routing plastics): all composite families (K, KC, KCX, KX, KD, KDX) and plastics (P, HP Hard Plastics/Acrylic).

JU03 (wood working): wood families (W, WC, WF).

Tolerance: h6 default across the board (matches the generator).

Three I want to flag rather than guess hard on:

- **G (Foam Endmill)** — foam isn't metal, wood, or composite. I've provisionally put it on JU09 (closest fit, soft-material routing), but it's a genuine judgement call for us.
- **h5 candidates** — h5 (tighter shank tolerance) is where I'd most expect us to override the h6 default: the finishing families (F, AF, WF) and the hard/exotic ones (H, S) are the obvious ones to review, since those are precision-sensitive. I've left them all h6 for now.
- **I (BANNED FROM USE) and Y (Experimental)** — no grade assigned; I is banned, Y is a placeholder.

[Want me to write this into D17](#) as the starting rule (with those flags noted), and should G go to JU09 as I've provisionally set it, or would you rather park G specifically for us to decide later?