

AEGIS AI -- Automated Emergency Response Report

Generated 2026-07-23 07:09 UTC

Incident INC-AUTO-2-1784790584 (id 48)

Hazard class: explosion

Equipment: V-12

Zone: 3

Risk score: 0.0/100 | Severity: low | Confidence: 0%

AI-Generated Summary

Automated risk assessment flagged a explosion risk on V-12 at a score of 0.0/100 (confidence 0%). This assessment was produced by the versioned Bayesian Risk Fusion Engine, not this summary generator -- the summary only narrates what was already computed.

Top contributing evidence:

- sensor:fuel_gas (likelihood ratio 0.1)
- sensor:fuel_pressure (likelihood ratio 0.1)
- equipment_health:confinement_integrity (likelihood ratio 0.1)

Counterfactual: removing 'fuel_in_range' from the evidence would change the posterior to 0.0% (from the current assessed probability).

No governing procedure/regulation could be retrieved above the minimum confidence threshold for this hazard class.

Contributing Factors (ranked by evidentiary weight)

- sensor:fuel_gas (likelihood ratio 0.05) refs: 1
- sensor:fuel_pressure (likelihood ratio 0.06) refs: 2
- equipment_health:confinement_integrity (likelihood ratio 0.07) refs: V-12
- sensor:ignition_temp (likelihood ratio 6.36) refs: 4

Recommendations

- Investigate the gas concentration reading and verify containment integrity on the affected line.
- Verify process pressure against the line's design envelope; a rise here alongside gas evidence suggests contained accumulation.
- Prioritize an inspection of pressure-relief and containment equipment in this equipment's neighborhood.

Response Timeline

- [2026-07-23T07:09:45.328568Z] created
- [2026-07-23T07:09:45.655563Z] auto_response_started
- [2026-07-23T07:09:46.331211Z] users_notified
- [2026-07-23T07:09:47.018011Z] emergency_team_notified
- [2026-07-23T07:09:47.350519Z] evacuation_activated
- [2026-07-23T07:09:47.936067Z] sensor_data_captured
- [2026-07-23T07:09:48.264188Z] evidence_stored
- [2026-07-23T07:09:50.473584Z] ai_summary_generated