P 3.4 Control of Critical Steps and Intermediates

Manufacturing stage	Machine Parameters	Process Parameters	CQA (Critical Quality Attributes)
Dry Mixing	1.Speed of impeller	Mixing time	1. Assay
Wet Granulation (Preparation of wet granules)	1.Speed of impeller 2.Chopper speed	1.Binder addition time 2.Mixing time	1. Impeller speed: Slow RPM and Fast RPM. 2. Chopper speed: Fast RPM. 3. Impeller Amperage Load
Drying	1. Inlet temperature 2. Outlet temperature	1. Drying time	1.Moisture content
Milling of oversized dried granules	1.Screen size	1.Milling Speed	1. Consistent dried granules
Lubrication	1. Speed of blender	1.Mixing time	1. Assay 2. Water Content 3. TD and BD
Compression	1.Speed of Compression Machine 2. Force feeder speed 3. Tonnage	Low hardness High hardness Minimum Speed Optimum Speed Maximum Speed	Average weight Group Weight Thickness Hardness DT Friability Assay Water content
Coating	1. Speed of pan. 2. Peristaltic pump RPM	1. Inlet air temp. 2. Bed Temperature. 3. Exhaust Temperature. 4. Spray rate.	Description, Weight of 20 enteric coated tablets, Thickness, Disintegration test Assay Water content Average weight

Manufacturing stage	Machine Parameters	Process Parameters	CQA (Critical Quality Attributes)
			Dissolution
Blister packing	1.Forming temp. Sealing roller temp. 2. Speed of blister machine	-	Leak Test