


Mains Connections v1



Notes

- make sure the shorting bars (in Purple) across the terminals are only 3 units wide
- Use ring crimps on the SSR connections (4mm id)
- Use a small amount of heatsink compound between SSR and Aluminium plate

