


HDC Connections

HDC Connector


From	Cable colour / size AWG	Length mm	To Pin			
Chamber Heater L	Brown Silicone/18		1			
Chamber Heater N	Blue Silicone/18		2			
Chamber Heater E	Green Silicone/18		3			
N/C			4			
N/C			5			
N/C			6			
From	Cable colour / size AWG	Length mm	To pin			
Chamber Thermister	White/22		1			
Chamber Thermister	White/22		2			
FAN Tacho	yellow/22		3			
Fan PWM	Blue/ 22		4			
Fan Chamber +12	Red /18		5			
Fan Chamber gnd	Black/18		6			
From	Cable colour / size AWG	Length mm	To Pin			
Heated bed L	Used Supplied? Via thermal Fuse	500	1			
Heated bed N	Used Supplied	500	2			
Aluminium Bed	Green silicion/18	500	3			
N/C			4			
N/C			5			
Heater Bed Thermistor	Used Supplied	500	6			
Heater Bed Thermistor	Used Supplied	500	7			
N/C			8			
Anvil Sensor	white/22	800	9			
Anvil Sensor	white/22	800	10			

HDC 1




Plug view of screw terminals

HDC 2




Socket view of screw terminals

HDC 3



Socket view of screw terminals




HDC, 1 2 3

Place a blob of RTV over the L and N connections , safety precaution in case the screws come loose!

HDC Connector


HDC 1



Socket view of
screw terminals

From pin	Cable colour/size AWG	Length mm	To		
1			SSR Terminal 2		
2			Blue Terminal Block		
3			Earth Terminal Block		
4			N/C		
5			N/C		
6			N/C		


HDC 2



FromPin	Cable colour/size AWG	Length mm	To
1			TEMP 2/VSSA
2			TEMP 2/temp2
3			out6.tach
4			out6_out
5			Yellow Terminal Block
6			Black Terminal Block


Plug view of
screw terminals

HDC 3



Plug view of
screw terminals

From Pin	Cable colour/size AWG	Length mm	To	
1			SSR Terminal 2	
2			Blue Terminal Block	
3			Earth Terminal Block	
4			N/C	
5			N/C	
6			TENP 3/VSSA	
7			TENP 3/temp3	
8			N/C	
9			IO_2/io1in	
10			IO_2/GND	



HDC, 1 2 3

Place a blob of RTV over the L and N connections , safety precaution in case the screws come loose!