


DC power



Notes

make sure the shunting bars (in Purple) across the terminals are only 3 units wide, and spacers inserted between each block of 3