


DC Power Connections



Notes

Make sure the shorting bars (in Purple) across the terminals are only 3 units wide, and spacers inserted between each block of 3