Cryptolyte Upgrade Chart

Controller	BECSys5 (S/N >= 2974)*				
Version	v1.xx	v2.xx	v3.00 - v3.50	v3.52 and up	
LUI Upgrade Kit	2210623-M000149	2210623-M000149			
Program IC	(included in LUI upgrade kit)	(included in LUI upgrade kit)	M000149		
Cryptolyte Add-On	M000151	M000151	M000151	M000151	
chlorine dioxide sensor	2100490	2100490	2100490	2100490	

Controller	BECSys7 with filtration control			
Version	v1.xx	v2.xx	v3.00 - v3.50	v3.52 and up
LUI Upgrade Kit	2210625-M000150	2210625-M000150		
Program IC	(included in LUI upgrade kit)	(included in LUI upgrade kit)	M000150	
Cryptolyte Add-On	M000151	M000151	M000151	M000151
chlorine dioxide sensor	2100490	2100490	2100490	2100490

Controller	BECSys7c without filtration control			
Version	v1.xx	v2.xx	v3.00 - v3.50	v3.52 and up
LUI Upgrade Kit	2210625-M000152	2210625-M000152		
Program IC	(included in LUI upgrade kit)	(included in LUI upgrade kit)	M000152	
Cryptolyte Add-On	M000151	M000151	M000151	M000151
chlorine dioxide sensor	2100490	2100490	2100490	2100490

Example

If you are adding Cryptolyte control to a BECSys5 with v2.40 firmware, you will need:

Qty 1, PN **2210623-M000149** BECSys5 LUI Upgrade Kit with M000149 program IC Qty 1, PN **M000151** Cryptolyte Add-On, to enable Cryptolyte in controller

Qty 1, PN **2100490** Chlorine dioxide sensor and flow cell

NOTE: BECSys5's Serial Number <= 2973 have a DIP program IC, which is no longer supported. The last of these BECSys5's was shipped in March 2012.