Tiva TM4C1294NCPT Traffic Light Controller Testing Document

This document describes the testing procedure of the software. Refer to: 1. Requirements 2. Architecture and Design

For software details.

Wiring Table

- MR Main Road
- SR Side Road
- G Green
- Y Yellow
- R Red

LED or Button	uC pin	LabJack pin
MR Car G	K7	EIO-7
MR Car Y	K6	EIO-6
MR Car R	K5	EIO-5
SR Car G	K2	EIO-2
SR Car Y	K1	EIO-1
SR Car R	K0	EIO-0
MR Ped G	L5	FIO-7
MR Ped R	L4	FIO-6
SR Ped G	L1	FIO-5
SR Ped R	L0	FIO-4
Mode Change	M0	CIO-0
MR Ped Button	M1	CIO-1
SR Ped Button	M2	CIO-2
Car Sensor	M3	CIO-3

Tests:

Button tests are done, by pressing the button before beginning the test.

- Button 1: Main Pedestrian button
- Button 2: Side Pedestrian button
- Button 3: Car Sensor

In Total There will be 12 Tests, 4 button press cases for each of 3 operating modes:

Test Name	Test Usage	Requirement
Standard	To check the operation of all LEDs.	RE1, RE4, RE5, RE6

Test Name	Test Usage	Requirement
Standard	The button press should alter LED	RE2, RE7, RE8
Button 1	operation.	
Standard	The button press should alter LED	RE2, RE7, RE8
Button 2	operation.	
Standard	Button press should be ignored .	RE2
Button 3		
Rush	To check the operation of all LEDs.	RE1, RE3, RE4, RE5, RE9
Rush Button 1	Button press should be ignored.	RE2, RE10
Rush Button	Button press should loop the	RE2, RE11
2	operation 1 cycle.	,
Rush Button	Button press should loop the	RE2, RE7, RE11
3	operation 1 cycle.	
Night	To check the operation of all LEDs.	RE1, RE3, RE4, RE5,
		RE12, RE13
Night Button	Button press should interrupt the	RE2, RE14
1	blinking.	
Night Button	Button press should interrupt the	RE2, RE14
2	blinking.	
Night Button 3	Button press should be ignored.	RE2
<u> </u>		

Test Data:

The data of the tests can be found at: Test Data

Test Results:

The results of the tests can be found at: Test Results

Interpretation of the tests:

While almost everything has worked as intended, there is a problem with the main pedestrian button. Throughout all the tests directly involving this button, it has not shown any changes to the behaviour of the operation. This a bug in the software.

Test Status:

Test Name	Test Status
Standard	Passed
Standard Button 1	Failed
Standard Button 2	Passed

Test Name	Test Status
Standard Button 3	Passed
Rush	Passed
Rush Button 1	Passed
Rush Button 2	Passed
Rush Button 3	Passed
Night	Passed
Night Button 1	Failed
Night Button 2	Passed
Night Button 3	Passed