

Hero / Header Section

- Item: Pocket Weather Meter
- Make: Kestrel
- Model: 3000 AN



- Photo:

- Quick note: Portable anemometer for field wind, temp, and humidity checks. Scan NFC tag for manuals, calibration, and logs.

Public Information (Visitor-Friendly)

Manufacturer & Documentation:

- [Product page – Kestrel 3000 AN](#)
- [User manual PDF](#)

Technical / Asset Info:

- NSN: 6660015072650
- Distributor: sales@r-p-r.co.uk
- Battery: CR2032
- Calibration:
 - Impeller: 1% per 100 hrs
 - Temp sensor: not required
 - Humidity sensor: 2% over 24m
- Storage: Remove battery for long-term storage

- Replacement cost: ~£200

Usage Notes:

- Ideal for field checks of wind, temperature, and humidity
- Not for life-critical measurements — verify calibration before mission use.

Optional Owner / Nerd Section (Collapsible)

Apple Shortcuts / Automation Links:

- Open manual → Launch PDF in Books or Files
- Log battery change → Update Notes log with timestamp
- Update calibration date → Record new calibration in Notes
- Email supplier → Prefilled email to sales@r-p-r.co.uk

Calibration / Usage Logs (example):

Date	Event	Notes	Logged by
24 Jan 2026	New battery	CR2032, checked voltage	Richie

10 Jan 2026	Calibration done	Impeller checked, humidity sensor within tolerance	
----------------	---------------------	---	--

Advanced Tips:

- Keep away from strong magnetic fields during measurement
- Remove battery for long-term storage to avoid leakage
- Optional: use small protective pouch for impeller

Sharing / Access Notes

- Hub page URL: <https://mysharedhub.com/kestrel3000an>
- Visitors just open → see manuals, key info, usage notes
- Owner-only section remains collapsed for casual users
- Apple Shortcuts links only work if iPhone has shortcuts installed