

Office No. 2, Gold Wings, 1st Floor, Above Darshan Tyres, Opp. Big Bazaar, Sinhgad Road, Pune – 411 030 Tele/fax: (020) 24251225, Mob: 98220 21012, Email: kamalbiyani@gmail.com

FINAL SURVEY REPORT

Surveyor Ref:

No: 15099/ICICI/19-20 Insured Name: Persistent Systems limited

Report Date: December 30, 2019. Claim No: FIR005146566

STRICTLY CONFIDENTIAL & PRIVILEGED FOR THE USE OF INSURERS AND THEIR LEGAL ADVISORS ONLY

NAME OF INSURED : Persistent Systems Limited

ADDRESS OF THE INSURED 402 E, Bhageerath, Senapati Bapat Road,

Pune. Maharashtra Pin-411016.

NAME OF INSURERS ICICI Lombard GIC LTD,

206-219 Sohrab Hall,

Opp to Pune Railway Station,

Pune 411001

LOCATION OF LOSS, WITH PIN CODEPersistent Systems Limited,

Aryabhatta-pingala- off karve road,

Erandwane, Pune-411004

DATE OF LOSS : 15th October 2019

DATE AND TIME OF INSTRUCTION FROM: 16th October 2019

INSURER

TIME & DATE OF VISIT : 17th October 2019

NAME OF POLICY : Standard Fire and Special Perils Insurance

POLICY NO : 1001/169305424/00/000

April 01, 2019 To March 31, 2020

:

RISK LOCATION : Aryabhatta-pingala- off karve road,

Erandwane, Pune-411004

OCCUPATION : Office premises, Meeting rooms.

TOTAL SUM INSURED FOR AFFECTETD

LOCATION (Aryabhatta-pingala- off

karve road, Erandwane, Pune)

Total sum Insured for affected location:

Rs.15,000,000.00+ Rs. 2,488,400,000.00 =

Rs. 2503400000.00. Details are as follows:

Location of Risk(10)

Total	15,000,000.00
Plant and Machinery	15,000,000.00
COMPONENET	Sum Insured in Rs.

Location of Risk(18)

COMPONENET	Sum Insured in Rs.
Building (with Plinth &	1,454,800,000.00
foundation	
Plinth & Foundation	218,200,000.00
Plant, Machinery and	844,500,000.00
Accessories	
Furniture Fixture &	151,000,000.00
Fittings	
Electrical Fittings &	38,100,000.00
Installations	
Total	2,488,400,000.00

AFFECTED ITEM : Solar Inverter (under Plant & Machinery)

INCIDENT: It was reported that due to heavy rains on

9th October 2019 water was accumulated

on the terrace floor of the building where

batteries, battery inter cell connectors and

inverter are installed. Due to incessant water

accumulation, there was short circuit inside

the inverter leading to system failure.

CAUSE OF LOSS

Due to heavy rain and rain water

accumulation

NATURE AND EXTENT OF DAMAGE

We visited the premises at location Aryabhata-Pingala, Erandwane, CYS No. 12A/12, Pune on 17th October 2019 to survey the loss to Solar inverter 125KVA reportedly caused due to heavy rain. At the time of our inspection, internal parts of the inverter such as DC filter capacitors, IGBTs, snubber circuits were found in burnt condition. Insured was advised to provide the quotation and repair invoice for the damaged items. Further Insured had shared quotation for repairs. We have assessed the loss based on such quotation and our observations.

ASSESSMENT OF LOSS

Insured have provided us the repair quotations of **Rs.** 1,28,000.00 obtained from PSL/Solar Inverter/Pune/NMD dated 15th October 2019 for the damaged parts of inverter. As per the Policy held by Insured, Sum insured availed for loss location is **Rs.** 250,34,00,000.00. Policy excess for Policies having Sum Insured above INR 100 cr and up to INR 1500 cr per location is 5% of claim amount subject to a minimum of INR

5,00,000.00. Thus claim amount falls below applicable excess. Please refer assessment sheet for detailed working.

The assessment of loss works out to Rs. **Nil.** The detailed assessment is attached as Annexure to the report. Our assessment of loss was shared to the Insured wide our mail 27th December 2019.

ADMISSIBILITY

Policy Period Covered
 Date of loss Covered
 Loss location Covered
 Peril operated Covered

The date of loss falls within the policy period. The peril operated is also covered under the Policy issued to and held by the Insured. Hence, the claim is admissible under the policy.

This report is issued without prejudice & subject to the terms, conditions and warranties to the policy issued to & held by the insured.

DECLARATION

 We hereby declare that the photographs of the affected property as detailed in our report were snapped by us by our Digital Camera and uploaded on our Office Computer. These were got printed in-house and are not manipulated. • We hereby declare that we have no interest in the subject matter in question and reported as above. We are neither related to the Insured nor the business either by blood, business or share-holding of whatsoever nature.





K. R. BIYANI KAMAL BIYANI ASSOCIATES License No. SLA 34365 valid till 27.11.2022 Encl:

- Annexure of assessment of loss.
- Policy copy
- Quotation (PSL/Solar Inverter/Pune/NMD) for repairs
- Photographs
- Our fee bill