Off. no. 2, 1st floor, 'Gold Wings', oop. Big Bazaar, Behind Aditya Nakoda Enclave, Above Darshan Tyres, Sinhgad Road, Parvati, Pune - 411030 Telefax - 020 - 24251225 | Cell- 9822021012 | E-mail - kamalbiyani@gmail.com





To,

CICI Lombard GIC LTD, 206-219 Sohrab Hall,

Opp to Pune Railway Station,

Pune 411001

**Kind Attn:** Mr. K K Chaithanya Manager Customer Service

Our Ref No.: 14971/ICICI/19-20

**Date:** 10<sup>th</sup> September 2019 **Claim No.** FIR002765777

IMMEDIATE LOSS ADVICE

DATE OF LOSS : 4th August 2019

**DATE AND TIME OF INSTRUCTION** : 6<sup>th</sup> August 2019

FROM INSURER

TIME & DATE OF VISIT : 7<sup>th</sup> August 2019

PERSON CONTACTED Mr. Nikhil Lohar

Mobile No. 9561395692

NAME OF INSURED : M/s. Yug Motors

ADDRESS OF THE INSURED Sr. No 269, 1 2 3, Aundh Hinjewadi Brts Rd Sahara

**/LOCATION OF LOSS, WITH PIN** Chowk Shedge Wasti, Hinjewadi, Pune,

CODE Maharashtra - 41 1057, India.

Contact Details: +91-7276751799

NAME OF POLICY : Standard Fire And Special Perils Insurance

**POLICY NO** : 1001/170695403/00/000

April 30, 2019 To: Midnight of April 29, 2020

AFFECTED ITEM : Building

Sum Insured Rs. 10,000,000.00

**SUPPOSED CAUSE** : Due to Flood/Inundation

## NATURE AND EXTENT OF DAMAGE

We carried out the survey on 7th August 2019. The insured has dealership of Honda two wheelers wherein sales and service is provided. The building was having two levels (Lower floor + Ground floor). The entire lower floor was submerged to the level of 5 to 8 feet. The stocks of two wheelers was kept under shed as well as in open yard. The premises was very near to the river and hence the level of inundation was very high. The stocks of new two wheelers, workshop equipment, FFF, painting of the building, wall etc were submerged. Water marks and mud traces were seen inside the lower floor. Insured have taken another policy for the stock coverage. This policy dealt only building thus, the could be considered under this policy. The wall was broken due to pressure of the water.

Insured were advised for following line of action .....

## **Line of action**

- To start the cleaning activity & to provide estimate for the same
- To keep the damaged material in demarcated place for further inspection

Insured was also advised to provide the requisite documents /information.

**POLICY LIABILITY** : Yes, loss is covered under the policy.

**POLICY** COVERAGE, SCOPE: STFI and allied perils are covered. Hence, the

(COVERAGE FOR PROPERTY AND operated peril is covered under the policy

MAIN PERIL OPERATION)

**INSURED'S ESTIMATE OF LOSS** : No estimate is indicated

PRESENTLY ESTIMATED LOSS RESERVE : Rs. 10,00,000/-

BASIS OF RESERVE : Reserves are based on our inspection.

issues : Policy is having basement exclusion – need to

be discussed

**DOES LOSS NEED FURTHER** : The premises is built on a slope. The front portion

**DISCUSSIONS WITH INSURERS?** is on the higher altitude than the rear portion.

Hence, the building is having two levels (just to

use the topography). It cannot be strictly termed as basement. Moreover, the open yard is also at the level of lower floor. The policy is having basement warranty. This aspect need to be discussed further.





K. R. BIYANI

## KAMAL BIYANI ASSOCIATES

License No. SLA 34365 valid till 27.11.2019













