

INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

e-mail: timeline.isla@gmail.com, Website: www.timelineisla.com

Er. Anil K. Pandey

B.E. (MECH.), MIEI, Chartered Engineer Fellow IIISLA (F/N-01028) (SLA28562) Fire, Marine & Engineering 8299390800, 9415202098

#### Dr. Jaya Pandey

Ph.D. (Economics), Associate III Licentiate IIISLA (L/N-07294, SLA74567) Marine & Miscellaneous Mob - 09993953500 Er. Abhinav Pandey

B. Tech, IIT-Kanpur, Chartered Engineer Licentiate IIISLA (L/N-8497, SLA85166) Fire Marine & Engineering 7982562479, 7065207736

REF: ILGI0553FRM19-20

DATED: 03.09.2019

#### PRE-RECEIPTED PROFESSIONAL FEE BILL

To,
ICICI Lombard General Insurance Co. Ltd.
ICICI Lombard House, 414, Veer Savarkar Marg,
Near Sidhi Vinayak Temple,
Prabhadevi, Mumbai-400025
GSTIN: 27AAACI7904G1ZN

#### Claim Ref No. :- FIR001840860

POLICY

No. 1001/166668722/00/000 (Standard Fire & Special Perils)

**INSURED** 

M/s Viviana Co-Operative Housing Society Ltd

RE

Survey & Assessment of loss on a/c damage to DG sets, Motors &

Lifts due to Inundation on 04.08.19

SN	DESCRIPTION	UNIT	QTY.	RATE	AMOUNT
1	GROSS LOSS	RS.	298023.60		
	PROFESSIONAL FEE ON	RS.	100000.00	FIXED	7125.00
	PROFESSIONAL FEE ON	RS.	198023.60	1.75%	3465.41
	SUB-TOTAL	RS.			10590.41
2	CONVEYANCE:Office-Dombivli to & fro	KMS	100.00	12.00	1200.00
3	PHOTOGRAPHS	NOS.	12.00	10.00	120.00
	TOTAL	RS.			11910.41
C 220	ADD: IGST			18.00%	2143.87
	GRAND TOTAL	RS.			14054

RS. FOUREEN THOUSAND AND FIFTY-FOUR ONLY

For TIMELINE Insurance Surveyors And Loss Assessors Private Limited

GSTIN		9AAFCT392	2N1ZW		
A/C NAME	NAME: TIMELINE INSURANCE SURVE	EYORS AND L	OSS ASSESSORS P	RIVATE I	IMITED
BANK NAME	KOTAK MAHINDRA BANK LIMITED	BRANCH	SIGRA, VARANASI	TYPE	CA
A/C NO.	573011030388	IFSC	KKBK0005305	MICR	221485005



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

e-mail: timeline.isla@gmail.com, Website: www.timelineisla.com

Er. Anil K. Pandey

B.E. (MECH.), MIEI, Chartered Engineer Fellow IIISLA (F/N-01028) (SLA28562) Fire, Marine & Engineering 8299390800, 9415202098

#### Dr. Jaya Pandey

Ph.D. (Economics), Associate III Licentiate IIISLA (L/N-07294, SLA74567) Marine & Miscellaneous Mob - 09993953500 Er. Abhinav Pandey

B. Tech, IIT-Kanpur, Chartered Engineer Licentiate IIISLA (L/N-8497, SLA85166) Fire Marine & Engineering 7982562479, 7065207736

REF: ILGI0553FRM19-20

DATED: 03.09.2019

PRIVILEGED FOR UNDERWRITERS CONCERNED & THEIR LEGAL CONSULTANTS ONLY

## SURVEY & LOSS ASSESSMENT REPORT

ON A/C OF DAMAGE TO DG, MOTORS, LIFTS DUE TO INUNDATION ON 04.08.19

Claim Ref No:- FIR001840860

INSURED	M/s Viviana Co-Operative Housing Society Ltd
INSURER	M/s ICICI Lombard General Insurance Company Limited
POLICY NO.	1001/166668722/00/000 (Standard Fire & Special Perils)
EVENT	Damage to Lifts due to Inundation on 05.08.19

#### INTRODUCTION

Instructions were received from M/s ICICI Lombard General Insurance Co. Ltd., Mumbai on 07.08.19 to survey and assess the loss to DG, Motor, Lifts, etc due to Inundation on 04.08.19 at M/s Viviana Co-Operative Housing Society Ltd., Dombivli. Accordingly, survey was conducted by us on 08.08.19 & 10.08.19 and the Insured was requested to provide claim documents through our letter dated 11.08.19. Now we are pleased to submit our survey & assessment report as under for onward doing needful.

#### POLICY PARTICULARS

Policy No.

1001/166668722/00/000

Type

Standard Fire & Special Perils Policy

Issued by

M/s ICICI Lombard House, Veer Savarkar

Marg, Near Siddhi Vinayak Temple Main

Gate, Prabhadevi, Mumbai – 400025, Maharashtra

Insured

M/s Viviana Co-Operative Housing Society Ltd.

Ground Floor, A Wing, Casa Rio Gold Palava City, Nilje, Kalyan Shill Road, Dombivli East, Thane-421204, Kalyan-

Dombivali, Maharashtra Pin- 421204

Aldrina landey



# INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0553FRM19-20

DATED: 03.09.2019

Policy period

05.03.2019 to 04.03.2020

Occupancy Sum Insured **Dwellings** 

SN	Component	SUM INSURED
	Building (Without Plinth & Foundation)	39000000
2	Plinth & Foundation	110000000
TOT	AL	500000000

#### Conditions: -

- 1. Deductible: 5% of the claim amount subject to a minimum of INR 25,000 on each and every claim
- 2. Basement exposure is excluded from the scope of cover
- 3. Katcha Construction is excluded from the scope of the cover

### Special Conditions: -

- 1. Deductible :5% of the claim amount subject to a minimum of INR 25,000 on each and every claim
- 2. Basement exposure is excluded from the scope of cover
- 3. Katcha Construction is excluded from the scope of the cover
- 4. Following fixed assets are covered under the building sum insured Building (Building value includes 9 wings of G8 Floors having 423 flats & Society office & Furniture, Computer, DG Set 4 Nos, OH & UG water tanks, Lifts 9 Nos.,
- & Furniture, Computer, DG Set 4 Nos, OH & UG water tanks, Lifts 9 Nos., Electrical fittings, Meters & Meter Rooms, Pumps & Pump Rooms, CCTV, Intercom System, Fire Fitting with alarm system, Septic tank, Plate Glass, Biometric System and all other common amenities)
- 5. Earthquake is covered and Terrorism is excluded
- 6. Basis of Valuation Reinstatement Value excluding Stocks
- 7. Storm, Tempest, Flood, & inundation sets of Perils are covered under the scope of policy and Riot, Strike, Malicious Damage perils are covered under the policy
- 8. Cost of Expediting expenses Covered upto INR 5,00,000
- 9. Loss or damage to gardens, landscaping and trees/shrubs is excluded from the scope of cover
- 10. Proposal quoted on assumption that the building age is less than 5 years as on date

Clauses

1. FC03: Designation of Property Clause

2. FC05: Local Authorities Clause

Ablina Codey



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0553FRM19-20

DATED: 03.09.2019

3. FC14: Earthquake (Fire and Shock)

4. FC25: Removal of Debris Clause (upto 1% of the claim amount)

5. FC26: Architects, Surveyors and Consulting Engineers Fees (upto 3% of the

claim amount)

6. FC29: Terrorism Exclusion Clause

#### THE RISK

M/s Viviana Co-Operative Housing Society Ltd., located at Ground Floor, A Wing, Casa Rio Gold Palava City, Nilje, Kalyan Shill Road, Dombivli East, Thane-421204, Kalyan-Dombivali, Maharashtra-421204 is a residential complex. It has 9 Wings each having ground plus 8 floors, area of flats & number of flats in each wing provided by insured is enclosed. Walls are made of burnt bricks plastered with mortar cement and roof is RCC. Building SI also includes Society office & Furniture, Computer, DG Set 4 Nos, OH & UG water tanks, Lifts 9 Nos., Electrical fittings, Meters & Meter Rooms, Pumps & Pump Rooms, CCTV, Intercom System, Fire Fitting with alarm system, Septic tank, Plate Glass, Biometric System and all other common amenities

#### **OCCURRENCE**

As informed by Insured's Representative, Mr. Sandeep: - It started raining continuously from 03.08.19 till late night of 04.08.19. Water entered into society premises, pump rooms & lift pits upto a height of 4 ft. This water logging caused damaged to components of one lift, 4 DG sets, Pumps. Flats on ground floor got flooded with water upto 2 feet. Society belongings such as documents, audit reports, ledgers got damaged.

#### INSPECTION

On 08.08.19, we visited Insured's premises and the damages to walls on ground floor were verified in the presence of Mr. Sandeep & Incident Report was prepared.

We revisited on 10.08.19 to verify damages to DG sets, Pump & components of Lift in presence of respective Service engineers & quotations were collected depicting damages to various components that got submerged. As we approached the Lift pits we noticed that water had been logged upto height of approx. 4 ft as seen through marks on the pit walls.

3



# TIMELINE INSUBANCE SUBVEYORS AND

LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0553FRM19-20

DATED: 03.09.2019

12 Photographs taken by us depicting overall condition of the premises are hereby enclosed for perusal.

#### OPINION ON LOSS

During survey we observed that the walls of the lift pit had water marks upto a height of 4-5 feet and insured provided photographs depicting the society being submerged in water. The losses occurred due to excessive continuous rainfall which led to accumulation of water which entered these DG sets, Lifts & Pump along with mud causing damage to their components. Inundation is an insured peril of the SFSP policy in force thus the losses are indemnifiable.

#### EXTENT OF LOSS

Damages verified during survey as detailed per quotations enclosed.

#### **INSURED'S CLAIM**

The Insured provided quotations towards replacement of various components of 04 DG sets for Rs. 41,205.60(incl GST), cleaning charges for 04 DG Diesel Tank for Rs. 16,000.00(excl GST), rewinding of Alternator for Rs. 50,150.00(incl GST), varnish & servicing of Alternator for Rs. 22,302.00(incl GST), repaint on walls of I-H wing 25 flats at ground floor for Rs. 1,15,000.00(excl GST), repair of Pumps for Rs. 13,600.00(excl GST), replacement of components of Lift for Rs. 39,766.00(incl GST), enclosed for perusal.

## ADEQUACY OF INSURANCE

#### BUILDING

SI against building is Rs. 50,00,00,000.00 (with Plinth & Foundation) taken on Reinstatement Value Basis. The Insured did not provide Valuation Report of the Building to obtain value at risk, but revealed construction area of all flats as 2,27,268.00 sqft. Considering construction rate is Rs. 2100.00/sqft RIV is computed & compared with SI to arrive at underinsurance, as under: -



#### INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

AREA/SQFT

25252

227268

REF: ILGI0553FRM19-20

SUM INSURED
UNDERINSURANCE

RATE/SQFT	AMOUNT (RS.)
2100.00	477262800.00
	5000000.00
	482262800.00
	500000000.00

DATED: 03.09.2019

#### ASSESSMENT OF LOSS

Area on one Wing (47 flats)

**PARTICULAR** 

Building Total of 9 wings (423 flats)

All Common amenities DG, Lifts, etc

Building including other amenities were damaged due to Inundation which is an insured peril of Standard Fire & Special Perils Policy. Thus, the losses are indemnifiable and are being assessed as per Annexure-A on basis of quotation, under the following considerations: -

- a) Lift: Quotation provided towards spare cost of electronic components that got shorted may be considered genuine & adequate for the purpose of assessment
- b) 04 DG sets: Quotation provided towards spare cost may be considered genuine & adequate for the purpose of assessment
- c) Quotation provided towards labour for cleaning of Diesel Tank may be considered genuine & adequate for the purpose of assessment
- d) Quotations provided towards rewinding, varnishing & servicing of Alternator of DG set may be considered genuine & adequate for purpose of assessment
- e) Building: Quotation provided towards repaint on lower 3 ft of 25 flats on ground floor may be considered genuine & adequate for the purpose of assessment
- f) Pump: Quotation provided towards rewinding & varnishing of 7.5 HP pumps & repairing of 2 HP pump may be considered genuine & adequate for the purpose of assessment

#### ADJUSTMENT OF LOSS

The loss assessed above is adjusted under following considerations: -

a) Insured has confirmed that they cannot avail GST credit thus considered

5



#### INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0553FRM19-20

DATED: 03.09.2019

- b) Policy taken on RIV but repair/reinstatement invoices not provided thus 5% depreciation suggested
- c) Nominal salvage value of Rs. 1000.00 may be deducted
- d) Underinsurance as computed above is nil
- e) Excess @ 5% of the claim amount subject to min. of Rs. 25,000.00 is being deducted

SN	PARTICULARS		Amount
	GROSS LOSS	INR	298023.60
	Less: Depreciation	5%	14901.18
	ASSESSED LOSS		283122.42
	LESS: SALVAGE		1000.00
	ASSESSED LOSS		282122.42
	LESS: POLICY EXCESS		25000.00
	NET ADJUSTED LOSS		257122.42

RS TWO LAC FIFTY-SEVEN THOUSAND ONE HUNDRED TWENTY-TWO ONLY

Survey & Loss Assessment report hereby issued without prejudice is subject to the terms & conditions of the policy; reserving our rights to amend unintended error, if any.

For TIMELINE Insurance Surveyors And Loss Assessors Private Limited

#### **Enclosure:**

- 1. Deputation Mail & Copy of Policy
- 2. Incident Report
- 3. PAN & Certificate of registration
- 4. Quotations/Estimates
- 5. Area of construction of flats
- 6. Photographs-12 & Professional Fee Bill

		A	Annexure-A					
S	DESCRIPTION	WOI		QTY	1		AMC	AMOUNT
			CLAIMED	ALLOWED	KAIE	3	CLAIMED	ALLOWED
∢,								
Н.	Multibeam Sensor	Pcs	1	н	23500	18%	27730 00	27730.00
7	G tech PCB	Pcs	1	-	10200		-	12026.00
	Sub-Total				00101		10	12036.00
മ	04 DG sets						32700.00	39/66.00
Н	Oil	Ltr	09	09	230	18%	16284 00	00 18781
7	Oil Filter Primary	Pcs	4	4	268		1264.00	1264.00
m	Oil Filter Secondary	Pcs	4	4	580		7737 60	2237 60
4	Fuel Filter	Pcs.	8	00	246		7377 74	1,575
2	Air Filter	Pcs	4	0 4	2250		1050000	1000000
9	Fan Belt	Prs	4		077	-	10020.00	10620.00
2	Coolant	- L	000	t c	100	-8	3634.40	
$\infty$	Battery Water	+ -	77	707	TRO	. 0	4248.00	42
	Sub-Total		4	4	20	18%	94.40	94.40
0	50 10						41205.60	41205.60
,	04 DO 3615							
-	Labour for Cleaning of Diesel Tank	S	4	4	4000		16000,00	1600000
	Sub-lotal						1600000	16000000
0	DG set						100000	T00000.00
1	Alternator Varnish & Service	51	1	,	40000	400%		
2	Alternator Rewinding	3 2	٠, ١	7	18900	18%	22302.00	22302.00
	Sub-Total	3	7	1	42500	18%	50150.00	50150.00
ш	25 flats G Floor						72452.00	72452.00
Н	Material: Repaint upto height 3 ft	ST	25	75	7000		000001	000
2	Labour	SI		0 -	15000		100000	100000
	Sub-Total		1	4	77000	1	117555 65	15000
ш	C-Wing LH						115000.00	115000.00
	7.5 HP motor rewinding	Nos	-	-	0000	T	0000	0000
7	Revarnishin	Nos	-	f (-	3500	T	3000	3000
3	Repairing 2 HP pump	NON	1 -	1 -	1000	T	3300	3500
	Sub-Total		1	<del>-</del> 1	0011		1100	1100
	GROSS ASSESSED LOSS					1	13600.00	13600.00
1							298023.60	298023.60