

INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

e-mail: timeline.isla@gmail.com, Website: www.timelineisla.com

Er. Anil K. Pandey

B.E. (MECH.), MIEI, Chartered Engineer Fellow IIISLA (F/N-01028) (SLA28562) Fire, Marine & Engineering 8299390800, 9415202098 Dr. Jaya Pandey

Ph.D. (Economics), Associate III Licentiate IIISLA (L/N-07294, SLA74567) Marine & Miscellaneous Mob - 09993953500 Er. Abhinav Pandey

B. Tech, IIT-Kanpur, Chartered Engineer Licentiate IIISLA (L/N-8497, SLA85166) Fire Marine & Engineering 7982562479, 7065207736

REF: ILGI0911RM19-20

DATED: 27.11.2019

PRE-RECEIPTED PROFESSIONAL FEE BILL

To,
ICICI Lombard General Insurance Co. Ltd.
ICICI Lombard House, 414, Veer Savarkar Marg,
Near Sidhi Vinayak Temple,
Prabhadevi, Mumbai-400025
GSTIN: 27AAACI7904G1ZN

Claim Ref No: - FIR006384076

POLICY No. 1001/160288655/00/000 (Standard Fire & Special Perils)

INSURED M/s Primia Cooperative Housing Society Ltd

RE Survey & Assessment of loss on a/c damage to Building & Contents due

to Fire on 09.11.19

| SN | DESCRIPTION | UNIT | QTY. | RATE | AMOUNT |
|----|-------------------------------------|------|-----------|--------|----------|
| 1 | GROSS LOSS | RS. | 172250.00 | | |
| | PROFESSIONAL FEE ON | RS. | 100000.00 | FIXED | 7125.00 |
| | PROFESSIONAL FEE ON | RS. | 72250.00 | 1.75% | 1264.38 |
| | SUB-TOTAL | RS. | | | 8389.38 |
| 2 | CONVEYANCE:Office-Dombivli to & fro | KMS. | 110.00 | 12.00 | 1320.00 |
| 3 | PHOTOGRAPHS | NOS. | 20.00 | 10.00 | 200.00 |
| 4 | DA | NOS. | 1.00 | 750.00 | 750.00 |
| | TOTAL | RS. | | | 10659.38 |
| | ADD: IGST | | | 18.00% | 1918.69 |
| | GRAND TOTAL | RS. | | 5 | 12578 |

RS TWELVE THOUSAND FIVE HUNDRED AND SEVENTY-EIGHT ONLY

For TIMELINE Insurance Surveyors And Loss Assessors Private Limited

| GSTIN 09AAFCT3922N1ZW | | | | | | |
|-----------------------|--------------------------------|------------|-----------------|----------|-----------|--|
| A/C NAME | NAME: TIMELINE INSURANCE SURVE | YORS AND L | OSS ASSESSORS P | RIVATE L | IMITED | |
| BANK NAME | KOTAK MAHINDRA BANK LIMITED | BRANCH | SIGRA, VARANASI | TYPE | CA | |
| A/C NO. | 573011030388 | IFSC | KKBK0005305 | MICR | 221485005 | |



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

e-mail: timeline.isla@gmail.com, Website: www.timelineisla.com

Er. Anil K. Pandey

B.E. (MECH.), MIEI, Chartered Engineer Fellow IIISLA (F/N-01028) (SLA28562) Fire, Marine & Engineering 8299390800, 9415202098 Dr. Jaya Pandey

Ph.D. (Economics), Associate III Licentiate IIISLA (L/N-07294, SLA74567) Marine & Miscellaneous Mob - 09993953500 Er. Abhinav Pandey

B. Tech, IIT-Kanpur, Chartered Engineer Licentiate IIISLA (L/N-8497, SLA85166) Fire Marine & Engineering 7982562479, 7065207736

REF: ILGI0911FRM19-20

DATED: 27.11.2019

PRIVILEGED FOR UNDERWRITERS CONCERNED & THEIR LEGAL CONSULTANTS ONLY

SURVEY & LOSS ASSESSMENT REPORT ON A/C OF DAMAGE TO BUILDING & CONTENT DUE TO FIRE CAUSED BY FIRE CRACKERS ON 09.11.19

Claim Ref No: - FIR006384076

| INSURED | M/s Primia Cooperative Housing Society Ltd |
|------------|--|
| INSURER | M/s ICICI Lombard General Insurance Company Limited |
| POLICY NO. | 1001/160288655/00/000 (Standard Fire & Special Perils) |
| EVENT | Damage to Building & Contents due to Fire caused by fire cracker in Flat no. 801 on 09.11.19 |

INTRODUCTION

Instructions were received from M/s ICICI Lombard General Insurance Co. Ltd., Mumbai on 11.11.19 to conduct survey and assess the loss to Building & Contents due to Fire caused by fire cracker in flat No. 801 on 09.11.19 at M/s Primia Co Operative Housing Society Ltd, Palava City, Dombivli East, Mumbai. Accordingly, survey was conducted by us on 11.11.19 and the Insured was requested to provide claim documents through our letter dated 14.11.19. Now we are pleased to submit our survey & assessment report as under for onward doing needful.

POLICY PARTICULARS

Policy No.

1001/160288655/00/000

Type

Standard Fire & Special Perils Policy

Issued by

M/s ICICI Lombard House, Veer Savarkar

Marg, Near Siddhi Vinayak Temple Main

Gate, Prabhadevi, Mumbai – 400025, Maharashtra

Insured

M/s Primia Co Operative Housing Society LTD

Society office, Ground Floor, B- wing, Casa Bella Gold, Palava City, Kalyan Shill Road, Dombivli East, Thane,

Maharashtra - 421204

Abhirar Ronde

CIN: U74120UP2015PTC070835, LICENCE NO.: IRDA/CORP/SLA-200016, EXP: 03.01.2022, PAN NO. AAFCT3922N, GSTIN ♦9AAFCT3922N1ZW



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0911FRM19-20

DATED: 27.11.2019

Policy period

26.11.2018 to 25.11.2019

Location of risk

Survey No. 11/16, Village Kattai, Casa Bella Gold,

Palava City, Kalyan Shill Road, Dombivli East, Thane,

Maharashtra - 421204

Occupancy

Dwellings

Sum Insured

| SN | INSURED COMPONENT | SUM INSURED (RS) |
|----|--|------------------|
| 1 | Building (Without Plinth & Foundation) | 189396800.00 |
| 2 | Plinth & Foundation | 46099200.00 |
| 3 | Others (Excluding stocks) | 144000000.00 |
| | Total Sum Insured with Plinth & Foundation | 379496000.00 |

Subject to Clause(s) / Endorsement(s) as attached herewith: -

1. FC03: Designation of Property Clause

2. FC05: Local Authorities Clause

3. FC14: Earthquake (Fire and Shock)

4. FC25: Removal of Debris Clause (upto 1% of the claim amount)

5. FC26: Architects, Surveyors and Consulting Engineers Fees (upto 3% of the claim amount)

6. FC29: Terrorism Exclusion Clause

Subject to Conditions as mentioned below: -

- 1. Loss or damage to gardens, landscaping and trees/shrubs is excluded from the scope of cover
- 2. Basement exposure is excluded from the scope of cover
- 3. Content Cover is on a First Loss basis
- 4. Contents for 144 flats of 2 BHK covered for Rs.10,00,000 each
- 5. The Coverage for Contents is on Market Value (Value for New minus applicable depreciation)
- 6. Following fixed assets are covered under the building sum insured 1) Building (Building value includes 3 wings of Stilt 8 Floors having 144 flats, Society office & Furniture, Computer, 1 DG Set, OH & UG water tanks, Lifts 3 Nos., Electrical fittings, Meters & Meter Rooms, Pumps & Pump Rooms, CCTV, Intercom System, Fire Fitting with alarm system, Septic tank ,Solar System, Security Cabins, Plate Glass, Biometric System and all other common amenities) 2) Home Contents Insurance (Individual flat Owners

Allina landey

2



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0911FRM19-20

DATED: 27.11.2019

contents value upto 10 Lacs covers Furniture, Durables, Electronic Items, Clothes & Utensils) 3) Building Contents Rs. 50,00,000/

7. Earthquake is covered and Terrorism is excluded

8. Cost of Expediting expenses Covered upto INR 5,00,000

- 9. Deductible: 5% of the claim amount subject to a minimum of INR 25,000 on each and every claim
- 10. Katcha Construction is excluded from the scope of the cover

11. Basis of Valuation Reinstatement Value excluding Stocks

- 12. Storm, Tempest, Flood, & inundation sets of Perils are covered under the scope of policy and Riot, Strike, Malicious Damage perils are covered under the policy
- 13. Content Covers is for Electronic Equipments, Furniture & Fixtures, consumer durables, Clothes & utensils owned or in care custody control by the residents (Jewellary/Watches and other precious stones are excluded from coverage)
- 14. Proposal quoted on assumption that the building age is between 5 years to 10 Years as on date
- 15. Loss Payee Clause: In the event of claim payment being made under the policy in relation to the insured risk, that payment can be made to individual member of the housing society subject to the NOC from Housing Society

OCCURRENCE

As informed by Arwa Burhanpurwal (Owner), on 09.11.19 around 08:45 PM a Rocket (Fire cracker) came flying inside balcony of her flat no. 801 C wing due to which clothes lying on racks & in laundry bag caught fire. Outdoor unit of AC installed in balcony area also caught fire which spread to the IDU as well. The fire caused damages to sliding door & glass between balcony & main hall and walls of balcony & main hall.

INSPECTION

On 11.11.19, we visited Insured's premises and the damages were verified in the presence of Arwa Burhanpurwal (Flat owner). During survey walls, roof, grill of balcony area & wall, roof of main hall found blackened and floor tiles of balcony area found cracked/dislodged, layout was prepared depicting areas with dimensions that needed repaint, etc. Electrical installations i.e. T.V cable wiring, LED bulb wiring & AC wiring were found burnt/melted & 01 LED bulb found cracked. Aluminium sliding door glass found in pieces & aluminum frame found

Allin landy



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0911FRM19-20

DATED: 27.11.2019

misshapen & wooden duct door installed in balcony area found severely burnt. 01 No. revolving chair, LG AC's indoor & outdoor unit found severely burnt, 01 No. carpet found darkened whereas photographs provided for clothes that were burnt but disposed off prior to our visit. We took 20 photographs depicting overall condition of damage flat & contents are enclosed for perusal.

OPINION ON LOSS

As Informed by insured a fire cracker landed in their balcony & fire caught onto clothes which spread through AC's ODU to IDU then main hall area. Fire is an insured peril under the SFSP policy in force, thus losses are indemnifiable.

EXTENT OF LOSS

Damages noted during survey as per JIR are depicted as under: -

| sn | DESCRIPTION | DETAIL | DIMENSION (IN FEET) | | | | |
|---------|----------------|--------------------|---------------------|-------|--------------------|--------------------------------|-------------------|
| SIN | | DETAIL | | WIDTH | - Chillian Charles | Condition | Remarks |
| | | Right wall | 10 | 6 | 60 | blackend | putty & painting |
| - 1 | | Left wall | 10 | 4 | 40 | blackend | painting |
| - 1 | | Minus Duct door | . 4 | 2 | 8 | 3 | |
| | | Net left wall | | | 32 | 2 | painting |
| 1 | Balcony | Roof | 9 | 4 | 36 | blackend | painting |
| | | Column | 4 | 12 | 48 | Blackend | painting |
| | | Floor Tiles | 4 | 8 | 32 | cracked/uprooted | replace |
| - | | Grill | 8 | 2 | 16 | blackend | painting |
| _ | | Façade | 12 | 10 | 120 | blackend | painting |
| | | Back wall | 12 | 10 | 120 | blackend | painting |
| | | Minus door | 7 | 3 | 21 | | |
| - | | Net right wall | | | 99 | | painting |
| 1 | | Right Wall | 11 | 10 | 110 | blackend | painting |
| 2 | Main Hall | Left wall | 14 | 10 | 140 | blackend | painting |
| | | Minus window | 4 | 3.5 | 14 | MEDIT | |
| 1 | | Minus sliding door | 8 | 8 | 64 | | |
| 1 | | Net Left Wall | | | 62 | | painting |
| | | Funiture/cabinet | 12 | 10 | 120 | Ash/Smoke/dust | chemical cleaning |
| \perp | | Roof area | 12 | 14 | 168 | blackend | painting |
| 3 A | Aluminium Slid | ling door | | | 3 | Frame mishapen & glass cracked | replace |
| _ | Vooden Duct I | | | | 1 | Burnt | replace |
| 5 L | ED Bulb & Bul | b wiring | | | 1 | Burnt/melted | replace |
| 6 T | V Cable wiring | 3 | | | 1 | burnt/melted | replace |

Abbinar Pandy



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0911FRM19-20

DATED: 27.11.2019

| DAI | MAGES TO CONTENT NOTICE | D DURING SURVEY | ON 11.11.19 |
|-----|---|-----------------|-------------|
| | DESCRIPTION | CONDITION | REMARK |
| 1 | Revolving Chair | Burnt | Replace |
| 2 | AC Indoor & Outdoor unit | Burnt | Replace |
| 3 | Carpet | Burnt | Replace |
| | 8 Burkhas, 4 Pant Shirts, 2 sets School uniforms, General Undergarments & 2 Jackets | Burnt | Replace |
| 5 | Clothes Hanging Plastic Rack | Burnt | Replace |
| 6 | Laundry Bag | Burnt | Replace |

INSURED'S CLAIM

Insured has claimed for Rs. 1,81,290.00 as per quotations provided for damages to Building & Contents.

ADEQUACY OF INSURANCE

BUILDING

SI against building is Rs. 18,93,96,800.00 (without Plinth & Foundation) taken on Reinstatement Value Basis. The Insured did not provide Valuation Report of the Building to obtain value at risk, but revealed construction area of all flats as 65,856.00 sqft. Considering construction rate as Rs. 2500.00/sqft RIV is computed & compared with SI to arrive at underinsurance, as depicted below: -

| PARTICULAR | AREA/SQFT | RATE/SQFT | AMOUNT (RS.) |
|------------------------------|-----------|-----------|--------------|
| Value of Building Total Area | 65856 | 2500.00 | 164640000.00 |
| RIV | | | 164640000.00 |
| SUM INSURED | | | 189396800.00 |
| UNDERINSURANCE | | | NIL |

ASSESSMENT & ADJUSTMENT OF LOSS

The loss is being assessed as per Annexure-A under following considerations: -

BUILDING

a) Quotations provided towards repaint of balcony, grill, main hall, replacement of Sliding Door with glass, Duct Door, LED bulb & its wire, TV cable wire may be considered genuine & adequate for the purpose of

Abhina lonly



INSURANCE SURVEYORS AND LOSS ASSESSORS PRIVATE LIMITED

Website: www.timelineisla.com

e-mail: fire@timelineisla.com, enginering@timelineisla.com, marine@timelineisla.com, misc@timelineisla.com

REF: ILGI0911FRM19-20

DATED: 27.11.2019

assessment as are consistent with observations noted during survey & photographs and rates comparable to market

b) Policy taken on RIV but repair/reinstatement invoices not provided thus 10% deduction suggested to a/c for the same

CONTENTS

- a) Quotation provided towards replacement of 8 Burkhas, 4 Pant Shirts, 2 sets School uniforms, General Undergarments & 2 Jackets claimed for Rs. 27,000.00 that were already disposed off prior our visit may be considered genuine & adequate for the purpose of assessment. Maximum depreciation @ 60 % suggested to arrive at Market value
- b) Cash Invoice provided towards purchase of Carpet for Rs. 24,570.00 is being considered after deducting 60% depreciation to arrive at MV
- c) Revolving Chair, Split AC, Laundry Bag, Clothes Rack claimed for Rs. 2500.00, 29,500.00, 700.00 & 1500.00 respectively but no purchase invoice provide thus 60% depreciation suggested
- a) Nominal Salvage value of Rs. 3000.00 suggested
- b) Excess @ 5% of the claim amount subject to min. of Rs. 25,000.00 is being deducted

The loss has been adjusted for Rs. 83,960.00

Survey & Loss Assessment report hereby issued without prejudice is subject to the terms & conditions of the policy; reserving our rights to amend unintended error, if any.

For TIMELINE Insurance Surveyors And Loss Assessors Private Limited

Enclosure:

- 1. Deputation Mail & Copy of Policy
- 2. Incident Report, Layout & Estimates/quotation
- 3. Copy of cancelled cheque, PAN, Aadhar, Electricity Bill, Certificate of registration & Sale deed
- 4. Area of flats
- 5. Photographs-20 & Professional Fee Bill

ANNEXURE-A

| | DESCRIPTION | UOM | QTY | | Rate | Amount | |
|------|--|------|---------|---------|-------|--|-----------|
| SN | | | Claimed | Allowed | Rate | Claimed | Allowed |
| Α | Balcony | | | | | | |
| 1 | Right Wall | sqft | 60 | 60 | 95 | 5700.00 | 5700.00 |
| 2 | Left Wall | sqft | 12 | 12 | 95 | 1140.00 | 1140.00 |
| 3 | Roof | sqft | 36 | 36 | 25 | 900.00 | 900.00 |
| 4 | Column | sqft | 48 | 48 | 95 | 4560.00 | 4560.00 |
| 5 | Tiles | sqft | 32 | 32 | 310 | 9920.00 | 9920.00 |
| 6 | Grill | sqft | 16 | 16 | 180 | 2880.00 | 2880.00 |
| 7 | Façade | sqft | 120 | 120 | 95 | 11400.00 | 11400.00 |
| В | Main Hall | | | | | | |
| 1 | Right wall | sqft | 110 | 110 | 20 | 2200.00 | 2200.00 |
| 2 | | sqft | 62 | 62 | 20 | 1240.00 | 1240.00 |
| 3 | Furniture/Cabinet | sqft | 120 | 120 | 15 | 1800.00 | 1800.00 |
| _ | Back wall | sqft | 120 | 120 | 20 | 2400.00 | 2400.00 |
| | Roof | sqft | 192 | 192 | 20 | 3840.00 | 3840.00 |
| | Wall Repair | sqft | 20 | 0 | 300 | 6000.00 | 0.00 |
| С | Sliding Door with Glass | nos. | 3 | 3 | 10667 | 32000.00 | 32000.00 |
| D | LED & wire | LS | 1 | 1 | 2000 | 2000.00 | 2000.00 |
| Е | Duct Door | nos. | 1 | 1 | 2500 | 2500.00 | 2500.00 |
| F | Policina de la California de la Californ | LS | 1 | 1 | 2000 | 2000.00 | 2000.00 |
| 207/ | Gross Loss Building | | | | | 92480.00 | 86480.00 |
| | Less: 10% for quotation | | | | | 1 | 8648.00 |
| | Loss Considered/Assessed Loss (A) | | | | | | 77832.00 |
| | CONTENTS | | | | | | |
| 1 | 8 Burkhas, 4 Pant Shirts, 2 sets School uniforms, General Undergarments & 2 Jackets | LS | 1 | 1 | 27000 | 27000.00 | 27000.00 |
| 2 | w and the second | nos. | 1 | 1 | 24570 | 24570.00 | 24570.00 |
| 3 | Revolving Chair | nos. | 1 | 1 | 2500 | 2500.00 | 2500.00 |
| | Split AC | nos. | 1 | 1 | 29500 | 29500.00 | 29500.00 |
| | Clothes Hanging Plastic Rack | nos. | 1 | 1 | 1500 | 1500.00 | 1500.00 |
| _ | Laundry Bag | nos. | 1 | 1 | 700 | 700.00 | 700.00 |
| | Gross Loss Contents | | | | | 85770.00 | 85770.00 |
| | Less: Depreciation @ 60% | | | | | | 51642.00 |
| | Market Value/Assessed Loss (B) | | | | | | 34128.00 |
| | Combined Assessed Loss for Building & Contents (A+B) | | | | | the life control of the li | 111960.00 |
| | Less: Salvage | | | | | | 3000.00 |
| _ | Net Assessed Loss | | | | | | 108960.00 |
| | Less: Excess | | | | | 24-140 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) | 25000.00 |
| | Net Adjusted Loss | | | 10100 | | | 83960.00 |

Abbin Ponday