

Part List

- 1. FITPIX
- 2. Motherboard



2





List of the Accessories

- 1. Bias cable
- 2. USB cable
- 3. USB memory stick
- 4. Switching adapter +5V



