

APEX INDUSTRIAL MAINTENANCE MANUAL

Asset ID: P-101 (Centrifugal Pump)

Procedure: In case of bearing overheat on P-101, isolate inlet valve V-202 immediately.

Safety Check: Verify electrical lock-out tag-out before opening housing.