













Add capacitors to I2C lines. Battery add resistors, diodes, capacitors for battery safety

Mount IR sensors vertically, need 3D print. Need 3.3V step up





TITLE: 2026-2027 micromouse sigma wiring	REV: 1.0
EasyEDA	Company: ratatouieee / Sheet: 1/1
	Date: 2025-11-05 Drawn By: carzav06