

```
% Assignment-4 Q-1
clear
% [ all units in GPa, mm, KN]
ele_X_coord = [0 200 200 0];
ele_Y_coord = [0 0 100 100];
ele_nodes = [1 2 3 4];
KE = stiffness(ele_X_coord,ele_Y_coord);
F = sparse(8,1); U = zeros(8,1);
% DEFINE LOADS AND SUPPORTS (HALF MBB-BEAM)
F(5) = 10/sqrt(2);
F(6) = 10/sqrt(2);
fixeddofs = [1 2 7 8];
alldofs
            = 1:8;
freedofs
            = setdiff(alldofs,fixeddofs);
% SOLVING
U(freedofs,:) = KE(freedofs,freedofs) \ F(freedofs,:);
U(fixeddofs,:)= 0;
X = [0,200;0,200];
Y = [0 \ 0;100 \ 100];
dx = [U(1) U(3); U(7) U(5)];
dy = [U(2) U(4); U(8) U(6)];
X_{mod} = X + 10*dx;
Y_{mod} = Y + 10*dy;
stress_vm = stress(ele_X_coord,ele_Y_coord,U);
figure(1)
contourf(X, Y,[stress_vm(1) stress_vm(2);stress_vm(3) stress_vm(4)],100,'edgecolor', 'none')
colorbar()
figure(2)
hold on
for i = 1:2
plot(X(i,:),Y(i,:),'k')
plot(X_mod(i,:),Y_mod(i,:),'b')
plot(X,Y,'k')
plot(X_mod,Y_mod,'b')
title('Mesh with & w/o Deflection(10x)')
hold off
function stress_vm = stress(X,Y,Q)
E = 120; % [GPa]
nu = 0.25;
D = (E/((1+nu)*(1-2*nu)))*[1-nu nu 0; nu 1-nu 0;0 0 0.5-nu];
coord = [X',Y'];
stress_temp = [];
for i = 1:2
for j = 1:2
eta = (2*i-3);
zeta = (2*j-3);
J = (1/4)*[eta-1 1-eta 1+eta -eta-1; zeta-1 -zeta-1 1+zeta 1-zeta]*coord;
H = (1/4)*[eta-1 1-eta 1+eta -eta-1; zeta-1 -zeta-1 1+zeta 1-zeta];
H = [H(1,1) \ 0 \ H(1,2) \ 0 \ H(1,3) \ 0 \ H(1,4) \ 0; \ 0 \ H(2,1) \ 0 \ H(2,2) \ 0 \ H(2,3) \ 0 \ H(2,4); \ H(2,1) \ H(2,1) \ H(2,2) \ H(1,2) \ H(2,3) \ H(1,3) \ H(2,4) \ H(1,4)];
stress_temp = [stress_temp D*H*Q]; % Sigma XX, Sigma YY, Sigma XY
end
end
stress_xx = stress_temp(1,:);
stress_yy = stress_temp(2,:);
stress_xy = stress_temp(3,:);
stress\_vm = sqrt((stress\_xx.^2 + stress\_yy.^2)*(1 + nu^2 - nu) + 3*stress\_xy.^2 - stress\_xx.*stress\_yy*(1 - 2*nu);
function K = stiffness(X,Y)
```

```
E = 120; % [in GPa]
nu = 0.25;
D = (E/((1+nu)*(1-2*nu)))*[1-nu nu 0; nu 1-nu 0; 0 0 0.5-nu];
coord = [X',Y'];
K = zeros(8,8);
for i = 1:2
for j = 1:2
eta = (2*i-3)/sqrt(3);
zeta = (2*j-3)/sqrt(3);
J = (1/4)*[eta-1 1-eta 1+eta -eta-1; zeta-1 -zeta-1 1+zeta 1-zeta]*coord;
H = (1/4)*[eta-1 1-eta 1+eta -eta-1; zeta-1 -zeta-1 1+zeta 1-zeta];
H = J\backslash H;
H = [H(1,1) \ 0 \ H(1,2) \ 0 \ H(1,3) \ 0 \ H(1,4) \ 0; \ 0 \ H(2,1) \ 0 \ H(2,2) \ 0 \ H(2,3) \ 0 \ H(2,4); \ H(2,1) \ H(2,1) \ H(2,2) \ H(1,2) \ H(2,3) \ H(1,3) \ H(2,4) \ H(1,4)];
K = K + det(J)*H'*D*H;
end
end
end
```





Published with MATLAB® R2021b