BestRun EV

After-Sales & Warranty Guide

Apex Series - Authorized Dealer Reference

1. Warranty Terms by Model

Component	Apex City	Apex Trail	Apex Pro
Frame & fork	2 years	2 years	3 years
Battery pack	1 yr / 300 cycles	2 yr / 500 cycles	3 yr / 1,000 cycles
Motor	1 year	1 year	2 years
Electronics & display	1 year	1 year	1 year
Drivetrain (chain, cassette)	Not covered	6 months	1 year
Suspension (fork/shock)	Not covered	1 yr (seals)	2 yr (seals + internals)
Brakes (pads, rotors)	Not covered	Not covered	Not covered
Tires & tubes	Not covered	Not covered	Not covered

Note: Battery warranty is the shorter of the time period or cycle count. Warranty is valid from the date of original retail purchase (end customer). Dealer stock held unsold is covered from the dealer invoice date.

2. Warranty Conditions

2.1 What the warranty covers

- Manufacturing defects in materials and workmanship
- Battery capacity falling below 70% of rated capacity within the warranty period (verified by BestRun EV Diagnostic Tool)
- Motor failure not caused by impact, submersion beyond IP rating, or unauthorised modification
- Electronic faults not caused by water ingress beyond IP rating, incorrect charging, or physical damage

2.2 What the warranty does NOT cover

- Normal wear items: brake pads, tires, tubes, chains, cables, grips, saddles
- Damage from accidents, impacts, or rider error
- Damage from use outside the stated IP rating
- Battery degradation from improper storage (e.g., stored fully discharged for >3 months)
- Modifications or repairs carried out by non-authorised technicians
- Cosmetic damage (scratches, paint chips) not affecting function
- Products with a removed or tampered serial number

3. Warranty Claims Process

Step 1: Dealer assessment

Inspect the unit and reproduce the fault. Log the fault via the dealer portal (Service > New Warranty Claim). Include: serial number, purchase date, fault description, and photos.

Step 2: BestRun EV approval

BestRun EV Warranty Team reviews and responds within 2 business days. Approval is required before any work begins. Unauthorized work will not be reimbursed.

Step 3: Repair or replacement

On approval: carry out the authorised repair using BestRun EV genuine parts. For total replacement, BestRun EV ships a replacement unit and arranges collection of the faulty unit.

Step 4: Labour reimbursement

Approved warranty labour is reimbursed at the current BestRun EV Warranty Labour Rate (EUR 75/hour Gold and Platinum dealers; EUR 65/hour Silver). Submit labour record via portal.

Step 5: Parts

Warranty replacement parts are shipped free of charge to the dealer. Non-warranty parts are ordered via the Parts Portal and invoiced at dealer price.

4. Common Issues & Troubleshooting

Apex City

Symptom	Likely Cause	Action
Motor cuts out at low speed	Throttle calibration drift	Recalibrate via BestRun EV app > Settings > Throttle Reset
Battery drains faster than expected	Cold weather or cell aging	Check SoH in app; if SoH <80%, raise warranty claim
Display shows error E03	BMS over-temperature	Allow battery to cool 20 min; charge in cooler environment
Rear brake rubbing	Pad wear or rotor alignment	Adjust or replace pads; not a warranty item

Apex Trail

Symptom	Likely Cause	Action
Drivetrain noise under load	Chain wear or derailleur adjustment	Check chain wear indicator; adjust derailleur limit screws
Motor assistance stutters at cadence	Cadence sensor magnet alignment	Inspect magnet on crank arm; re-align if >3 mm from sensor
Fork feels harsh on small bumps	Low air pressure in fork	Check and adjust fork pressure per RockShox chart for rider weight
Display shows error E07	Speed sensor fault	Check sensor cable connector at motor; re-seat if loose

Apex Pro

Symptom	Likely Cause	Action
Range significantly below expected	Cold weather, heavy terrain, or SoH de	Check SoH via Pro app; if SoH <80% within warranty, raise claim
Motor noise (grinding at high torque)	BRD-750 bearing wear	Do not continue riding; raise warranty claim - motor replacement require
Charging stops at <80%	BMS high-temperature protection	Charge in ambient <30 deg C; check for fan obstruction near motor
App shows 'BMS Update Required'	BMS firmware update pending	Connect to BestRun EV Pro app on Wi-Fi; run update (approx. 8 min)
Display error E12	LFP cell imbalance detected	Run full charge cycle to allow active balancing; if persists, raise claim

5. Service Schedule

Service	Apex City	Apex Trail	Apex Pro
Basic service (brakes, tyres, bolts)	1,000 km / 12 mo	1,500 km / 12 mo	2,000 km / 12 mo
Full service (drivetrain, suspension)	Not applicable	3,000 km / 24 mo	3,000 km / 24 mo
Battery capacity check	Every 12 mo	Every 12 mo	Every 12 mo
Motor inspection	2,000 km / 12 mo	3,000 km / 12 mo	5,000 km / 12 mo
BMS firmware check	Via app, as notified	Via app, as notified	Via app, as notified
Fork service (seal replacement)	Not applicable	100 h use or 24 mo	100 h use or 12 mo

6. Spare Parts Ordering

Genuine BestRun EV parts are ordered via the dealer portal at bestrun-ev.com/dealer/parts. Key parts for Apex Series:

Part	Part Number	Models	Lead Time
LFP Battery Pack (48V/25Ah)	BAT-PRO-LFP	Apex Pro	5-7 business days
NMC Battery Pack (48V/17.5Ah)	BAT-TRL-NMC	Apex Trail	5-7 business days
NMC Battery Pack (36V/14.5Ah)	BAT-CTY-NMC	Apex City	5-7 business days
BRD-750 Motor Unit	MOT-BRD750	Apex Pro	7-10 business days
Bafang M400 Motor Unit	MOT-BAF400	Apex Trail	5-7 business days

Apex Pro Fast Charger (8A)	CHR-8A-48V	Apex Pro	3-5 business days
Apex Trail/City Charger (4A)	CHR-4A-48V	Apex Trail, City	3-5 business days
Apex Pro Display (4.2")	DSP-PRO-42	Apex Pro	5-7 business days
Apex Pro Brake Set (Magura MT5e)	BRK-MT5E-203	Apex Pro	3-5 business days
Apex Trail Brake Set (Shimano)	BRK-SHM-180	Apex Trail	3-5 business days