

INFT-1205 – Data Communications & Networking II

Capstone Project

Ping Documentation

Institution: Durham College

By: Group 1

Suhaan Bhanwer, Anointing Iyawe, Hossein Abdolzahraei

Document Overview

This document serves as brief documentation on the pings. It includes pings from hosts to ISP, and host to host.

1. Ping – FL1 Host 2 – FL1 Host 1

This is the result of the ping from FL1 host 2 on the Customer Support VLAN to the FL1 host 1 on the IT VLAN. It tests inter-VLAN communication.

```
C:\Users\Owner>ping 10.160.0.11

Pinging 10.160.0.11 with 32 bytes of data:
Reply from 10.160.0.11: bytes=32 time=3ms TTL=127
Reply from 10.160.0.11: bytes=32 time=4ms TTL=127
Reply from 10.160.0.11: bytes=32 time=3ms TTL=127
Reply from 10.160.0.11: bytes=32 time=4ms TTL=127

Ping statistics for 10.160.0.11:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 3ms, Maximum = 4ms, Average = 3ms
```

2. Ping – FL1 Host 1 – FL2 Host 1

This is the result of the ping from FL1 host 1 on the IT VLAN to the FL2 host 1 on the HR VLAN. It tests inter-VLAN communication.

```
C:\Users\Owner>ping 10.160.1.11

Pinging 10.160.1.11 with 32 bytes of data:
Reply from 10.160.1.11: bytes=32 time=3ms TTL=127
Reply from 10.160.1.11: bytes=32 time=3ms TTL=127
Reply from 10.160.1.11: bytes=32 time=3ms TTL=127
Reply from 10.160.1.11: bytes=32 time=3ms TTL=127

Ping statistics for 10.160.1.11:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 3ms, Maximum = 3ms, Average = 3ms
```

Ping – FL1 Host 1 – FL2 Host 2

This is the result of the ping from FL1 host 1 on the IT VLAN to the FL2 host 2 on the Management VLAN. It tests inter-VLAN communication.

```
C:\Users\Owner>ping 10.160.1.203

Pinging 10.160.1.203 with 32 bytes of data:
Reply from 10.160.1.203: bytes=32 time=2ms TTL=127
Reply from 10.160.1.203: bytes=32 time=3ms TTL=127
Reply from 10.160.1.203: bytes=32 time=2ms TTL=127
Reply from 10.160.1.203: bytes=32 time=3ms TTL=127

Ping statistics for 10.160.1.203:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 2ms, Maximum = 3ms, Average = 2ms
```

Ping – FL1 Host 2 – FL2 Host 1

This is the result of the ping from FL1 host 2 on the Customer Support VLAN to the FL2 host 1 on the HR VLAN. It tests inter-VLAN communication.

```
C:\Users\Owner>ping 10.160.1.11

Pinging 10.160.1.11 with 32 bytes of data:
Reply from 10.160.1.11: bytes=32 time=1ms TTL=127
Reply from 10.160.1.11: bytes=32 time=2ms TTL=127
Reply from 10.160.1.11: bytes=32 time=1ms TTL=127
Reply from 10.160.1.11: bytes=32 time=1ms TTL=127

Ping statistics for 10.160.1.11:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 1ms, Maximum = 2ms, Average = 1ms
```

5. Ping – FL1 Host 2 – FL2 Host 2

This is the result of the ping from FL1 host 2 on the Customer Support VLAN to the FL2 host 2 on the Management VLAN. It tests inter-VLAN communication.

```
C:\Users\Owner>ping 10.160.1.203

Pinging 10.160.1.203 with 32 bytes of data:
Reply from 10.160.1.203: bytes=32 time=1ms TTL=127
Reply from 10.160.1.203: bytes=32 time=1ms TTL=127
Reply from 10.160.1.203: bytes=32 time=1ms TTL=127
Reply from 10.160.1.203: bytes=32 time=1ms TTL=127

Ping statistics for 10.160.1.203:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 1ms, Maximum = 1ms, Average = 1ms
```

6. Ping – FL2 Host 1 – FL2 host 2

This is the result of the ping from FL2 host 1 on the HR VLAN to FL2 host 2 on the Management VLAN. It tests inter-VLAN communication.

```
C:\Users\Owner>ping 10.160.1.203

Pinging 10.160.1.203 with 32 bytes of data:
Reply from 10.160.1.203: bytes=32 time=2ms TTL=127
Reply from 10.160.1.203: bytes=32 time=3ms TTL=127
Reply from 10.160.1.203: bytes=32 time=3ms TTL=127
Reply from 10.160.1.203: bytes=32 time=3ms TTL=127

Ping statistics for 10.160.1.203:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 2ms, Maximum = 3ms, Average = 2ms
```

7. Ping – FL1 Host 1 – RogersRouter

This is the result of the ping from FL1 host 1 on the IT VLAN to the RogersRouter.

```
C:\Users\iyawe>ping 101.1.1.2

Pinging 101.1.1.2 with 32 bytes of data:
Reply from 101.1.1.2: bytes=32 time=5ms TTL=254
Reply from 101.1.1.2: bytes=32 time=6ms TTL=254
Reply from 101.1.1.2: bytes=32 time=6ms TTL=254
Reply from 101.1.1.2: bytes=32 time=7ms TTL=254

Ping statistics for 101.1.1.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 5ms, Maximum = 7ms, Average = 6ms
```

8. Ping – FL1 Host 1 - BellRouter

This is the result of the ping from FL1 host 1 on the IT VLAN to the BellRouter.

```
C:\Users\iyawe>ping 101.1.2.2

Pinging 101.1.2.2 with 32 bytes of data:
Reply from 101.1.2.2: bytes=32 time=6ms TTL=254
Reply from 101.1.2.2: bytes=32 time=6ms TTL=254
Reply from 101.1.2.2: bytes=32 time=6ms TTL=254
Reply from 101.1.2.2: bytes=32 time=6ms TTL=254

Ping statistics for 101.1.2.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 6ms, Maximum = 6ms, Average = 6ms
```

9. Ping – FL1 Host 2 – RogersRouter

This is the result of the ping from FL1 host 2 on the Customer Support VLAN to the RogersRouter.

```
C:\Users\Owner>ping 101.1.1.2

Pinging 101.1.1.2 with 32 bytes of data:
Reply from 101.1.1.2: bytes=32 time=21ms TTL=254
Reply from 101.1.1.2: bytes=32 time=16ms TTL=254
Reply from 101.1.1.2: bytes=32 time=9ms TTL=254
Reply from 101.1.1.2: bytes=32 time=8ms TTL=254

Ping statistics for 101.1.1.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 8ms, Maximum = 21ms, Average = 13ms
```

10. Ping – FL1 Host 2 – BellRouter

This is the result of the ping from FL1 host 2 on the Customer Support VLAN to the BellRouter.

```
C:\Users\Owner>ping 101.1.2.2

Pinging 101.1.2.2 with 32 bytes of data:
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254

Ping statistics for 101.1.2.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 7ms, Maximum = 7ms, Average = 7ms
```

11. Ping – FL2 Host 1 – RogersRouter

This is the result of the ping from FL2 host 1 on the HR VLAN to the RogersRouter.

```
C:\Users\Owner>ping 101.1.1.2

Pinging 101.1.1.2 with 32 bytes of data:
Reply from 101.1.1.2: bytes=32 time=5ms TTL=254
Reply from 101.1.1.2: bytes=32 time=5ms TTL=254
Reply from 101.1.1.2: bytes=32 time=7ms TTL=254
Reply from 101.1.1.2: bytes=32 time=18ms TTL=254

Ping statistics for 101.1.1.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 5ms, Maximum = 18ms, Average = 8ms
```

12. Ping – FL2 Host 1 – BellRouter

This is the result of the ping from FL2 host 1 on the HR VLAN to the BellRouter.

```
C:\Users\Owner>ping 101.1.2.2

Pinging 101.1.2.2 with 32 bytes of data:
Reply from 101.1.2.2: bytes=32 time=6ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254

Ping statistics for 101.1.2.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 6ms, Maximum = 7ms, Average = 6ms
```

13. Ping – FL2 Host 2 – RogersRouter

This is the result of the ping from FL2 host 2 on the Management VLAN to the RogersRouter.

```
C:\Users\Owner>ping 101.1.1.2

Pinging 101.1.1.2 with 32 bytes of data:
Reply from 101.1.1.2: bytes=32 time=44ms TTL=254
Reply from 101.1.1.2: bytes=32 time=7ms TTL=254
Reply from 101.1.1.2: bytes=32 time=11ms TTL=254
Reply from 101.1.1.2: bytes=32 time=8ms TTL=254

Ping statistics for 101.1.1.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 7ms, Maximum = 44ms, Average = 17ms
```

14. Ping – FL2 Host 2 – BellRouter

This is the result of the ping from FL2 host 2 on the Management VLAN to the BellRouter.

```
C:\Users\Owner>ping 101.1.2.2

Pinging 101.1.2.2 with 32 bytes of data:
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=10ms TTL=254
Reply from 101.1.2.2: bytes=32 time=7ms TTL=254
Reply from 101.1.2.2: bytes=32 time=8ms TTL=254

Ping statistics for 101.1.2.2:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 7ms, Maximum = 10ms, Average = 8ms
```