Fast-Drone-250 on Arm.md 2023/7/16

Fast-Drone-250 on Arm

OpenCV报错

- 报错信息: Project 'cv_bridge' specifies 'usr/include/opency' as an include dir, which is not found
- 报错原因:由于Nvidia jetpack将OpenCV文件夹命名为OpenCV4,导致编译的时候找不到
- 找到报错文件,即cv_bridgeconfig.cmake,搜索"/usr/include/opencv",并改为"/usr/include/opencv4"

realsense报错

• 报错原因: realsense在x86平台和在arm平台上安装方法不一致,arm平台的安装方式如下:

1.编译安装realsense

```
#编译realsense
sudo apt install -y cmake git
sudo apt-get install -y libusb-1.0-0-dev pkg-config
sudo apt-get install -y libglfw3-dev libgl1-mesa-dev libglu1-mesa-dev
sudo apt-get install openssl libssl-dev

cd ~/librealsense
mkdir build
cd build
rm -rf *
cmake ../ -DFORCE_RSUSB_BACKEND=ON -DBUILD_PYTHON_BINDINGS:bool=true -
DPYTHON_EXECUTABLE=/usr/bin/python3
make -j6
sudo make install
```

• 加入环境变量

export

PYTHONPATH=\$PYTHONPATH:/usr/local/lib:/usr/local/lib/python3.6/pyrealsense2

2.安装ROS+realsense环境

```
sudo apt-get install ros-melodic-realsense2-camera sudo apt-get install ros-melodic-realsense2-description
```