Due to high demand and worldwide supply chain issues, we are experiencing longer than normal delivery time X frames for many Tormach machines and accessories.

## **PCNC 770 Tech Specs**

+	Key Dimensions/Weight
_	Power
•	Power Requirements: 115 VAC 50/60 Hz single phase (primary). 20A breaker recommended
+	Iron
+	Spindle
+	Motion
+	Control
+	Maintenance Capacities

+ Controller