


# HCRO Site Update

## Overview:

- Antennas
- Compute infrastructure
- Full buildout and developments
- Other updates



# Antennas

- Next maintenance: 2C, 2A
- Plan to retrofit of 2A feed base




# Compute infrastructure

- Paul's update
- HVAC maintenance: outside fan RPM modified
- Spare power supplies & power modules arrived




## RAID storage:

- Data “y” copy is done
- RAID: 2x16 disks replaced with 3x11 disks
- Initialization: 1 week
- Primary volume will then be increased



- Hat Creek house fiber splicing



- Fiber to Hat Creek house damaged



- Fiber to Hat Creek house damaged




Main suspect arrested:



# Other updates


- CHIME & NRDZ fiber cables installed



# Terminator observation console

- Replace workspaces in a single window
- Simplify the process for new observers
- Atastatus, pipeline monitoring, etc... separated
- Coming soon, will need your feedback!





- NRDZ UPS at CHIME location installed



- LuSEE tests

