General Update

- SPR
 - Removal of legacy system
 - Planning of tone measurement of RFCBs
 - Planning of power measurement after RF 4-way splitter
 - Investigate IF ripples
- Observing Campaign
 - SETI-nodes OS INSTALLED
 - Can't boot from U.2 drive NVME adapter arrived
 - NVME buffer ready (74.14 Gbps)
 - Storage drive raid build in progress (16 disks)
 - Ldap setup DONE
 - Shared mounts DONE
 - Ansible setup DONE
- General update
 - LNF 6 spare LNAs ORDER PLACED
 - Station Clock INSTALLED
 - Components for RFSoC enclosure ordered ARRIVED
 - Missing optocoupler PCB design
 - IF gain Control

Antonio Feed update

- Feeds (003, 004, 008, 010, 011, 014)
 - MINEX:
 - 2 feeds DONE
 - two more will follow next week
- Trip to Minex on the sometime yesterday


Feed List		Feed Revision Overview							
Number	Installed Ant.	Tip-Link: R03	Temp S. Isolation	New Harness	Bellow Removed	Cryo Tuned	Firmware 5.4	Gold-Plated	Preconditioned Coax
<u>5C4-002</u>	Feed Lab								
<u>5C4-003</u>	Feed Lab (5B)	Х	Х	Х	Х		Х	Х	х
5C4-004	Feed Lab (2E)	In Progress	In Progress	In Progress	In Progress			Х	In Progress
<u>5C4-005</u>	2A								
<u>5C4-006</u>	4J	Х	Х	Х	Х	Х	Х	X	X
5C4-007	Feed Lab								
<u>5C4-008</u>	Feed Lab (1G)	In Progress	Х	Х	Х	Х	Х	X	In Progress
	Minex								
<u>5C4-010</u>	Feed Lab (2B)	In Progress	Х	Х	X			X	Needs X-Pol LNA replacement
<u>5C4-011</u>	Feed Lab (3L)	In Progress	Х	X	X	Х	Х	X	In Progress
<u>5C4-012</u>	1K	X	X	X	X	Х	X	X	NA
<u>5C4-013</u>	Feed Lab (1H)	Х	Х	Х	Х	Х	Х	X	X
<u>5C4-014</u>	Feed Lab (2J)	In Progress	Х	X	X			X	In Progress
	Minex								
	Minex								
	Minex								
5C4-018	2H	Х	X	Х	Х	Х	Х	X	NA
<u>5C4-019</u>	1C		X	X	Х	X			
<u>5C4-020</u>	3C	Х	Х	Х	X	Х	Х	X	X

Next round of retrofits




Parts missing for final build out

- Feed Base
 - 1 Glass Dome (quote for 3)
 - 6 diaphragm pumps
 - 15+ in need of service
 - New one \$2k
 - Pfeiffer service \$700 each
 - Minex service \$200 each
- 2 new build pyramids (20 total)
- 6 SS coax cables from LNA to base
- 3 48V power supplies to be installed at antennas (collected from Minex)
- 4 LNAs (6 ordered)
- UT-034-95 coax cable ordered (60ft)



SPR removal of old hardware!





SPR removal of old hardware!



