General Update

- SPR
 - AC replacement INITIATED
 - IF wiring DONE
 - Need more fixed attenuators for course power leveling
- Other
 - Antenna control box retrofit
 - 2x RFSoC boards this week
 - Weather station failed, replacement ordered
 - REU field trip to HCRO (Sarah will take over organization)
 - 27 of June to 3 of July
 - Agenda in prep.
 - Berkeley House:
 - Quotes for: roof, asbestos removal, windows, electric wiring, new kitchen
 - 2nd Electrician looked at the house
 - Can replace wiring without removing walls
- CHIME:
 - Agreement draft send to Chime
 - Need to get quotes for geotechnical survey
 - Construction permit minor modification
 - List of available equipment at HCRO

Antonio Feed


- Wael will take Pyramid 020 to Minex (Friday)
- Feed 015 currently under vacuum test
- Feed 018 cooling down, waiting for HC test
- Diaphragm pumps not available currently
- 3C showed failure on Monday
- 2B needed azimuth motor replaced DONE
- 4G elevation drive replaced DONE

- Antonio Feed Overview
 - 18 Antennas fully operational
 - 14 / 19 Antonio Feeds

Feed List		Feed Revision Overview							
Number	Installed Ant.	Tip-Link: R03	Temp S. Isolation	New Harness	Bellow Removed	Cryo Tuned	Firmware 5.4	Gold-Plated	Preconditioned Coax
5C4-001	Feed Lab		In Progress	In Progress	In Progress		In Progress		
5C4-002	2H	Х	Х	Х	Х	Х	Х	Х	X
5C4-003	Feed Lab	In Progress	Х	Х	Х	Х	Х	Х	X
5C4-004	2B	Х	Х	Х	Х	Х	Х	Х	X
5C4-005	2A	NA	NA	NA	NA	NA	NA	NA	NA
<u>5C4-006</u>	4J	X	Х	X	Х	X	Х	Х	X
5C4-007	3L	X	Х	Х	Х	X	Х	Х	X
<u>5C4-008</u>	2M	X	Х	Х	Х	X	Х	Х	X
<u>5C4-009</u>	Feed Lab	In Progress	Х	Х	Х	Х	Х	Х	Х
<u>5C4-010</u>	2C	X	X	Х	Х	X	Х	Х	X
<u>5C4-011</u>	2J	X	Х	Х	Х	X	Х	Х	X
<u>5C4-012</u>	1K	X	Х	Х	Х	Х	Х	Х	NA
<u>5C4-013</u>	1H	X	X	Х	Х	X	Х	Х	X
<u>5C4-014</u>	2E	X	Х	Х	Х	X	Х	Х	X
<u>5C4-015</u>	Feed Lab	Х	Х	Х	Х	Х	Х	Х	X
5C4-016	5B	Х	Х	Х	Х	Х	Х	Х	X
5C4-017	3D	Х	Х	Х	Х	Х	Х	Х	X
5C4-018	3C	Х	Х	Х	Х	Х	Х	Х	NA
<u>5C4-019</u>	1C	NA	Х	Х	Х	Х	NA	NA	NA
<u>5C4-020</u>	Feed Lab	X	Х	Х	Х	X	Х	Х	Х

Feed 020:

- Broken tip link
- Cryo-cooler was not well tuned
- Coax cable is fine
















2B Azimuth gearbox:

• Gearbox fine, need new gear for belt

4G Elevation drive:

Needs new bearings





SETI branding:

