
## 2k - Pointing calibration





## Measured offsets

Scatter in pointing offsets


Obvious issues with 1k

Investigation underway









## Timeline

- 8-bit mode with all antennas (no delay engine) October 15th
- Network ingest test + write-to-disk tests October 22nd
- Interface with GPU-beamforming library October 31st.
- 8-bit mode + delay firmware November 7th
- Calibration runs, phase stability, beam forming efficiency <u>November 22nd</u>
- Real-time beam forming operations <u>December 15th</u>