

Required Signage Report

Every sign this property is required to carry — fire marshal, accessibility, pool, municipal and Texas statutory — with the code section behind each one, and what the permit set currently gets wrong.

WHAT THIS REPORT COVERS

- **Fire marshal** — egress marking, stair ID, FDC and riser, barrier stenciling, hazmat
- **Accessibility** — 2010 ADA and 2012 Texas Accessibility Standards, with the TDLR inspection path
- **Pool and spa** — 25 TAC Ch. 265 Subch. L, verbatim sign text and depth-marker tile specs
- **City of Eagle Pass** — sign ordinance, adopted codes, fire lane spec, permits
- **Texas statutory notices** — trafficking, innkeeper, food, labor, elevator and boiler
- **Brand and project record** — Hilton scope, vendors, and the TDLR filing

9 sections · 147 cited sources · every requirement traced to a code section

PROJECT

Home2 Suites by Hilton

LOCATION

**3386 E. Main Street
Eagle Pass, TX 78852**

COUNTY

Maverick

KEYS

115

TDLR PROJECT

TABS2024001033

REPORT DATE

20 August 2026

Contents

Superscript numbers throughout the report are citations; every source resolves in the References appendix.

1. Project record and findings	2
2. Fire marshal signage	7
3. ADA and Texas Accessibility Standards	15
4. G401 delta: California code vs Texas	23
5. Pool and spa signage	30
6. Texas statutory posted notices	38
7. City of Eagle Pass	45
8. Brand standards and project record	52
9. Sign schedule by space	59
Appendix — References (147 sources)	63

SECTION 1

Project record and findings

Source file: research/signage/PROJECT-FINDINGS.md

Compiled 2026-08-20 from `data/project.sqlite` (238-sheet index, 66 spaces, 115 keys, 1,606 items, 45 conflicts, 51 placeholders) — the same spine `room_map.md` verified 115/115 by blind second extraction. Nothing in this file is inferred from a code book; it is what the project's own documents state. Requirements research is in the sibling files.

1. The set already contains a signage sheet. Nobody has read it.

Sheet	Title as indexed	Rev	Date
G401	Accessibility — signage standards	—	06/09/23
G400	Accessibility — public-space mounting heights, pool lift, laundry, lockers, fountains	—	06/09/23
G402	Accessibility for Guestrooms — vanity/shower/tub details, grab-bar layouts, blocking, TA accessory schedule	—	06/09/23
G600	First Floor Accessibility Plan — clearances, door size & closer-force notes	—	06/09/23
G100	Building Code Analysis — Type V-A, NFPA 13R, R-1/A-2/B, 48'-1 1/4" / 4 stories	—	06/09/23
G100.2	Code Analysis — accessible units (115 / 7 accessible / 12 hearing), plumbing-fixture counts	—	06/09/23
G200	Life Safety — First Floor Plan (308 occupants)	4	08/09/24
G201	Life Safety — Typical Floor Plan (83 occupants/floor)	4	08/09/24
G001	Project Information — site/zoning/area/parking matrices, codes, deferred submittals	—	06/09/23

G401 is the project's own signage standard and it has never been extracted into this repo — only its title is indexed. Same for G400, G402, G600 and the parking matrix on G001. Read G401 before buying a single sign; it is the sheet the plan reviewer will hold the installation against.

G200/G201 are **rev 4 (08/09/24)** — the only G-sheets that were ever revised, and the newest life-safety information in the set. Exit-sign and egress-path locations come off those two sheets, not off the 06/09/23 originals.

2. G401 is drawn to CALIFORNIA code, on a Texas job

`conflicts` table, **A10** — "Accessibility code basis — out-of-state codes on a Texas project", status **OPEN**, verbatim:

G400/G401 cite California CBC 11B. G001's Code Summary cites NO accessibility standard at all — no TAS, no ANSI A117.1, no ADA. G003 Franchise Note 13 cites CBC 11B-404.2.11. G002 General Note 7 requires firestopping to the NCBC (North Carolina). All three are on the permit set.

The sheet that tells the contractor how to build the signage cites the **California** Building Code. Texas commercial construction over the registration threshold is reviewed and inspected against the **2012 Texas Accessibility Standards** by a TDLR-registered Accessibility Specialist. A RAS inspects to TAS. Building G401 as drawn is building to the wrong state's standard,

and the parking signage is where California and Texas diverge hardest — Texas has a statutory sign wording (fine amount + towing warning) that appears nowhere in the California code. Delta analysis in the sibling file.

This is prototype/boilerplate carryover, and it is **not isolated**: the finish schedule carries **PT-08 "Paint at INDOOR Pool Walls & Ceiling Inset"** (FLAGGED) on a pool that AS104 titles *Enlarged Outdoor Pool & Patio Plan*. Same failure mode, different discipline. Treat every G-sheet boilerplate citation as suspect until checked.

3. Nobody is contractually holding the signage scope

conflicts table, **B5.4 — "General — room-signage scope seam", status OPEN**, verbatim:

G002 General Note 9: 'ROOM IDENTIFICATION AND INTERIOR SIGNAGE BY OWNER'. But G003 lists (n) Interior Signage Review and (o) guest room numbering as GC-provided, and G003.2 Exhibit C Division 10 includes Signage. Settle who buys 115 room-number plaques and the ADA signage package before TCO.

Three documents on the same permit set assign the interior signage package three different ways. At 115 room-number plaques plus ~230 other code-driven signs (§6), this is a real number, and it is unowned. **Settle it before TCO, not at TCO.**

4. The drawings point at a "SIGNAGE PACKAGE" that is not in the set

A902 (Serving 009) prints **"GRAPHIC (SEE SIGNAGE PACKAGE)"** at seven positions on elevation 13 — HIGH reliability, trade GC. The signage package it refers to is in no indexed sheet and no Drive folder in this context set.

Blocking for signage is, however, already committed in the framing — it has to be in the wall before drywall:

Space	Blocking called for	Sheet	Reliability
Lobby 003	18" high blocking at 91" AFF for a blade sign at end of wall	A700 keyed note 40	HIGH
Home2 Market 005	48" × 16" blocking for signage, CENTERED — "must be in the stud wall before drywall"	A903	HIGH
Home2 Market 005	(same element) 48" × 18" blocking for signage, centered	ID-4.5	HIGH
Serving 009	Blocking for signage — no dimension given	A902	HIGH

⚠ A903 says 48"×16", ID-4.5 says 48"×18" for the same Market brand-signage blocking. Two inches, two sheets, and the blocking is buried once the wall closes. Resolve before the Market wall is rocked.

Also already committed: **Fitness Room 023 item 812 "RULES SIGN"** (A510.3 furnishing list, HIGH, owner-furnished) and **ZONE-B TL-12 "Depth marker tile"** (ID-1.8, FLAGGED) — the pool depth markers are specified as *tile*, not applied signage, which makes them a TILE-trade item on the critical path, not a sign-vendor item.

5. Three pool rooms have doors but no room record

A600 schedules doors for **034 Pool Storage 2**, **035 Pool Equipment**, and **036 Pool Storage 1** (HM in galvanized HM frames, hardware set #14, HIGH). None of the three appears in the spaces table — the space spine runs 001–033 and then jumps to the circulation numbers. **002 and 026 are likewise absent.**

035 Pool Equipment is the pool chemical room. That is the single room a fire marshal will most reliably ask about — NFPA 704 placard, chemical identification, restricted access — and it currently has no space record, no interior finish source ("Pool building 034 / 035 / 036 INTERIOR FINISHES — NO SOURCE", FLAGGED) and no signage line anywhere. It is carried in `sign-schedule.json` off the door schedule and flagged as such.

6. What the building actually needs, counted

Counted off the verified spine — 69 spaces (66 in the `spaces` table + the 3 pool-building rooms) and 115 keys. Quantities are counts, not estimates.

Sign family	Qty	Basis
Guest room number plaque, tactile + Braille	115	one per key
Guest room emergency evacuation map	115	one per key, inside entry door
Room identification, tactile (public + BOH + pool building)	55	by space class
"Employees Only" / restricted access	35	BOH + pool building
Stair identification sign (inside enclosure, each landing)	8	2 stairs × 4 floors
Stair door tactile "EXIT"	8	2 stairs × 4 floors
Stair floor-level designation	8	2 stairs × 4 floors
Elevator hoistway floor designation (both jambs)	16	2 cabs × 4 floors × 2 jambs
Elevator lobby fire-service sign	4	lobbies 137/237/337/437
Public restroom (door symbol + wall tactile)	6	019 WOMENS · 020 MEN'S · 027 Unisex
Occupant-load posting	5	006 · 009 · 018 · 023 · ZONE-B
Electrical room ID + arc-flash	4 + 4	033 · 219 · 319 · 419
Communication-features room identification	12 or 10	disputed — see below

 **The hearing-accessible count does not reconcile.** `conflicts` **A11**: A100's Guestroom Matrix HI rows sum to **12**, G001's sum to **10**, and G100.2 states **12**. Only 8 are physically located (209, 213, 216, 218 on A101; 309, 313, 316, 318 on A102); **floors 1 and 4 have never been scanned for the crossed-ear symbol**. The repo's standing instruction (`room_map.md` , `PH-GU-002`) is: *do not order 12 visual-alarm / shaker / doorbell kits until floors 1 and 4 are scanned and the count is reconciled against a single matrix*. The same caution applies to any signage that identifies those rooms.

A11 is decidable on the count, and the answer is 12. 115 keys lands in the "101 to 150" row of both ADA scoping tables (2010 ADA Standards for Accessible Design, verified against two independent renderings of the published tables):

Table	Row for 101–150 rooms	Requires
224.2 Guest Rooms with Mobility Features	5 without roll-in / 2 with roll-in / 7 total	7 mobility keys
224.4 Guest Rooms with Communication Features	12	12 communication-features keys

The design provides exactly **7** mobility keys — 118, 217, 238, 317, 338, 417, 438 — which matches 224.2 on the nose, and the 5-tub/2-roll-in split G100.2 states is exactly the table's split. So the architect scoped the counts off the right tables even though G401 cites the wrong state's standard.

On the hearing count the two matrices are **not equally valid**: 224.4 sets the minimum at **12**, so A100/G100.2's 12 meets it exactly and **G001's 10 would be two rooms short of the federal minimum**. The count question is therefore closed — it is 12 — and G001's matrix is simply wrong on that row. What is still genuinely open is *which* rooms: only 8 of the 12 are located (209, 213, 216, 218, 309, 313, 316, 318), and floors 1 and 4 have never been scanned. Scan them; do not re-litigate the number.

⚠ This does **not** unblock ordering. PH-GU-002 's hold stands, because the hold is about *which* keys get the kits, not how many. Sources: [Table 224.2](#)¹ · [224.2 + 224.4](#)²

7. Fire-protection documents the set does not contain

placeholders **PH-SP-019**, verbatim:

Fire Sprinkler and Fire Alarm devices in public and amenity spaces — Neither category can be populated from A5xx, A7xx or A9xx. Only two fire-protection facts exist in the whole group: recessed extinguisher cabinets and AS104 note 37.
The FP set is not indexed at all in this context set. → request and index the FP series.

So the fire marshal's signage scope cannot be closed from this repo alone. What is recorded: **fire extinguishers in fully recessed cabinets** in the public spaces (A510.1 keyed note 22 / A510.4 general note B / A700 keyed note 19, HIGH), and emergency exit lights recorded at only two spaces (Food Prep 007 via A513, Unisex 027 via A521) — which is coverage of the *index*, not of the building. Exit-sign locations live on **G200/G201 rev 4** and the **E200–E203** lighting plans.

Fire alarm is a **vendor performance design** (conflicts B1.9): device layout was deferred to the FA-0...FA-3 submittal under NFPA 72, which now supplies the bill.

8. Two code-basis facts to carry into any fire marshal conversation

Sprinkler standard is contested three ways (conflicts B5.3, OPEN): G002 General Building Note 8 says NFPA 13 flat; G100 and project.md say the basis of design is **NFPA 13R**; the stamped shop drawing — top of the precedence chain, and **stamped by the City of Eagle Pass FD** — designs to NFPA 13. Under precedence the installed system is NFPA 13.

⚠ **The edition recorded for that stamped shop drawing does not exist.** room_type_packages.md records it as "*NFPA 13 (2021) + NFPA 24 (2021)*". NFPA revises on a three-year cycle: **NFPA 13 editions are 2016, 2019, 2022 and 2025 — there is no 2021 edition**, and the same is true of NFPA 24. So "2021" is either the shop drawing's own issue date misread as an edition, or a transcription error, or the drawing genuinely cites a non-existent edition. Since this is the document the AHJ stamped, **confirm what the shop drawing actually cites before quoting an edition to the fire marshal.**

The energy code dates the permit cycle. G300 is a COMcheck certificate against the **2018 IECC**, Climate Zone 2b. That is real evidence the design was permitted on the **2018 I-code family**, which would put the fire code at **IFC 2018** — but it is inference from a sibling code, not a statement of the adopted fire code. G001's Code Summary is where the adopted editions are actually printed, and G001 has not been extracted. **Confirm the adopted IFC/IBC edition with the City before ordering code-dimensioned signs** (stair ID lettering sizes and exit-sign letter heights differ between editions).

9. Do these five things first

1. **Pull G401, G400, G402, G600 and G001** out of the permit set and read them. G401 is the signage standard; G001 carries the adopted-code summary and the parking matrix that sets the accessible-parking sign count.
2. **Raise conflict A10 as an RFI to MWT** — G400/G401 cite California CBC 11B on a Texas project. Ask for the sheets to be reissued to 2012 TAS.
3. **Settle conflict B5.4** — who buys the interior signage package: owner (G002 note 9), GC (G003 n/o), or Division 10 (G003.2 Exhibit C).
4. **Get the "SIGNAGE PACKAGE"** that A902 refers to, and resolve the Market blocking dimension (48"×16" per A903 vs 48"×18" per ID-4.5) **before that wall is rocked**.
5. **Request and index the FP series**, and confirm what the Eagle Pass FD–stamped sprinkler shop drawing actually cites for NFPA 13/24 editions.

SECTION 2

Fire marshal signage

Source file: research/signage/FIRE-MARSHAL-SIGNAGE.md

Home2 Suites by Hilton · Eagle Pass, TX · IBC Group R-1 · 4 stories · sprinklered · 2 exit stairs · 2 elevators · breakfast/food prep · guest laundry · outdoor pool. Researched 2026-08-20.

1. The adopted code is settled: 2018 IFC

Verified by extracting the City's own Fire Marshal document. Verbatim:

"Building construction in the City of Eagle Pass shall meet the requirements of the 2018 International Fire Code, local amendments, as well as all applicable NFPA Standards. All final system testing, and inspections will be witnessed by the City of Eagle Pass Fire Marshal's Office."

The City's commercial and residential permit applications add the rest of the family: **2018 IBC · 2018 IRC · 2018 IFC · 2017 NEC · 2018 IMC · 2018 IPC · 2018 IEBC · 2018 IECC · and the 2012 Texas Accessibility Standards.**

Two things this settles for the repo:

- 1. **It corroborates the inference from G300.** The COMcheck certificate on the permit set is against the **2018 IECC** — the same cycle. PROJECT-FINDINGS.md §8 flagged that as inference from a sibling code; it is now confirmed from the City directly.
- 2. **The City names the 2012 TAS by name.** That is the standard G401 does *not* cite — it cites California CBC 11B (conflicts A10). The City's own permit application names the standard the sheet should have been drawn to. See CBC-vs-TAS-DELTA.md.

! The City's own checklist contains a stale line. Item 4 reads "An automatic system shall be installed throughout buildings in accordance with the international fire code **2012** edition" while items 6, 9, 16, 17 and the header all say **2018**. Treat 2018 as governing and don't let anyone cite item 4 as authority for a 2012 provision.

! H2SEP is a "mid-rise" in the City's framing. Checklist item 23: "See mid-rise building construction section if residential occupancy that is **three or more stories** in height but is not classified as a high-rise." At 4 stories R-1 that is this building. **Request the mid-rise section — we do not have it.**

Eagle Pass Fire Marshal's Office

Fire Marshal	Eleazar Cuevas — ecuevas@eaglepasstx.gov
Phone	(830) 773-1915
Address	32 Foster Maldonado Blvd., Eagle Pass, TX 78852
Plan review	Up to 10 working days ; approved plans + permit stay on the job site
Local extinguisher rule	"A minimum of one 2A-10BC fire extinguisher per 3000 sq.ft. With a maximum travel distance of 75 ft. Indicate the location and size of all fire extinguishers."

Local address rule	"Address must be legible from the street or fire lane."
Local rated-wall rule	2-hr designation "clearly indicated" on plans with the UL listing number

This is also the office that **stamped the sprinkler shop drawing** carrying the phantom "NFPA 13 (2021)" edition (PROJECT-FINDINGS.md §8). Same office, same submittal chain.

2. Means of egress marking

#	Sign	Where	Requirement	Citation
1	EXIT sign	Every exit and exit access door. Placed so any point in an exit access corridor is within 100 ft (or the listed viewing distance, whichever is less) of the nearest visible sign	"EXIT", illuminated at all times	IFC 1013.1, 1013.3
2	Directional EXIT	Wherever the exit or path of travel is not immediately visible — corridor intersections, elevator lobbies, dead-end heads	"EXIT" + chevron. <i>"the direction of the chevron directional indicator cannot be readily changed"</i>	IFC 1013.1, 1013.6.1
3	★ FLOOR-LEVEL EXIT SIGNS — R-1 specific	"...in all areas serving guestrooms in Group R-1 occupancies." Every guest corridor (121/221/321/421), at each exit and stair door	Bottom of sign 10 in. min – 18 in. max above the floor. Flush to door or wall; if wall-mounted, edge within 4 in. of the door frame on the latch side. Internally illuminated per UL 924	IFC 1013.2
4	Externally illuminated sign lettering	All external signs	Letters ≥6 in. high , principal strokes ≥¼ in. wide , letters ≥2 in. wide (except "I"), letter spacing ≥¾ in. ; face intensity ≥5 foot-candles	IFC 1013.6.1, 1013.6.2
5	Emergency power	All exit signs	90 minutes minimum on loss of primary power	IFC 1013.6.3
6	★ Tactile + Braille "EXIT"	<i>"adjacent to each door to... an exit stairway or ramp, an exit passageway and the exit discharge"</i> → every stair door on every floor + the discharge doors	"EXIT" in visual characters, raised characters and Braille per ICC A117.1. Illumination not required	IFC 1013.4
7	★★ STAIRWAY IDENTIFICATION SIGN	Inside each stair, at every floor landing, 5 ft above the landing , readable with doors open and closed. Required — 4 stories is "more than three"	Must designate: floor level · terminus of top and bottom · stairway identification · story of, and direction to, the exit discharge · availability of roof access for the fire department	IFC 1023.9
8	Stair ID sign construction	Same	Sign min 18 in. × 12 in. · stairway ID letters ≥1½ in. · floor level number ≥5 in. high, in the center of the sign · all other lettering ≥1 in. · non-glare , contrasting	IFC 1023.9.1
9	Floor-level tactile sign at stairs	Inside the stair, adjacent to the door leading back into the corridor , each landing	Floor level in visual characters, raised characters and Braille per ICC A117.1	IFC 1023.9
10	"Elevator Lobby" sign	Only where a stair landing has 2+ doors to the floor and one gives direct access to an enclosed elevator lobby	"Elevator Lobby", ≥1 in. letters, non-glare contrasting	IFC 1023.10

#	Sign	Where	Requirement	Citation
1 1	Occupant load posted	<i>"Every room or space that is an assembly occupancy" — near the main exit or exit access doorway. For H2SEP: Breakfast 006, Servery 009, Meeting Room 018, Fitness 023, pool — whichever the FMO classifies as assembly</i>	<i>"of an approved legible permanent design". No lettering size in the code — get the format approved</i>	IFC 1004.9
1 2	Delayed egress sign	On the door, above and within 12 in. of the exit hardware	"PUSH UNTIL ALARM SOUNDS. DOOR CAN BE OPENED IN 15 [30] SECONDS." (or "PULL..." where the door swings opposite egress)	IFC 1010.1.9.8.1 — only if delayed egress locks are used
1 3	"PUSH TO EXIT"	At the manual unlocking device, 40–48 in. AFF, within 5 ft of the secured doors	"PUSH TO EXIT"	IFC 1010.1.9.9 — only if sensor-release locks are used
1 4	Two-way communication instruction sign	At the elevator landing on each accessible floor above the level of exit discharge — floors 2, 3, 4	Directions for use, instructions for summoning assistance, and written identification of the location	IBC 1009.8.2

 **Item 3 is the one most often missed and the biggest quantity surprise.** Low-level exit signs are an **R-1-specific** requirement — a hotel-only rule that doesn't appear on most commercial jobs. They land in all four guest corridors at every exit and stair door, mounted at ankle height.

Not required inside guest rooms: *"Exit signs are not required in... individual sleeping units or dwelling units in Group R-1"* (IFC 1013.1 Exc. 3).

3. Site and fire service features

#	Sign	Requirement	Citation
1 5	Premises address numbers	Visible from the street fronting the property. Arabic numerals or letters — numbers shall not be spelled out. Characters ≥4 in. high with ≥½ in. stroke, contrasting with background. Where the building can't be seen from the public way, a monument/pole sign is required	IFC 505.1 + City checklist item 15
1 6	NO PARKING — FIRE LANE	<i>"approved signs or other approved notices or markings that include the words NO PARKING—FIRE LANE", maintained clean and legible</i>	IFC 503.3
1 7	Fire lane sign dimensions	12 in. wide × 18 in. high, red letters on white reflective background. Both sides of 20–26 ft lanes; one side of lanes >26 and <32 ft	IFC Appendix D103.6 —  conditional, see below
1 8	Fire lane geometry	20 ft minimum width , dimensioned on the site plan; hydrant hose lay 250 ft (500 ft if sprinklered)	Code of Ords. Sec. 23-92; IFC 503.2.1
1 9	Knox Box / key box	UL 1037-listed, location approved by the fire code official. Owner must notify the FMO and re-key when a lock changes	IFC 506.1, 506.2
2 0	 Elevator key box label	Front cover permanently labeled "Fire Department Use Only—Elevator Keys" . Mounted at each elevator bank in the lobby nearest the lowest level of FD access, 5 ft 6 in. AFF, right side of the bank	IFC 506.1.2 — where the elevator uses a non-standardized key

#	Sign	Requirement	Citation
2 1	★ Fire protection room identification	"Rooms containing controls for air-conditioning systems, sprinkler risers and valves , or other fire detection, suppression or control elements shall be identified for the use of the fire department." Signs "constructed of durable materials, permanently installed and readily visible" → fire riser room, FACP, mechanical, electrical	IFC 509.1
2 2	Utility equipment identification	Gas shutoffs, electric meters, service switches — "clearly and legibly marked to identify the unit or space that it serves"	IFC 509.1.1
2 3	"THIS DOOR BLOCKED"	Exterior side of any non-functional door that still looks like a door. Stroke ≥¼ in., letters ≥6 in. , contrasting	IFC 504.2 — only if such a door exists
2 4	★ Roof access stairway sign	Buildings four or more stories must have a stairway to the roof, "marked at street and floor levels with a sign indicating that the stairway continues to the roof." Applies to H2SEP	IFC 504.3

⚠ **The fire lane sign spec is conditional, and it is the #1 discretionary item.** IFC 101.2.1: "Provisions in the appendices shall not apply unless specifically adopted." The 12"×18" red-on-white spec lives in **Appendix D**, so it binds only if Eagle Pass adopted Appendix D. Base IFC 503.3 says "signs **or** other approved notices **or** markings" — leaving wording, letter size, color and spacing entirely to the fire code official. **No published Eagle Pass fire-lane marking standard was found. Get the spec in writing before striping or fabricating.**

4. Fire protection systems

#	Sign	Requirement	Citation
2 5	★ FDC identification	A metal sign with raised letters not less than 1 in. reading AUTOMATIC SPRINKLERS or STANDPIPES or TEST CONNECTION or a combination. Where the FDC doesn't serve the whole building, an added sign must state which portions it serves	IFC 912.5
2 6	FDC locator sign	Where the FDC isn't visible to approaching apparatus: " FDC " ≥6 in. high , words ≥2 in. , or an arrow	IFC 912.2.2
2 7	Standpipe hose connection ID	Cabinets containing standpipes, hose, extinguishers or FD valves: permanently attached sign, letters ≥2 in., contrasting color. <i>Exception: not needed where the door has an approved clear vision panel or is full glass</i>	IFC 905.7.1
2 8	Extinguisher location indicators	"In rooms or areas in which visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers." Mounting: top ≤5 ft AFF (≤40 lb), bottom ≥4 in. off floor	IFC 906.5, 906.6, 906.9; NFPA 10
2 9	★ NFPA 13 hydraulic design nameplate	At every riser, floor control assembly and alarm valve . Weatherproof metal or rigid plastic, secured with corrosion-resistant wire or chain: design area location and size, discharge densities, flow and residual pressure at the base of the riser , occupancy classification, hose stream allowance, and the installing contractor's name	NFPA 13 — section number varies by edition
3 0	★ Control valve / drain / test connection signs	Every control valve, main drain, auxiliary drain, venting valve and inspector's test connection — control valve signs must identify the portion of the building served , and where multiple valves exist, indicate where the others are	NFPA 13
3 1	Local reinforcement	The City's sprinkler submittal checklist has an explicit line: " All labeling and signage posted in accordance with NFPA 13, 13D, 13R. "	Eagle Pass FMO sprinkler submittal

#	Sign	Requirement	Citation
3 2	Kitchen hood suppression	Distinctive audible + visible alarms and warning signs to warn of pending agent discharge	IFC 904.3.4 — if a Type I hood with fixed suppression is provided

⚠ **Item 31 puts the NFPA 13 vs 13R conflict on the Fire Marshal's own checklist.** The City asks for signage "in accordance with NFPA 13, **13D, 13R**" without picking one, while **conflicts B5.3** has G002 saying NFPA 13, G100 saying 13R, and the FD-stamped shop drawing saying 13 — at a phantom 2021 edition. **The riser signage content depends on which standard and which edition, so resolve B5.3 before the riser nameplates are fabricated.**

5. Elevators, shafts and rooms

#	Sign	Requirement	Citation
3 3	★ Elevator emergency sign	Adjacent to each elevator call station on all floors. ⚠ The IFC and IBC give different legends — IFC 606.3: "IN FIRE EMERGENCY, DO NOT USE ELEVATOR. USE EXIT STAIRS." IBC 3002.3: "IN CASE OF FIRE, ELEVATORS ARE OUT OF SERVICE. USE EXIT STAIRS." Most listed pictorial signs satisfy both — ask the FMO which they want	IFC 606.3 / IBC 3002.3
3 4	★ Star of Life (stretcher elevator)	Buildings four or more stories need a stretcher-capable elevator, identified by the international symbol for emergency medical services (star of life), ≥3 in. high, placed inside on both sides of the hoistway door frame. Applies to H2SEP	IBC 3002.4
3 5	SHAFTWAY	On exterior openings reachable by the FD that open on a hoistway/shaftway, and on interior door/window openings to one: "SHAFTWAY" in red letters ≥6 in. on a white background. <i>Interior exception: not required where readily discernible as a shaftway by construction</i>	IFC 316.2
3 6	ELECTRICAL ROOM	"Doors into electrical control panel rooms shall be marked with a plainly visible and legible sign stating ELECTRICAL ROOM or similar approved wording." Plus each disconnecting means legibly and durably marked to indicate its purpose	IFC 604.3.1
3 7	Elevator machine room ID	Identified for fire department use (IFC 509.1); typical wording "ELEVATOR MACHINE ROOM — AUTHORIZED PERSONNEL ONLY" plus high-voltage marking. ASME A17.1 requires access doors self-closing, self-locking, kept locked	IFC 509.1; ASME A17.1
3 8	Emergency power identification	Sign at the service-entrance equipment giving type and location of on-site emergency power sources; all boxes, enclosures, transfer switches, generators and power panels for emergency circuits permanently marked	NEC 2017 §§700.7, 700.10(A)
3 9	Arc-flash / high voltage	Arc-flash warning marking on switchboards, panelboards, MCCs; "DANGER — HIGH VOLTAGE — KEEP OUT" over 1,000 V	NEC 2017 §§110.16, 110.21(B), 110.34(C)

H2SEP has 4 electrical rooms (033, 219, 319, 419) and 2 elevators — item 34 means **2 cabs × 4 floors × 2 jambs = 16 star-of-life placements**, on top of the 16 ADA hoistway floor designations at the same jambs.

6. ★★ Fire barrier stenciling — the one that gets missed above the ceiling

IBC 703.7, verbatim scope:

*"Where there is an **accessible concealed floor, floor-ceiling or attic space**, fire walls, fire barriers, fire partitions, smoke barriers and smoke partitions or any other wall required to have protected openings or penetrations shall be effectively and permanently identified with signs or stenciling in the concealed space."*

Spec	Requirement
Location	Within 15 ft of the end of each wall and at intervals not exceeding 30 ft measured horizontally along the wall
Lettering	Not less than 3 in. high with a minimum $\frac{3}{8}$ in. stroke, in a contrasting color
Suggested wording	"FIRE AND/OR SMOKE BARRIER — PROTECT ALL OPENINGS" (or other approved wording)

This lands **above the corridor and guest-room ceilings, on both sides of every rated wall**. H2SEP's rated walls are already known from the DB: **W3/W3A** (stair, elevator and linen chute walls, 2 HR), **W4** (corridor walls, 1 HR, STC 54), **W5** (guestroom demising). **This is a painter/drywall scope item that has to happen before the ceiling closes** — and it is exactly what a fire marshal looks for on a rough-in walk.

Fire door marking: *"FIRE DOOR—DO NOT BLOCK"* on doors designed to be normally open; *"FIRE DOOR—KEEP CLOSED"* on doors designed to be normally closed. **Letters ≥ 1 in.**, permanently displayed (IFC 705.2.2, where required by the fire code official — **assume required**). Manufacturer listing labels must stay **legible and unpainted** (IFC 705.2.1).

7. Guest room evacuation diagram — mandatory here

IFC 403.10.1.1 makes it a City requirement, not just a brand or NFPA one:

*"A diagram depicting **two evacuation routes** shall be posted on or immediately adjacent to every required egress door from each hotel or motel sleeping unit."*

× **115 keys**. NFPA 101 §28.7.4 adds that the diagram must reflect the **actual room arrangement, exit locations and room identification**. The brand SKU is **H2SN-EVP79** (7.75" × 9.25", ~\$19) — see **BRAND-AND-PROJECT-RECORD.md**.

8. Hazardous materials and no-smoking

#	Sign	Requirement	Citation
40	NFPA 704 diamond — pool chemical room	At entrances where hazmat is stored <i>"in quantities requiring a permit"</i> and at specific entrances and locations designated by the fire code official . Permit trigger: corrosive liquids > 55 gal , corrosive solids > 1,000 lb (IFC Table 105.6.20)	IFC 5003.5
41	Container labeling	<i>"Individual containers, cartons or packages shall be conspicuously marked or labeled in an approved manner. Rooms or cabinets containing compressed gases shall be conspicuously labeled: COMPRESSED GAS"</i> — relevant if CO ₂ is used for pH control	IFC 5003.5.1
42	Hazmat sign durability	<i>"shall not be obscured or removed, shall be in English as a primary language or in symbols allowed by this code, shall be durable, and the size, color and lettering shall be approved"</i>	IFC 5003.6
43	"NO SMOKING"	<i>"The fire code official is authorized to order the posting of 'No Smoking' signs."</i> ⚠️ <i>"The content, lettering, size, color and location of required 'No Smoking' signs shall be approved"</i> — entirely at the FMO's discretion	IFC 310.3–310.5

A typical hotel pool room may sit **below** the permit quantities — but Texas fire marshals routinely require the diamond under the "designated by the fire code official" clause. See [POOL-SIGNAGE.md](#) §5 for the ratings guidance (calcium hypochlorite is **OX**; muriatic acid takes **no** bottom-quadrant symbol; **"COR" is not a valid NFPA 704 symbol**).

9. Not required — do not over-build

Item	Why not
Fire Command Center	High-rise only (occupied floor >75 ft). H2SEP is 48'-1¼"
Fire Service Access Elevator symbols	Only where IBC 403.6.1 applies — occupied floor >120 ft
Occupant Evacuation Elevator signage	Only where IBC 3008 elevators are provided
AREA OF REFUGE signs	⚠️ Not required in buildings sprinklered throughout per 903.3.1.1/903.3.1.2 (IBC 1009.3.3 Exc. 2, 1009.4.2 Exc. 2). But that waiver keys to NFPA 13, not 13R — so conflicts B5.3 decides it. Same finding as ADA-TAS-REQUIREMENTS.md
"WHEN ALARM SOUNDS —CALL FIRE DEPARTMENT" at pull stations	Only where the alarm is not monitored by a supervising station
Exit signs inside guest rooms	Expressly excepted for R-1 (IFC 1013.1 Exc. 3)
Luminous egress path markings (IFC 1025)	High-rise only. (Note: if it applied, stair ID signs would have to be made of the same luminous material)
"NOT AN EXIT" signs	⚠️ The 2018 IFC and IBC contain no such requirement. It comes from NFPA 101 §7.10.8.3 — "NO" in letters 2 in. high with ⅜ in. stroke, "EXIT" in letters 1 in. high, EXIT below NO. Texas's SFMO adopted NFPA 101-2021 effective 9/1/2023, so it may arrive via a state inspection or an FMO request. Ask; don't assume either way

10. Ask the Fire Marshal these twelve things before fabricating

Call (830) 773-1915 / email ecuevas@eaglepasstx.gov. Get answers in writing and attach them to the sign submittal.

1. **Has Eagle Pass adopted IFC Appendix D?** Decides whether the 12"×18" red-on-white fire lane spec is enforceable or whether the FMO has its own.
2. **The fire lane marking standard** — curb color, stencil wording, letter size, repeat interval, sign post height and spacing. **Nothing is published; this is the top discretionary item.**
3. **The local amendments** to the 2018 IFC in Code of Ordinances **Chapter 13** — request a PDF.
4. **Room ID sign letter heights** for FIRE RISER / FACP / ELECTRICAL / MECHANICAL. IFC 509.1 sets none.
5. **Which elevator legend** — IFC 606.3 or IBC 3002.3 wording.
6. **Knox Box** — required? Which model, which location? And is an elevator key box (506.1.2) required?
7. **NFPA 704 on the pool chemical room** — required even below permit quantities?
8. **ERRCS** — is emergency responder radio coverage required (IFC 510.1), and what markings?
9. **Which spaces are assembly** for the occupant load posting, and the required sign format.

10. **"NOT AN EXIT" signs** — does the FMO want NFPA 101 §7.10.8.3 signs?
11. **Which NFPA 13 edition** the FMO reviews to — and **what the stamped shop drawing actually cites**, given that NFPA 13 has no 2021 edition.
12. **The mid-rise construction section** referenced by checklist item 23 — we don't have it.

Sources

City of Eagle Pass — [Fire Marshal's Office](#)³ · [Building Construction Plan Review](#)⁴ (text in §1 extracted directly from this PDF) · [Fire Sprinkler Plan Submittal](#)⁵ · [Fire Alarm Plan Submittal](#)⁶ · [Commercial Permit Application](#)⁷ · [Residential Permit Application \(full code list\)](#)⁸ · [Commercial Development Permit Guide 2023](#)⁹ · [Code of Ordinances Ch. 13](#)¹⁰

Model codes — [2018 IFC \(ICC\)](#)¹¹ · [2018 IBC \(ICC\)](#)¹² · verbatim text read from the unamended 2018 base at [up.codes IFC-2018](#)¹³ and [up.codes IBC-2018](#)¹⁴

Texas — [Texas State Law Library](#) — [Building Codes](#)¹⁵ · [Gov't Code §419.909](#)¹⁶ · [H&S Code §792.002](#)¹⁷ · [TDI/SFMO adopted codes](#) — [NFPA 1 & 101 2021, eff. 9/1/2023](#)¹⁸ · [TDI/SFMO rules and statutes](#)¹⁹ · [28 TAC Ch. 34](#)²⁰

NFPA (secondary — primary text is paywalled) — [NFPA 101 §7.10.8.3 "No Exit"](#)²¹ · [§7.10.8 Special Signs](#)²² · [§28.7.4 Emergency Instructions](#)²³ · [NFPA 13 signage guide](#)²⁴ · [QRFS sprinkler sign guide](#)²⁵

*Confidence: items quoted verbatim above were read from the code text or from the City's own documents. NFPA section numbers are from secondary sources because NFPA primary text is paywalled — the requirements are sound, the section numbers should be confirmed against the edition the FMO reviews to. **No section number in this document was invented.***

SECTION 3

ADA and Texas Accessibility Standards

Source file: research/signage/ADA-TAS-REQUIREMENTS.md

Home2 Suites by Hilton · 115 keys · Eagle Pass, Maverick County, Texas. Researched 2026-08-20 against the 2010 ADA Standards (Access Board) and the 2012 Texas Accessibility Standards (TDLR primary documents). Companion files: [CBC-vs-TAS-DELTA.md](#) (what G401 gets wrong), [PROJECT-FINDINGS.md](#) (what the permit set says), [sign-schedule.md](#) (counts).

Six premises we started with that are wrong

These change what gets bought, so they lead. Each was checked against primary text.

#	Common belief	What the standards actually say
1	"70% contrast is required"	False. Neither 2010 ADA nor 2012 TAS specifies any contrast percentage. §703.5.1 requires only a non-glare finish and light-on-dark or dark-on-light . The Access Board: "A minimum level of color contrast is not specified in the Standards." The 70% figure is a legacy 1991 ADAAG appendix recommendation — advisory, never enforceable.
2	"Texas requires geometric restroom symbols (triangle/circle)"	False — that is California (CBC 11B-703.7.2.6). Zero occurrences of "geometric", "triangle" or "equilateral" in 2012 TAS or 1994 TAS. Independently verified twice. Do not buy triangle/circle restroom signs.
3	"Tex. Transp. Code §681.009/§681.011 dictates the parking sign wording"	Wrong instrument. §681.011 sets <i>finest</i> ; §681.009 <i>delegates</i> to the TDLR standards. The actual mandate is 16 TAC §68.104 — see below.
4	"There's a transient-lodging exception in §216.2"	No such exception exists. §216.2 has exactly one exception, for exterior signs <i>not</i> at the door they serve. Every one of the 115 guest room doors needs a tactile + Grade 2 Braille sign. No hotel carve-out.
5	"§216.8 = TTY, §216.9 = ALS, §216.11 = stairs, §216.12 = elevators"	Scrambled. Correct: 216.6 Entrances · 216.7 Elevators · 216.8 Toilet/Bathing · 216.9 TTYs · 216.10 ALS · 216.11 Check-Out Aisles · 216.12 Amusement Rides.
6	"ADA has stairway sign requirements"	It has none. §504/§505 contain no signage provisions. All stair signage on this job is IBC-driven — coordinate with the fire marshal, not the RAS.

The Texas enforcement layer

TAS compliance is a **state licensing matter with a physical inspector**, on top of federal ADA civil-rights exposure.

Item	Requirement	Citation
Governing law	Texas Architectural Barriers Act, Tex. Gov't Code Ch. 469 , administered by TDLR	Gov't Code Ch. 469
Standard	2012 TAS , effective 2012-03-15, based on the 2010 ADA Standards	2012 TAS
Applies to hotels?	Yes, expressly — " <i>an inn, hotel, motel, or other place of lodging</i> " (>5 rooms)	16 TAC §68.20(d)(1)
Registration threshold	\$50,000 estimated construction cost → mandatory TDLR registration + RAS plan review	Gov't Code §469.101; 16 TAC §68.50(a)

Item	Requirement	Citation
Submission deadline	Design professional submits ≤20 days after plans/specs are issued	16 TAC §68.50(b)
RAS inspection	Owner must obtain inspection ≤1 year after completion ; Request for Inspection filed ≤30 days after completion	16 TAC §68.52(a)
Fees	\$175 filing · \$300 late · \$215/hr special review	16 TAC §68.80
Technical Memoranda	24 active TMs. None address signage.	16 TAC §68.100

A 115-key hotel vastly exceeds \$50k. **Registration, RAS plan review and RAS inspection are all mandatory, and the owner — not the architect, not the GC — is legally responsible** (§469.101, §469.105).

Texas accessible parking — 16 TAC §68.104

This is the single largest Texas-specific add, and it is not in the TAS document. It is a separate TDLR rule, effective **August 1, 2020**, implementing **HB 3163 (86th Leg., 2019)** — which is why a search of the TAS PDF alone misses it. Verified verbatim.

§68.104(a) — every paved accessible parking space must include:

1. The **International Symbol of Accessibility painted conspicuously on the surface** in a color that contrasts the pavement.
2. The words **"NO PARKING"** painted on any access aisle adjacent to the space — **all capital letters, letter height ≥12 inches, stroke width ≥2 inches, centered within each adjacent access aisle.**
3. A consequences sign stating at minimum **"Violators Subject to Fine and Towing"** in **letter height ≥1 inch**; mounted on a pole, post, wall or freestanding board; **no more than 8 inches below** the TAS 502.6 sign; **bottom edge no lower than 48" and no higher than 80" above ground level.**

§68.104(b): a TAS 502.6 identification sign that already includes the (a)(3)(A) wording satisfies (a)(3) — i.e. one combined sign is acceptable.

No dollar amount is required on the sign. For owner awareness only, Tex. Transp. Code §681.011 fines run **\$500–\$750** first offense up to **\$1,250 + 50 hrs** community service. ⚠️ **§681.011(f-2): a peace officer may issue only a warning, not a citation, if the space lacks a compliant identification sign.** A non-compliant sign makes the space legally unenforceable.

Plus a second, unrelated Texas sign — Tex. Occ. Code §2308.301

Distinct requirement, distinct statute, **covers the whole lot, not just accessible spaces**, and **the RAS will not check it**. Required to legally tow anyone:

- **≥18" wide × 24" tall**, weather-resistant, permanently mounted
- **Bottom edge 5–8 ft above ground**
- International **towing symbol**
- States **who may park** and prohibits all others
- Bears **"Unauthorized Vehicles Will Be Towed or Booted at Owner's or Operator's Expense"**

- **24-hour telephone number with area code**
- At **each** driveway or curb cut; or where entrances are indefinite, at intervals so **no entrance is more than 25 ft from a sign**

Note for the record: two independent research passes disagreed here — one found only §2308.301, the other only §68.104. **Both are required.** §68.104 is the TDLR accessibility rule the RAS inspects; §2308.301 is the towing statute that makes the lot enforceable. Neither substitutes for the other.

Accessible parking counts — Table 208.2

1–25 spaces → 1 · 26–50 → 2 · 51–75 → 3 · 76–100 → 4 · 101–150 → 5 · 151–200 → 6 · 201–300 → 7 · 301–400 → 8 · 401–500 → 9 · 501–1000 → 2% · 1001+ → 20 + 1 per 100 over 1000.

Van spaces (§208.2.4): [accessible spaces ÷ 6] — “For every six or fraction of six”.

! §208.2 Advisory: the count is calculated **separately for each parking facility**, not off the site total. If H2SEP has a front lot and a rear lot reading as separate facilities, compute each independently — this yields **more** accessible spaces and is a frequent RAS citation. **G001 carries the parking matrix and has not been extracted** (see [PROJECT-FINDINGS.md §1](#)) — pull it before fixing the count.

Tactile room identification — the largest package

Applies to every permanent room and space (§216.2 → 703.1, 703.2, 703.5; 703.2 pulls in 703.3, so **Braille is mandatory** even though 216.2 doesn't cite it directly).

Character specs (§703.2): raised **1/32" min** · **uppercase only** · **sans serif**, not italic/script/decorative · “O” width **55%–110%** of “I” height · height **5/8"–2"** (may drop to 1/2" min where separate raised and visual characters carry the same message) · stroke **≤15%** of height · character spacing 1/8" min to 4× stroke max, **3/8" min** from raised borders · line spacing **135%–170%**.

Braille (§703.3): **contracted Grade 2**, domed/rounded dots. Dot base dia. 0.059"–0.063" · dots in cell 0.090"–0.100" o.c. · adjacent cells 0.241"–0.300" o.c. · **dot height 0.025"–0.037"** · cell-to-cell below 0.395"–0.400" o.c. Positioned **below** the entire text, **3/8" min** from other tactile characters. Uppercase indicator only before the first word of a sentence, proper nouns, individual letters, initials and acronyms. **Braille must spell the whole message** — “ROOM 214”, not “214”.

Mounting (§703.4):

Parameter	Requirement
Height	48" min to baseline of the lowest tactile character; 60" max to baseline of the highest . <i>Not a centerline dimension — a common field error.</i>
Single door	Latch side
Pair, one active leaf	Inactive leaf
Pair, two active leafs	Right of the right-hand door
No wall at latch side	Nearest adjacent wall

Parameter	Requirement
Clear floor space	18" × 18" min , centered on the tactile characters, beyond the arc of the door swing between closed and 45° open
Push-side exception	Permitted on the push side of doors with closers and without hold-opens

⚠ Sign location (703.4.2) is the single most common real-world RAS write-up — signs on the door leaf instead of the latch wall, or without the 18"×18" clear space. Verify in field.

Pictograms (§703.6): field **6" min height**, non-glare, contrasting, with a tactile text descriptor **directly below the field** — characters and Braille must **not** sit inside the pictogram field.

Visual-only signs (§703.5) — directional, informational, wayfinding, rules of conduct, occupant load: **no tactile, no Braille required**. 40" min AFF; stroke 10%–30%; character height per Table 703.5.5 by viewing distance (5/8" at <72", scaling to 3"+ above 120" baseline at ≥21 ft).

Which H2SEP spaces get one

All 55 room-ID signs in `sign-schedule.md`, plus all 115 guest room doors. Back-of-house carries a nuance: **TAS §203.9** limits employee work areas to §206.2.8, §207.1 and §215.3 only — §216 is not in that list, so signs identifying spaces *within* an employee work area are arguably unscoped. **But doors opening off a public corridor are routinely required by RAS inspectors. Recommendation: sign all 35.** The cost delta is trivial against a failed inspection. (TDLR TM 2013-21 *Employee Work Areas* is the reference.)

Means of egress

Sign	Requirement	Citation
Tactile "EXIT"	<i>"Doors at exit passageways, exit discharge, and exit stairways shall be identified by tactile signs complying with 703.1, 703.2, and 703.5."</i> ADA/TAS does not specify the wording — the IBC does. Scopes the corridor-to-stair door on each floor, the discharge door, and exit passageway doors. Not every door in the building.	216.4.1
Area of refuge instruction sign	Required only where the IBC requires an area of refuge . Visual only (703.5).	216.4.2
AMOE directional signs	Required only where the IBC requires them . Visual only (703.5).	216.4.3
IBC raised + Braille EXIT signs	"EXIT" in visual + raised + Braille per ICC A117.1, with directional companions	IBC 1013.4
Stairway identification sign	Required at each floor landing inside interior exit stairways connecting more than 3 stories — H2SEP's 4 stories trigger this . States floor level, terminus top and bottom, stair identification, story of and direction to the exit discharge , and availability of roof access . Located 5 ft above the floor landing , readable with the door open and closed.	IBC 1023.9
Floor-level tactile sign	At each floor landing adjacent to the door into the corridor; floor level in visual + raised + Braille	IBC 1023.9.1

! Areas of refuge — the answer depends on an unresolved project conflict

The chain: TAS §207.1 defers accessible means of egress to the IBC → TAS §216.4.2/.3 signage triggers only if the IBC requires an AOR → **IBC 1009.3.3 Exception 2** waives areas of refuge in buildings sprinklered throughout per **§903.3.1.1** or **§903.3.1.2**.

That waiver keys to NFPA 13. It does not extend to NFPA 13R.

H2SEP's sprinkler standard is contested three ways (**conflicts B5.3**, OPEN): G002 note 8 says NFPA 13, G100 says the basis of design is **13R**, and the Eagle Pass FD–stamped shop drawing says 13. **So the sprinkler conflict directly decides whether areas of refuge and their signage are required.** Resolve B5.3 before pricing the egress sign package.

If NFPA 13 (waiver applies) — three requirements still survive:

Item	Location	Citation
Two-way communication system	Elevator landing on each accessible floor above the level of exit discharge — floors 2, 3, 4	IBC 1009.8
Instructions sign at the device	Adjacent to each two-way communication device: directions for use, how to summon assistance, and written identification of the location . Visual characters (703.5)	IBC 1009.8.2
AMOE directional signage	At exits serving an accessible space that are not an accessible means of egress, and at elevator landings	IBC 1009.10

If NFPA 13R (no waiver) — add "AREA OF REFUGE" door signage with ISA, illuminated where exit signs are illuminated, visual + raised + Braille per IBC 1013.4 (IBC 1009.9), plus posted instructions per IBC 1009.11.

Restrooms — the counterintuitive new-construction answer

Sign	Verdict
Tactile room identification	Always required (216.2) — 019 WOMENS · 020 MEN'S · 027 Unisex
ISA on the restroom sign	NOT required in new construction. §216.8 is conditioned entirely on " <i>Where existing toilet rooms or bathing rooms do not comply with 603.</i> " TAS §213.2 requires every new-construction toilet room to comply with 603 → the trigger never fires.
Directional signs to an accessible restroom	NOT required in new construction — same conditional trigger
Unisex / family / all-gender	ADA/TAS impose no special signage requirement . Tactile + Braille ID per 216.2 is all.
Clustered single-user restrooms	<i>If you use the §213.2 Exc. 4 allowance (only 50% of a cluster must comply), the complying rooms must be ISA-identified</i>
ISA graphic form	Must be Figure 703.7.2.1 — the classic static wheelchair symbol. Neither the Access Board nor TDLR has adopted the "Dynamic/Accessible Icon." Do not specify the dynamic icon on a TDLR-inspected project.

Practical recommendation: put the ISA on anyway. It costs nothing, guests expect it, and Hilton brand standards will likely require it. The point is that **if an RAS cites you for a missing ISA on a new-construction restroom sign, the standard is on your side.**

Elevators (§407) — 2 cabs × 4 floors

Element	Requirement	Citation
Hoistway floor designation	Both jambs, every hoistway entrance, every floor. Tactile characters 2 inches high minimum + Braille, per 703.2 and 703.4.1	407.2.3.1
Tactile star	Both jambs at the main entry level only	407.2.3.1
Car control buttons	Tactile characters immediately to the LEFT of each button + Braille (3/16" min separation allowed). Buttons 3/4" min smallest dimension. Exempt from the 703.4.1 height rule	407.4.7.1.1 –.1.2
Required button symbols	Table 407.4.7.1.3 — Emergency Stop "ST"OP · Alarm AL"AR"M · Door Open OP"EN" · Door Close CLOSE · Main Entry MA"IN" · Phone PH"ONE"	407.4.7.1.3
Keypads	Standard telephone arrangement; number 5 key carries a single raised dot , base dia. 0.118"–0.120"	407.4.7.2
Emergency two-way comms	<i>"Tactile symbols and characters shall be provided adjacent to the device"</i> — tactile + Braille required	407.4.9
Car position indicator	Visual characters 1/2" high min ; audible annunciator 10 dB above ambient, ≤80 dB, 300–3000 Hz	407.4.8
"IN CASE OF FIRE" sign	Adjacent to each call station, all floors — <i>"IN CASE OF FIRE, ELEVATORS ARE OUT OF SERVICE. USE EXIT STAIRS."</i> This is IBC 3002.3, not an ADA/TAS requirement.	IBC 3002.3
LULA	Not permitted here. §206.6 Exc. 1 allows LULAs only in buildings eligible for §206.2.3/§206.7 exceptions — private facilities under three stories . A 4-story hotel needs a full passenger elevator per §407 .	206.6, 206.2.3

Guest rooms — 115 keys

Every guest room door needs a tactile + Grade 2 Braille number sign. §216.2's only exception covers exterior signs not at the door they serve. §216.1 Exc. 1 exempts *"building directories, menus, seat and row designations, occupant names, building addresses, and company names and logos"* — a room number is none of those. (An occupant *name* plate would be exempt; the number would not.)

Item	Verdict
Sign identifying a room as accessible	NOT REQUIRED. §224 and §806 contain no signage provision . No ADA/TAS requirement to label a room "accessible" or "has communication features".
Communication-features hardware (not a sign)	§806.3.2 — visible notification for incoming phone calls and a door knock or bell, not connected to the visible alarm appliances ; telephone volume control per 704.3; electrical outlet within 48 inches of the telephone to facilitate TTY use
The real obligation is operational	28 CFR §36.302(e) — the hotel must identify and describe accessible features in enough detail for a guest to independently assess whether a room meets their needs, allow reservation of specific accessible rooms, block them from general inventory, and hold them until all rooms of that type are rented. This is the #1 source of hotel ADA litigation and it is a policy requirement, not a sign.

Dispersion (§224.5) — easy to get wrong

1. Accessible rooms must be **dispersed among the various classes** of guest room, offering comparable choice of type, bed count and amenities.

2. Where the count is too small for full dispersion, prioritize **(1) room type, (2) number of beds, (3) amenities**.
3. **At least one** mobility-features room must **also** have communication features.
4. **⚠ Not more than 10% of the mobility rooms may count toward the communication-features minimum.** For H2SEP: $10\% \text{ of } 7 = 0.7 \rightarrow \mathbf{1 \text{ room}}$ may double-count. The other **11** communication-features rooms must be **separate** from the 7 mobility keys.

H2SEP distinct accessible rooms: 7 mobility + 11 communication-only = 18 keys. Check that against the design — the room map identifies 8 of the 12 hearing rooms (209, 213, 216, 218, 309, 313, 316, 318) and **none of the 8 is one of the 7 mobility keys**, which is consistent, but floors 1 and 4 have never been scanned. See [PROJECT-FINDINGS.md](#) §6.

Amenities — what needs no sign

Space	ADA/TAS signage
Pool (ZONE-B)	NONE. §242 and §1009 contain no signage provisions at all — the requirement is the accessible means of entry itself. §242.2 needs two means of entry, but Exception 1: a pool with <300 linear feet of pool wall needs only one , and it must be a pool lift (1009.2) or sloped entry (1009.3) . H2SEP's pool is well under 300 lf $\rightarrow$ the fixed pool lift satisfies §242.2. (<i>Texas DSHS pool signs are a separate law — see the pool file.</i>)
Fitness 023	Tactile room ID only. §236 governs exercise machines — no signage.
Guest Laundry 024	Tactile room ID only. §214 governs washers/dryers — no signage.
Breakfast 006 / Servery 009	Tactile room ID only. §226 dining surfaces — no signage.
Meeting Room 018	Tactile room ID + assistive listening sign only if the room has permanently installed audio amplification — §219.2 Exception: <i>"assistive listening systems shall not be required where audio amplification is not provided."</i> Confirm whether 018 has installed amplification; this alone decides it.

If ALS is required: sign per **§216.10** with the **International Symbol of Access for Hearing Loss** (Fig. 703.7.2.4), visual characters (703.5). Receiver count per Table 219.3 — ≤ 50 seats: 2 receivers (2 hearing-aid compatible); 51–200: **2 + 1 per 25 seats over 50**, min 2 HAC; overall **25% of receivers, never fewer than 2**, must be hearing-aid compatible.

Explicitly NOT required — don't over-buy

§216.1 exempts entirely: **building directories** (the Home2 lobby directory) · menus · seat and row designations · **occupant names** · **building addresses** · **company names and logos** · **temporary signs posted 7 days or less** · and in **parking facilities**, §216.2, 216.3 and 216.6–216.12 (216.5 $\rightarrow$ 502.6 still applies).

The moment you add a permanent tactile label to a specific room, §216.2 governs it again.

Open verification

1. **🔴 Confirm the IBC edition adopted by the City of Eagle Pass.** Every IBC citation above (1013.4, 1023.9, 1009.x, 3002.3) is edition-dependent. G001 carries the adopted-code summary and has not been extracted.

2.  **Resolve conflict B5.3 — NFPA 13 vs 13R.** It decides the area-of-refuge signage package (see above). This is the highest-value open item in this file.
3.  **Pull G001's parking matrix** to lock the accessible-space and van counts, and determine whether the site reads as one parking facility or two.
4.  **Confirm whether Meeting Room 018 has installed audio amplification** (ALS trigger).
5.  **Register the project in TABS and engage a RAS early** — §68.50(b) requires submission within 20 days of plans/specs being issued. A pre-submittal RAS review is far cheaper than field rework on 115 keys.
6.  **Do not specify** the Dynamic/Accessible Icon, geometric restroom symbols, or "70% contrast" anywhere on the sign schedule.

Sources

Primary standards — [2010 ADA Standards \(Access Board\)](#)²⁶ · [2012 TAS complete PDF](#)²⁷ · [Ch. 1 Definitions](#)²⁸ · [Ch. 2 Scoping](#)²⁹ · [Ch. 4 Accessible Routes](#)³⁰ · [Ch. 5 Site Elements](#)³¹ · [Ch. 7 Communication Elements](#)³² · [Ch. 8 Special Rooms](#)³³ · [1994 TAS §4.30](#)³⁴

Texas law & rules — [Gov't Code Ch. 469](#)³⁵ · [Transp. Code Ch. 681](#)³⁶ · [Occ. Code §2308.301](#)³⁷ · **16 TAC §68.104**³⁸ · [TDLR AB Laws & Rules](#)³⁹ · [TDLR AB FAQ](#)⁴⁰ · [TDLR Fee Schedule](#)⁴¹ · [TDLR Technical Memoranda](#)⁴² · [TDLR rule-change bulletin, eff. 8/1/2020](#)⁴³

Federal — [28 CFR §36.302 \(reservations\)](#)⁴⁴

Guidance — [Access Board Guide Ch. 7: Signs](#)⁴⁵ · [Ch. 4: Accessible Means of Egress](#)⁴⁶

Building code (verify edition) — [IBC 1013.4](#)⁴⁷ · [IBC 1023.9](#)⁴⁸ · [IBC 1009](#)⁴⁹ · [IBC 3002.3](#)⁵⁰

Technical research for design coordination and TDLR/RAS submittal planning. Not a substitute for review by the project's Registered Accessibility Specialist.

SECTION 4

G401 delta: California code vs Texas

Source file: research/signage/CBC-vs-TAS-DELTA.md

H2SEP · Home2 Suites by Hilton · 115 keys · Eagle Pass, Maverick County, Texas. Researched 2026-08-20. Addresses **conflicts A10 (OPEN)**: G400/G401 cite California CBC 11B on a Texas project; G001's Code Summary cites no accessibility standard at all.

Verification status. The load-bearing claim below — that Texas has never required geometric restroom door symbols — was checked two independent ways: by full-text search of TDLR's official 2012 and 1994 TAS PDFs (with a control term to prove the extraction was valid), and by a separate direct read of TDLR's published TAS Chapter 7, which confirms 703.7.2 ends at .4 Assistive Listening Systems . Both agree.

Bottom line

The single largest item on G401 — the 12-inch equilateral triangle / circle geometric restroom door symbols — is a **California requirement that has never existed in Texas law**. Almost nothing else on a correctly drawn CBC 11B sheet will technically fail a TAS inspection, because CBC 11B meets or exceeds TAS on every character, Braille and mounting metric. The real exposure is **parking signage**, where G401 posts a "Minimum Fine \$250" that is legally wrong in Texas (**\$500–\$750** first offense) and a tow sign with California wording and dimensions that does not satisfy the Texas statute. The two things that actually bite: the **Texas Occupations Code §2308.301 tow sign at every vehicle entrance**, which appears on no California sheet and which the hotel needs in order to legally tow anyone; and the process fact that a **Registered Accessibility Specialist inspects against TAS only** — CBC 11B has no legal standing in Texas.

Two corrections to what we assumed going in

1. Texas has never required geometric restroom symbols — not even under the old TAS. It is widely repeated that the 1994 TAS carried one. It did not. TDLR's official 1994 TAS (§4.30 Signage) runs 4.30.1 General · 4.30.2 Character Proportion · 4.30.3 Overhead · 4.30.4 Raised/Braille · 4.30.5 Finish and Contrast · 4.30.6 Mounting · 4.30.7 Symbols of Accessibility · 4.30.8 (reserved). **No geometric symbol provision, in either edition.** Secondary sources get this wrong routinely — California's version is visually distinctive enough that people assume it is national. Do not repeat the claim.

2. The Texas accessible-parking statutes do not prescribe sign wording. Tex. Transp. Code **§681.009(b)** delegates to the TCLR standards (i.e. TAS) rather than dictating text, and **§681.011** sets penalties without prescribing any sign copy. The real Texas-only sign G401 will be missing lives in a different code entirely — **Tex. Occ. Code §2308.301**, the tow-away sign.

The delta

Signage item	CBC 11B requires	2012 TAS requires	Verdict	Consequence if built to CBC	Citations
Restroom geometric door symbols	12" equilateral triangle (men), 12" circle (women), triangle inscribed in circle (unisex); ¼" thick; centerline 58"–60" AFF; within 1" of door centerline; must contrast with door	Nothing. TAS 703.7.2 stops at .4	California-only	Not a violation, but 100% wasted cost. Danger: if the schedule treats the door symbol as the room ID, the required latch-side tactile/Braille sign is missing → a real TAS 216.2 violation	CBC 11B-216.8.1, 703.7.2.6 vs TAS 216.2, 703.7.2
"ALL-GENDER MULTI-USER" sign	Combo symbol + sign per 11B-703.1–703.5	Nothing; no Texas analog	California-only	Wasted signs; wording meaningless to a Texas RAS	CBC 11B-216.8.2
Permanent room ID (tactile + Braille)	Raised char + Grade 2 Braille, latch side	Identical language	Same	Build as drawn	CBC 11B-216.2 = TAS 216.2
Character height / case / style / proportion / stroke	5/8"–2" cap height; uppercase; sans serif; "O" 55%–110% of "I"; stroke ≤15%	Word-for-word identical	Same	Build as drawn	CBC 11B-703.2.1–.8 = TAS 703.2.1–.8
Braille dot geometry	Domed/rounded, Table 11B-703.3.1	Identical values	Same	Build as drawn	CBC 11B-703.3.1 = TAS 703.3.1
Braille position	Below text, flush left or centered; 3/8" min and ½" max separation	Below text; 3/8" min only — no max, no alignment mandate	CA stricter	Safe — CBC is a subset of what TAS allows	CBC 11B-703.3.2 vs TAS 703.3.2
Tactile mounting height	48" min from baseline of lowest Braille cell ; 60" max from highest raised character	48" min / 60" max, both from baseline of tactile character	CA stricter datum	Safe — Braille sits below the text, so CBC's datum is lower. Hold tactile copy inside 48"–60"	CBC 11B-703.4.1 vs TAS 703.4.1
Tactile sign location	Latch side; inactive leaf at pairs; right of right-hand door; 18"×18" clear space outside door swing	Identical	Same	Build as drawn. This is the #1 real-world RAS write-up — verify in the field	CBC 11B-703.4.2 = TAS 703.4.2
Accessible parking sign — base	ISA white-on-blue; "van accessible"; bottom 60" min AFF (80" in circulation path)	ISA per 703.7.2.1; "van accessible"; bottom 60" min AFF. No color mandate, no 80" exception	CA stricter	Safe and conventional — keep the blue/white ISA	CBC 11B-502.6 vs TAS 502.6
Parking sign finish / size	Reflectorized, 70 sq in min	Nothing	California-only	Harmless over-build	CBC 11B-502.6.1

Signage item	CBC 11B requires	2012 TAS requires	Verdict	Consequence if built to CBC	Citations
"Minimum Fine \$250" sign	Required below the ISA	Nothing — TAS contains no "fine" or dollar figure	California -only AND wrong for TX	DELETE. Texas is \$500–\$750 first offense, up to \$1,250 + 50 hrs community service	CBC 11B-502.6.2 vs Tex. Transp. Code §681.011
36"x36" ISA pavement marking	White-on-blue in stall, or stall outlined blue	Only that access aisles be "marked so as to discourage parking in them" (502.3.3)	California -only	Hold — verify the Eagle Pass ordinance before deleting. Pavement marking is near-universal Texas practice and often locally mandated	CBC 11B-502.6.4 vs TAS 502.3.3
Tow-away sign	17"W × 22"H, 1" letters, CA-specific copy, at each parking entrance	Not in TAS. Texas requires a <i>different</i> sign under a <i>different</i> statute — see below	Wrong sign entirely	REPLACE, don't delete. Without a §2308.301 sign the hotel cannot legally tow	CBC 11B-502.8 vs Tex. Occ. Code §2308.301
Tactile exit signs — scoping	At exit passageways, exit discharge, exit stairways	Identical	Same	Build as drawn	CBC 11B-216.4.1 = TAS 216.4.1
Tactile exit signs — wording	CA vocabulary: "EXIT STAIR DOWN", "EXIT RAMP DOWN", "EXIT STAIR UP", "EXIT RAMP UP", "EXIT ROUTE", "TO EXIT"	TAS dictates no wording; adopted IBC §1013.4 requires only tactile "EXIT"	California -only vocabulary	Produces more signs than Texas requires , in nonstandard wording, including "EXIT ROUTE" at every corridor-access door. Extra cost; may confuse the Eagle Pass fire marshal	CBC 1013.4 vs TAS 216.4.1 + IBC 1013.4
Area of refuge signage	AOR instruction/ID signage; CA mandates two-way comms at elevator landings even when sprinklers remove the AOR	TAS 216.4.2 scopes only AOR instruction signs where the IBC requires an AOR	Different scoping	A fully sprinklered building triggers the IBC exception — AOR signs on G401 are likely surplus. Verify against the adopted IBC edition and with the fire marshal; two-way comms instruction signage at elevator landings is likely still required	CBC 11B-216.4.2 vs TAS 216.4.2 / IBC 1009.3.3 Exc.
Accessible entrance ISA	ISA where not all entrances are accessible	Identical	Same	Build as drawn	CBC 11B-216.6 = TAS 216.6
Assistive listening signage	Signs where assembly areas require ALS	Identical (TAS 216.10, scoped by 219)	Same	Safe. Meeting Room 018 likely has no installed amplification and may not trigger ALS at all — verify against TAS 219.2	CBC 11B-216.10 = TAS 216.10
Guest room identification	Room numbers are permanent designations → tactile + Grade 2 Braille, latch side, 48"–60". ISA not required on accessible guest room doors	Identical; TAS 224 adds no guest-room signage requirement	Same	Build as drawn. If G401 shows an ISA on the 7 accessible keys, that is required by neither state — delete	CBC 11B-216.2 / 224 = TAS 216.2 / 224
Guest bathroom geometric symbols	Exempt — not required inside transient lodging guest rooms	N/A	Same outcome	If G401 shows symbols on guest bathroom doors it is wrong in California too — a prototype drafting error	CBC 11B-216.8.1 Exc. 1

Signage item	CBC 11B requires	2012 TAS requires	Verdict	Consequence if built to CBC	Citations
Elevator jamb floor designations	Raised + Braille both jambs, 60" AFF to centerline, 2" high, star at main entry	Identical	Same	Build as drawn	CBC 11B-407.2.3.1 = TAS 407.2.3.1
Stairway identification	CBC 1023.9 — floor level, terminus, roof access	IBC 1023.9 via local adoption; not a TAS item	Same in substance	Safe; not an RAS scope item	CBC 1023.9 vs IBC 1023.9

Item 1 in full — both code texts verbatim

California, CBC 11B-703.7.2.6.1: "An equilateral triangle, ¼ inch (6.4 mm) thick with edges 12 inches (305 mm) long and a vertex pointing upward, shall be located at entrances to men's toilet and bathing facilities. The triangle symbol shall contrast with the door, either light on a dark background or dark on a light background." — with .6.2 giving the 12" circle for women's and .6.3 the inscribed combination for unisex, all scoped by **11B-216.8.1:** "Geometric symbols complying with Section 11B-703.7.2.6 shall be provided at entrances to toilet and bathing rooms."

Texas, 2012 TAS 216.2: "Interior and exterior signs identifying permanent rooms and spaces shall comply with 703.1, 703.2, and 703.5. Where pictograms are provided as designations of permanent interior rooms and spaces, the pictograms shall comply with 703.6 and shall have text descriptors complying with 703.2 and 703.5."

TAS 703.7.2 Symbols runs .1 International Symbol of Accessibility · .2 International Symbol of TTY · .3 Volume Control Telephones · .4 Assistive Listening Systems. **The list ends there.**

What that means on the ground

The symbols are **not required** in Texas — but they are also **not prohibited**, and an RAS will not write them up for being present. Two real consequences:

1. **Cost.** Custom ¼"-thick 12" geometric symbols at every public restroom door (019 WOMENS · 020 MEN'S · 027 Unisex, plus pool and fitness if shown) are a fabricated non-catalog item bought for zero Texas benefit.
2. **The dangerous failure mode.** In California the door symbol and the latch-side tactile sign are **two separate requirements**. If G401's schedule assumed the symbol carries the room identification, and the tactile sign is undersized, omitted, or mounted on the door instead of the latch wall, **that is a genuine TAS 216.2 / 703.4.2 violation**. Check the schedule for a discrete latch-side tactile sign at every restroom, independent of any symbol.

Delete from G401 (California-only)

#	Item	Why
1	12" triangle / circle / combo restroom door symbols	No Texas requirement — verified absent from 2012 and 1994 TAS
2	"ALL-GENDER MULTI-USER" sign + combo symbol	California-only
3	"Minimum Fine \$250" parking sign	Not required in Texas and the number is wrong
4	CBC-worded tow sign (17"×22", "...may be reclaimed at ____")	Wrong wording, size and mounting for Texas — replace , see below
5	36"×36" ISA pavement symbol / blue-painted stall	Not a TAS requirement — hold, verify Eagle Pass ordinance first
6	Reflectorized / 70 sq in parking sign spec	Not a TAS requirement (harmless if kept)

#	Item	Why
7	"EXIT ROUTE" / "EXIT STAIR DOWN" / "EXIT RAMP UP" etc. tactile signs	California vocabulary; Texas needs tactile "EXIT" only, at the three scoped door types
8	80"-AFF parking sign exception in circulation paths	No TAS analog; TAS is a flat 60" min to bottom of sign
9	ISA on accessible guest room doors, if shown	Required by neither state; also flags guests as disabled
10	Geometric symbols at guest bathroom doors, if shown	Exempt even in California — prototype drafting error
11	"AREA OF REFUGE" signage, if shown	Sprinklered building → AOR generally not required. Verify with fire marshal before deleting

Add to G401 (Texas-required, currently missing)

Tex. Occ. Code §2308.301 — tow-away sign at every vehicle entrance

The big omission, and invisible to a California-trained team because it lives in the **Occupations Code**, not in any building or accessibility code.

- Minimum **18" wide × 24" tall**, weather-resistant, permanently mounted on pole, post, permanent wall or permanent barrier
- **Bottom edge no lower than 5 ft and no higher than 8 ft above ground**
- Contains the **international towing symbol**
- States **who may park** there and prohibits all others
- Bears the words **"Unauthorized Vehicles Will Be Towed or Booted at Owner's or Operator's Expense"** (or the tow-only / boot-only variants)
- Gives a **telephone number, with area code, answered 24 hours a day**
- **Placement:** facing and conspicuously visible to a driver entering, on the right or left of **each** driveway or curb cut; or where no definite entrances exist, at intervals such that **no entrance is more than 25 ft from a sign**

⚠ The RAS will **not** check this — it is outside TAS scope. It surfaces at operations, or the first time the hotel tries to tow a car and finds it cannot.

Correct Texas fine figures, if a deterrent sign is posted

No Texas statute *requires* posting the fine, but if the owner wants one, **Tex. Transp. Code §681.011** is: no priors **\$500–\$750** · one prior \$550–\$800 + 10 hrs · two priors \$550–\$800 + 20 hrs · three priors \$800–\$1,100 + 30 hrs · four or more **\$1,250 + 50 hrs**.

The enforcement trap — §681.011(f-2)

"A peace officer may issue a warning but **may not issue a citation** for an offense" where the designated space lacks a parking space identification sign complying with the standards referred to in §681.009(b).

Because §681.009(b) points at TAS, **a parking sign that misses TAS 502.6 makes the space legally unenforceable** — police can only warn, not ticket. Getting TAS 502.6 right is an operational necessity, not a code checkbox.

Safe to build as drawn

No redesign needed. Where CBC is stricter, a CBC-compliant sign is automatically TAS-compliant, so the fabrication package can be reused as-is.

Identical: room ID scoping (216.2) · raised character depth, case, style, proportion, height, stroke, spacing (703.2.1–.8) · Grade 2 Braille dot geometry and Table 703.3.1 (703.3.1) · tactile sign location incl. 18"×18" clear space (703.4.2) · visual character finish, contrast, non-glare, Table 703.5.5 (703.5) · pictograms (703.6) · ISA, TTY, volume-control and assistive-listening symbols (703.7.2.1–.4) · tactile exit scoping (216.4.1) · accessible entrance ISA (216.6) · elevator jamb designations (407.2.3.1) · assistive listening signage (216.10) · "van accessible" + 60" min parking sign (502.6).

CBC stricter, therefore safe: Braille flush-left/centered with ½" max separation · 48" measured to lowest Braille cell · blue/white ISA · reflectorized 70 sq in sign.

Process — what happens at TDLR / RAS review

The project is governed by the **Texas Architectural Barriers Act, Tex. Gov't Code Ch. 469**, administered by TDLR. A 115-key hotel is far above the **\$50,000** threshold, so it **must** be registered with TDLR, plans **must** go to a Registered Accessibility Specialist for review per **16 TAC §68.50**, and the completed building **must** be inspected by a RAS, no later than **one year after the recorded completion date**. The **owner** — not the architect, not the GC — is legally responsible under §469.101/ §469.105.

A RAS reviews and inspects against the 2012 TAS. Full stop. CBC 11B has no legal standing in Texas; an RAS will not open it. Compliance with CBC is neither a defense nor a substitute. A sheet citing "CBC 11B" as the governing standard signals that the design team applied the wrong code to the whole project — which invites a line-by-line review instead of the routine pass a clean submittal gets, and is exactly the finding that gets pulled in a later Title III claim.

Would be cited: missing/non-compliant tactile room ID at restrooms (216.2, 703.1/.2/.5) · sign on the door leaf instead of the latch wall, or without 18"×18" clear space (703.4.2) — *the most common real-world write-up* · mounting height outside 48"–60" measured to the Texas datum (703.4.1) · parking sign bottom below 60" (502.6) · missing "van accessible" (502.6) · missing tactile signs at exit passageway/discharge/stairway doors (216.4.1) · Braille not contracted Grade 2 or dots not domed (703.3) · missing ISA or directional signage (216.6, 216.3).

Would NOT be cited: absence of geometric symbols (not a TAS requirement) · presence of them (permitted) · "Minimum Fine \$250" signs (outside TAS scope — a liability problem, not a TAS problem) · missing §2308.301 tow signs (outside TAS scope entirely; will not block the TDLR file, but leaves the hotel unable to tow).

Recommended sheet corrections before the TDLR submittal

1. **G001** — add the governing standard: *"2012 Texas Accessibility Standards (TAS), Texas Government Code Chapter 469, administered by TDLR."* Add the IBC edition the City of Eagle Pass has adopted.
2. **G400 / G401** — strike every "CBC 11B" reference; renumber all cited sections to their TAS equivalents. Retitle G401 *"Accessibility — Signage Standards (2012 TAS)."*
3. **G401** — delete the eleven California-only items; add the §2308.301 entrance tow sign detail with the 24-hour phone number; correct the fine figure if a deterrent sign stays.
4. **Sign schedule** — confirm a discrete latch-side tactile + Grade 2 Braille sign exists at **every** public restroom and **every** guest room, independent of any door symbol.
5. Engage the RAS **before** the drawings go to permit. A pre-submittal RAS review is far cheaper than field rework across 115 keys.

Sources

- [2012 TAS — complete PDF \(TDLR, official\)](#)⁵¹
- [2012 TAS Ch. 2 — Scoping](#)²⁹ · [Ch. 7 — Communication Elements](#)³²
- [1994 TAS — complete PDF](#)⁵² · [1994 TAS §4.30 Signage](#)³⁴
- [TDLR — Elimination of Architectural Barriers at a Glance](#)⁵³
- [CBC 11B-703.7.2.6 geometric symbols](#)⁵⁴ · [11B-216.8.1](#)⁵⁵ · [11B-216.8.2](#)⁵⁶
- [CBC 11B-502.6 Identification](#)⁵⁷ · [11B-502.8 Additional Signs](#)⁵⁸
- [CBC 11B-703.4 Height and Location](#)⁵⁹ · [11B-703.3 Braille](#)⁶⁰
- [CBC Section 1013 Exit Signs](#)⁶¹
- [Tex. Transp. Code §681.009](#)⁶² · [§681.011](#)⁶³
- [Tex. Occ. Code §2308.301 — tow sign](#)³⁷
- [IBC 1009.3.3 Area of Refuge](#)⁶⁴
- [TxDOT — TDLR RAS Program](#)⁶⁵

SECTION 5

Pool and spa signage

Source file: research/signage/POOL-SIGNAGE.md

Texas state rules. Researched 2026-08-20. **The sign wording and letter heights in §2 and §4 below were extracted directly from DSHS's own published sign-requirements PDF, not paraphrased from a secondary source.** City of Eagle Pass local rules are in the city file; under 25 TAC §265.181(g) local authorities may adopt standards **equal to or more stringent** than the state rule, so local review can only add.

1. Threshold findings — these drive everything else

Question	Finding	Basis
Is it a "public pool"?	Yes — Texas "public pool" includes hotel pools regardless of fee	25 TAC §265.182(51)
Class	CLASS C — "operated for and in conjunction with lodging, such as hotels, motels..."	§265.182(51) (C)(i)
Lifeguard required?	No. Class C is not on the mandatory-lifeguard list	§265.191(a) (1)–(5)
 Class-creep trap	If the hotel ever sells day passes or opens the pool to the public , it must meet Class B operational and lifeguard standards while open — two lifeguards . Same trap if a youth group, youth camp, childcare group or visiting school group swims.	§265.194(a); §265.191(a)
Does HSC Ch. 757 (Pool Yard Enclosures) apply?	No. §757.001 defines "multiunit rental complex" and expressly excludes "a facility primarily renting rooms to overnight guests." Hotels are carved out. Enclosure is governed by 25 TAC §265.192(d) instead.	HSC §757.001–.002
Governing version	25 TAC Ch. 265 Subch. L as amended eff. 5/2/2024.  Section numbers moved twice — see §7	49 TexReg 2695
Design code adopted by reference	2021 ISPSC Chs. 2–6 + §102, except §412.2, §508.3, §603.3 ; plus ANSI/APSP-16 and ANSI/PHTA/ICC-7	§265.181(b)–(d)
Enforcement	DSHS or the local regulatory authority	§265.181(g), §265.197

2. Required pool signs — verbatim, with letter heights

All of these are one figure. **Multiple signs may be used or the messages combined on one sign.** All must be **in the pool yard, securely mounted, readily visible to the pool user.**

#	Required text (VERBATIM — reproduce exactly)	Letter height
1	WARNING-NO LIFEGUARD ON DUTY (where no lifeguard required or provided) — note the hyphen with no spaces	4 inches
2	NO DIVING + the International no diving symbol (where no lifeguard required or provided)	4 inches
3	IN CASE OF EMERGENCY, DIAL 911	4 inches

#	Required text (VERBATIM — reproduce exactly)	Letter height
4	Precise location of the pool, on or with the emergency phone (address, directions, GPS location, or building number as appropriate)	Minimum 1 inch
5	Hours of operation	Minimum 1 inch
6	Directions to and location of the emergency phone — only if the phone is not visible in the pool yard	Minimum 2 inches
7	Maximum user load limit (<i>computed — see §6</i>)	Minimum 2 inches
8	PETS IN THE POOL ARE PROHIBITED	Minimum 2 inches
9	DO NOT SWIM IF YOU HAVE BEEN ILL WITH DIARRHEA WITHIN THE PAST 2 WEEKS	Minimum 2 inches
10	CHANGING DIAPERS WITHIN 6 FEET OF THE POOL IS PROHIBITED	Minimum 2 inches
11	GLASS ITEMS NOT ALLOWED IN THE POOL YARD	Minimum 2 inches
12	PERSONS UNDER THE AGE OF 14 MUST NOT BE IN THE POOL WITHOUT ADULT SUPERVISION	Minimum 2 inches
13	EXTENDED BREATH HOLDING ACTIVITIES ARE DANGEROUS AND PROHIBITED	Minimum 2 inches
14	Location of drinking water — only if drinking water is not in the pool yard	Minimum 1 inch

Panel rules to hand the sign vendor, verbatim:

"Signs shall be in the pool yard, securely mounted as applicable, and readily visible to the pool user." · "Sign panels shall be durable for the weather conditions. The message surface shall be clean and smooth and shall readily accept paint or precut lettering adhesives." · **"Theming or artwork applied to signs shall not invade the message panel. Signs shall have a distinct border."** · "Multiple signs may be used, or the messages may be combined on one sign."

⚠ Substitute wording needs pre-approval. Variations are allowed **only** if "*substantially equivalent*" and local regulatory officials **approve the variation before the sign is posted**. If the vendor proposes anything other than the strings above, get that approval in writing first — a stock "Texas pool sign" off a catalog is not automatically compliant.

Spanish is permitted, not required. "*In areas of Texas where the majority of citizens are non-English speaking, in addition to signs in English, signs and other written warnings or information required by these standards may be posted in the predominant language.*" Eagle Pass is a majority Spanish-speaking community — **bilingual signage is recommended as a risk measure**; confirm whether the City requires it.

Also required if the emergency device is present: a sign **directly above** it giving the precise location of the pool (address, building number, GPS), minimum **1 inch**.

3. Depth markers and NO DIVING — the TL-12 tile scope

⚠ This is the section that must be dimensionally correct, because on this project the depth markers are specified as TILE — tag TL-12 on ID-1.8 — not as applied signage. Two rule sets stack (25 TAC §265.190(b)–(c) and ISPSC 2021 §409); comply with the more stringent of each.

Requirement	Spec
Quantity	Not fewer than two per pool , regardless of size or shape
Character height	No less than 4 inches , numbers and letters
Color	Permanent , in a color contrasting the background of the deck and the vertical wall
Wall placement	In the top 4½ inches of the pool wall just under the coping , positioned to be read by a user while in the pool
Deck placement	Slip-resistant , readable while standing on the deck ; ISPSC adds within 18 inches of the water edge , facing the water
Spacing	Uniformly around the perimeter at intervals of no more than 25 feet ; ISPSC adds: at maximum and minimum depths , at all points of slope change , and at depth increments not exceeding 2 feet , uniformly distributed on all sides and ends
Units	Must spell out "feet"/"inches" or abbreviate "FT," "IN," or fractions of a foot
Accuracy	Within ± 3 inches of actual depth at normal operating level (ISPSC §409.2)

NO DIVING on the deck: required **where pool depth is 5 feet or less**, at intervals **not greater than 25 feet** and **directly adjacent to a depth marker**. Symbol is *"a diver's profile in a circle with a 45-degree slash through the diver"*; marker **and** symbol **not less than 4 inches high**, permanent contrasting color, slip-resistant, within 18" of the water's edge, read standing on the deck facing the water.

⚠ The waterline tile band does not satisfy it. *"The no diving marker and symbol is not required on the interior tile line of a pool or in a spa"* — it is a **deck** marking. Also required on **any permanent structure above the deck within 5 ft of the water surface** (exempt: diving boards/platforms, **ADA-compliant chair lifts**, slide flumes, lifeguard stands, bridges).

Transition-line tile: only if the pool **exceeds 5 ft deep** — then a **4-inch minimum width row of floor tile** in a color contrasting the pool bottom at the shallow-to-deep transition.

For the tile shop drawing: if the pool is ≤5'-0" throughout (typical Home2 prototype), TL-12 must deliver 4-inch numerals with spelled or abbreviated units, on the wall in the top 4½" under the coping **and** on the deck within 18" of the water's edge, contrasting and permanent, slip-resistant on the deck, at ≤25 ft spacing plus every slope change and every 2 ft of depth change — **with a 4-inch NO DIVING word-mark and slashed-diver symbol on the deck adjacent to every depth marker**. No transition-line tile needed.

4. Spa — conditional, and the brief's assumptions were wrong

No spa, hot tub or whirlpool appears anywhere in the project dataset — not in the room map, finish schedule or item table. **Confirm against AS104; if there is no spa this section drops out entirely.**

If there is one, required signs **inside the spa enclosure** (verbatim from DSHS):

Required text	Letter height
WARNING – NO LIFEGUARD ON DUTY (if no lifeguard provided or required) — note the spa version uses an en dash with spaces , unlike the pool version	4 inches
DO NOT USE THE SPA IF THE WATER TEMPERATURE IS ABOVE 104 DEGREES FAHRENHEIT	Minimum 1 inch
Maximum user load	Minimum 1 inch
Location of the nearest emergency phone or device	Minimum 2 inches
EMERGENCY SPA SHUTOFF	Minimum 2 inches
DO NOT SWIM IF YOU HAVE BEEN ILL WITH DIARRHEA WITHIN THE PAST 2 WEEKS	Minimum 2 inches
PERSONS UNDER THE AGE OF 14 MUST NOT BE IN THE SPA WITHOUT ADULT SUPERVISION	Minimum 2 inches
PETS IN THE SPA ARE PROHIBITED	Minimum 2 inches

The emergency shutoff switch itself must be **accessible to users, within sight of the spa, not less than 5 ft and not more than 10 ft from the inside spa walls.**

⚠ **Correction — three spa warnings we assumed are not Texas requirements**

The brief asked for elderly/pregnancy/heart-disease/diabetes/blood-pressure warnings, a **15-minute limit**, and **"no unsupervised children under 5."** None of those are Texas requirements.

- Texas uses **"PERSONS UNDER THE AGE OF 14"** — do not post "under 5."
- There is **no 15-minute time-limit sign** and **no medical-conditions sign** in the Texas figure or in ISPSC §508.2.
- Those come from other states' codes, ANSI/APSP-11, and spa-manufacturer literature. They are **permitted extras** — but crowding them onto a required panel risks violating the *"theming or artwork must not invade the message panel"* rule. **Put extras on a separate panel.**

5. Enclosure, gates, and the chemical room

Item	Requirement
Enclosure height	Minimum 48 inches , measured from ground on the outside
Openings	Nothing that passes a 4-inch diameter sphere
Climbability	No horizontal mid-rail ; on a 48" fence, horizontal members at least 45 inches apart . Chain link is prohibited for Class C
Clear zone	No planters, light poles, structures or site furnishings within 36 inches horizontally outside the enclosure; tree limbs trimmed
Gates	Self-closing and self-latching , opening outward away from the pool, lockable, locked when closed
Gate latch height	Hardware at least 3½ ft (42 in) above the deck , or on the pool-yard side at least 3 inches below the top of the gate; no opening greater than ½ inch within 18 inches of the latch (including the gate-to-post gap)

Item	Requirement
Propping	No gate may be propped open unless an employee or contractor is present doing work that reasonably requires it
Pool-closed sign	Required at entry gates when the pool is closed

⚠ The gate latch has a 6-inch compliant window on this project

25 TAC §265.192(d)(3)(A) sets a **42-inch minimum** latch height. **AS104 keyed note 37** — already carried in the project data at **HIGH** reliability — requires **"Maximum 48" AFF to any operable part at the pool"** (the ADA reach range).

So the latch must land between 42" and 48" AFF. Many self-latching pool gate latches default to a top-of-gate mount that overshoots 48". **Verify the specified gate hardware set achieves both before it is ordered.**

⚠ The pool building may not be able to open both ways

Per §265.192(d)(1)(F), if a room forms part of the pool yard enclosure, its door may open into the pool yard **only if that same room has no door or gate opening to the outside of the enclosure.**

Room 035 Pool Equipment has a D3 pair of doors (A600, HIGH). If a pair opens outward for equipment access **and** another door opens into the pool yard, that is a violation — and a direct route for a child into the pool yard. **Verify on AS104.** (Service gates used only by service personnel are exempt from self-closing/self-latching, but must never be used as user entry and must be kept closed and locked when not in actual use.)

Chemical room — 034 / 035 / 036

Item	Requirement
Unauthorized-entry sign	"A warning sign against unauthorized entry must be posted on the entry door or gate to the pool and spa equipment room, building, or area." ⚠ The rule prescribes neither wording nor letter height. "AUTHORIZED PERSONNEL ONLY" is the conventional compliant text — do not claim a mandated wording. (§265.194(g))
NFPA 704 hazard diamond	IFC §5003.5 requires it at entrances where hazardous materials are stored "in quantities requiring a permit" or at locations designated by the fire code official
NFPA 704 values	Must come from the SDS of the actual products stored , reflecting the most hazardous material present. Bottom quadrant recognizes only OX , W -and SA — calcium hypochlorite is OX ; muriatic acid takes no special symbol. ⚠ "COR" is not a valid NFPA 704 symbol (that is HMIS/DOT)
SDS	"Safety data sheets covering all chemicals for which personnel are responsible must be kept on-site and be readily available." (§265.189(f); also IFC §5003.4)
Container labeling	"All chemical bulk and day tanks must be clearly labeled to indicate the tank's contents" (§265.189(h)); plus IFC §5003.5.1 and OSHA HazCom 29 CFR 1910.1200(f)
Physical storage	Inaccessible to users; dry chemicals off the floor or in waterproof containers in a dry room; protected from flooding or wetting from floors, walls and ceiling; chlorine compounds must NOT be stored with petroleum products; compressed chlorine gas is prohibited in pools built on or after 1/1/2021 (§265.189(e),(i))

⚠ **Honest read on the NFPA 704 diamond:** IFC §5003.5 triggers on permit-quantity thresholds (Table 105.5.22), and a small hotel pool room holding a few drums may fall **below** them — the numeric thresholds could not be retrieved. **But Texas fire marshals routinely require the diamond on pool chemical rooms under the "designated by the fire code official"**

clause, and it is a near-zero-cost item. Install it — and get the specific ratings confirmed in writing by the Eagle Pass Fire Marshal against the actual SDS for the chemicals the pool contractor will stock. Do not let anyone print it from a generic template.

6. Rescue equipment, maximum user load, and things that are NOT required

Rescue equipment (§265.190(f)) — visible and readily accessible from all areas of the pool yard: at least **one ring buoy with throwing rope and one reaching pole per 2,000 sq ft** of pool surface up to 6,000 sq ft, plus one more set per additional 4,000 sq ft or fraction. Ring buoy **USCG-approved, max 24-inch diameter**; rope $\frac{1}{4}$ "– $\frac{3}{8}$ " diameter, length $\geq \frac{2}{3}$ the **maximum width of the pool**. Reaching pole: *"light, strong, non-telescoping, and at least 12 feet long... constructed of fiberglass or other material that does not conduct electricity"* with a **shepherd's crook with blunted ends**.

Emergency summoning device — within **200 feet of the water**, readily accessible and functioning whenever the pool is open; **must not be answered by an on-site office**; must reach 911; clear operating instructions provided.

Maximum user load is posted but the formula lives in **ISPSC Table 403.1**, driven by deck area relative to water surface area:

Deck condition	Shallow area	Deep area
Minimum deck area	15 sq ft/user	20 sq ft/user
Deck $\geq$ water surface area	12 sq ft/user	15 sq ft/user
Deck $\geq 2\times$ water surface area	8 sq ft/user	10 sq ft/user

Action: have the pool designer state the computed load on AS104. **A generous patio (ZONE-B) can move the pool into the 8/10 column and materially raise the posted number.**

Do not over-build — these are NOT Texas requirements

Asked about	Status
"NO RUNNING"	Not required — not in the figure
"SHOWER BEFORE ENTERING"	Not required — a Model Aquatic Health Code <i>recommendation</i> only
"NO FOOD OR DRINK"	No sign required. §265.194(p) prohibits consumption in the pool and (q) bans glass in the pool yard — only the glass message is a required sign
"No swimming under the influence"	Not required
Spa medical warnings / 15-minute limit / "under 5"	Not required — see §4
First aid kit, AED, backboard at the pool	Not required at an unguarded Class C pool — §265.191(k) is lifeguard-scoped
Pool lift sign	Not required by ADA §242/§1009 — no signage provision exists
CPO certificate posted	Not required to be posted. A certified operator is required, but need not be on-site; name and contact must be <i>"made available"</i> — the rule never says "posted"
State pool permit posted	No state permit exists. Check local

Asked about	Status
VGBA signage	None. VGBA is a product-marking law — drain covers must meet ANSI/APSP-16 and carry its permanent markings including flow rating in GPM . Documentation kept on-site, not posted (§265.194(e))

ADA: pool wall < 300 linear feet → one accessible means of entry, which must be a **pool lift or sloped entry**. "A pool lift must remain in place and be operational during all times that the pool is open" — **storage-and-retrieval-on-request is prohibited**, which supports the fixed lift on this project.

7. ⚠ Section numbering moved twice — cite carefully

Topic	Current (eff. 5/2/2024)	1/1/2023	1/1/2021
Pool safety sign figure	§265.190(e)(5)	§265.190(f)(5)	§265.201(j)(5)
Spa safety sign figure	§265.190(g)(1)	§265.190(h)(4)	§265.208(e)
Depth markers	§265.190(b)	§265.190(b)–(c)	§265.201
Deck NO DIVING	§265.190(c)	§265.190(d)	§265.201
Rescue equipment	§265.190(f)	§265.190(g)	—

DSHS's own hosted PDFs are out of date on numbering — the rule PDF is the 1/1/2023 text and the sign handout is the 1/1/2021 text (it is the handout the wording in §2 and §4 was extracted from). **Their substantive sign wording and letter heights are unchanged and reliable.** The 5/2/2024 amendment's only substantive change was clarifying that the "under 14" sign applies where a lifeguard is **not** required or provided — which on this project means **it is required**. Expect an inspector to be working from the 2023 checklist numbering.

8. Project-specific actions

1. **Confirm actual pool depths from AS104.** Everything in §3 branches on the 5'-0" line.
2. **Verify the gate latch lands between 42" and 48" AFF (§5)** before hardware is ordered.
3. **Verify room 035's doors** against the enclosure rule (§5).
4. **Resolve the TL-12 scope split.** The tag is FLAGGED in the project data — ID-1.8 prints TL-12 while the finish schedule carries "T-12 Depth Marker Tile, Pool," and the pool building is **design-build by others (Div 13 1113)**, with **whose scope the waterline and depth-marker tile falls in unconfirmed**. The dimensional requirements in §3 must appear on **someone's** shop drawing.
5. **Confirm whether a spa exists.** None appears in the dataset.
6. **Get the max user load computed and stated on AS104.**
7. **Get NFPA 704 ratings confirmed in writing by the Fire Marshal** against the real SDS.
8. **Recommend bilingual signage;** confirm whether the City requires it.

Sources

[DSHS — Sign Requirements for Public Swimming Pools and Spas⁶⁶](#) (*wording in §2 and §4 extracted directly from this PDF*) · [25 TAC Ch. 265 Subch. L — full rule PDF⁶⁷](#) · [25 TAC §265.190 — Cornell LII \(current\)⁶⁸](#) · [DSHS 2023 Pool/Spa inspection checklist \(EH-12\)⁶⁹](#) · [ISPSC 2021 Ch. 4⁷⁰](#) · [ISPSC 2021 Ch. 5⁷¹](#) · [HSC §757.001⁷²](#) · [HSC §341.0645⁷³](#) · [IFC 2021 Ch. 50⁷⁴](#) · [ADA.gov — pool accessibility Q&A⁷⁵](#) · [CPSC — pool and spa drain covers⁷⁶](#)

SECTION 6

Texas statutory posted notices

Source file: research/signage/TEXAS-STATUTORY-NOTICES.md

Everything the State of Texas (and the federal government) makes a 115-key hotel post that is **not** fire code, **not** ADA, and **not** pool rules — those live in sibling files. Researched 2026-08-20 against statute and rule text.

Jurisdictional facts established:

- H2SEP is a "commercial lodging establishment" under Tex. Bus. & Com. Code §114.0001(1) (a hotel offering **more than 10 rooms**) → **Chapter 114 applies**.
- Food service is permitted and inspected by the **City of Eagle Pass Health Unit** (Community Development Dept., 3295 Bob Rogers Dr., **(830) 773-7781**) — **not DSHS**. The City adopts the Texas Food Establishment Rules (25 TAC Ch. 228).
- Texas has **no** statewide indoor smoking ban. **Eagle Pass does** have a comprehensive smoke-free ordinance (≈2010) — section number and signage spec **unverified**.

Five more premises that were wrong

Assumed	Actual
Human trafficking signage runs through Gov't Code §402.0351	Hotels are not on that list. The duty is Tex. Bus. & Com. Code Ch. 114 (HB 390, 87th Leg., eff. 1/1/2022). §402.035 is just the Task Force — no signage duty.
Innkeeper valuables notice is in Civil Practice & Remedies Ch. 137	No such provision exists. It is Tex. Occ. Code §2155.052 , and a printed copy of the statute goes on the door of each guest's sleeping room .
The hotel firearms law is HB 302 (2019)	It is SB 20, 87th Leg. (2021) → Tex. Occ. Code §2155.1025 .
A choking/Heimlich poster is required	Not by state law. Removed from the TFER pre-2015; zero hits for "chok" or "Heimlich" in current 25 TAC Ch. 228. Only a first aid kit is required (§228.211). Verify the City ordinance.
Texas requires CO alarms in hotel guest rooms	It does not. H&S Code Ch. 766 is public-awareness only. (The adopted IFC and Hilton standards may still require them.)

A. Human trafficking — mandatory, employee-facing

Verified against the rule text. 1 TAC §54.103, "Human Trafficking Prevention Signs for Commercial Lodging Establishments."

Spec	Requirement
Size	At least 11" × 17"
Font	At least 16-point
Language s	Posted separately in English, Spanish, and any other primary language spoken by ≥10% of employees
Location	"In a location that is easily visible to all employees" — back of house: break room, time clock, employee entrance. Not a guest-facing sign.

Content must contain all four: (1) a statement that employees are required to receive annual human-trafficking training and **may not be disciplined, retaliated against, or discriminated against for a good-faith report**; (2) how to recognize and report trafficking, **including a list of indicators**; (3) the reporting phone number; (4) DPS suspicious-activity contact.

⚠️ Trap: the OAG's 8.5"×11" PDFs are **two pages meant to be taped together to make 11"×17"**. An 8.5"×11" sign alone **does not meet the statutory minimum**.

Paired duty (no sign, but the sign asserts it): every directly-employed employee must complete **OAG-approved** training **annually, ≥20 minutes**, new hires **within 90 days**. Records retained **≥2 years** and produced to the OAG **within 72 hours** of request (§§114.0051–114.0052, 1 TAC §54.101).

Enforcement: peace officers may enter 9–5 M–F to check. AG gives written notice + **30-day cure**, then **up to \$500 per violation, each day a separate violation** (§§114.0101–114.0103).

Downloads: [EN 11×17⁷⁷](#) · [ES 11×17⁷⁸](#) · [OAG lodging resources⁷⁹](#)

B. Innkeeper notices — in the guest rooms

#	Notice	Where	Requirement	Citation
1	Daily room-rate card or sign	A conspicuous place in EACH of the 115 guest rooms	Must state the daily room rate and the date the card was posted . A rate increase is not effective until the 30th day after a card showing it is posted — so post the maximum/sell-out rate. No prescribed wording. Misdemeanor, \$25–\$100 and/or up to 30 days.	Tex. Occ. Code §2155.001(a), (b) ; penalty §2155.002
2	Room-rate ticket to the guest	Handed over at check-in	Hotels with 20+ rooms must give the guest a ticket showing the daily rate charged, conforming to the posted rate. Fine up to \$100.	§2155.001(c) ; penalty §2155.002(b),(e)
3	Limited-liability-for-valuables notice	On the door of each guest's sleeping room — the statute says "on the door"	A printed copy of §2155.052 itself . Posting is what caps liability at \$50 . Conditions: the hotel continuously maintains a metal safe/vault in good order, and keeps suitable locks/bolts on guest room doors and proper fastenings on transoms and windows. Cap is lost if a guest offered valuables for the safe and the hotel failed to deposit them and issue a receipt.	§2155.052(b)(3)

Item 3 is technically conditional — not posting simply forfeits the cap — but **on 115 keys that is a real exposure, so treat it as mandatory**. THLA's model heading is "**LIMITED LIABILITY LAW.**"

C. Firearms — optional signs, mandatory constraint

⚠️ Read this before posting anything. Tex. Occ. Code **§2155.1025** (SB 20, 87th Leg., eff. 9/1/2021): a hotel **may not** adopt a policy prohibiting a guest from —

- carrying or storing a firearm or ammunition **in the guest's room**;
- carrying it **directly en route to or from** the hotel or the room;
- carrying it **directly en route to or from the guest's vehicle** on hotel property, including guest parking;
- carrying or storing it **in the guest's vehicle** on hotel property.

A hotel **may** require that in **common areas** a handgun be carried **concealed**, or that a firearm be carried **in a case or bag**.

Consequence: a §30.06/§30.07 sign at a hotel **cannot lawfully bar a guest** from any of the above. Such signs are effective only as to non-guests, and only in common areas within §2155.1025(b)'s limits. **Posting them without a written policy that carves out guests creates legal exposure** — and triggers the **§2155.103** duty to publish the firearms policy on the reservation website and in written booking confirmations (misdemeanor, fine up to \$100).

If the owner still elects to post, the wording is fixed by statute:

§30.06 (concealed): *"Pursuant to Section 30.06, Penal Code (trespass by license holder with a concealed handgun), a person licensed under Subchapter H, Chapter 411, Government Code (handgun licensing law), may not enter this property with a concealed handgun"*

§30.07 (open): *"Pursuant to Section 30.07, Penal Code (trespass by license holder with an openly carried handgun), a person licensed under Subchapter H, Chapter 411, Government Code (handgun licensing law), may not enter this property with a handgun that is carried openly"*

Format, both: English and Spanish · **contrasting colors** · **block letters at least one inch high** · conspicuous and clearly visible to the public · §30.07 additionally **at each entrance**. ⚠ The statute requires Spanish but **does not prescribe the Spanish wording** and there is no official state translation — have counsel approve the translation before fabrication. §30.05 signs (which reach **non-license** holders under permitless carry) have no prescribed wording.

D. Smoking

#	Notice	Where	Requirement	Citation
4	State smoking prohibition notice	In/at the elevator and other §48.01(a-1) spaces	<i>"A reasonably sized notice that smoking is prohibited by state law in such conveyance or public place and that an offense is punishable by a fine not to exceed \$500."</i> Absence of the notice is a defense to prosecution — so posting is what makes it enforceable. The space must also be equipped with facilities for extinguishment . Covers e-cigarettes.	Tex. Penal Code §48.01(a-1), (b),(c)
5	Eagle Pass smoke-free ordinance signage	Likely each entrance	Eagle Pass has a comprehensive 100% smoke-free workplace/enclosed-public-place ordinance (≈2010). Texas comprehensive ordinances typically require "No Smoking" signage with the international symbol at every entrance and removal of ashtrays. Section number and exact spec NOT retrievable — Municode is JavaScript-gated.	UNVERIFIED — call the City Secretary

E. Food service — Breakfast 006 / Servery 009 / Food Prep 007

#	Notice	Where	Requirement	Citation
6	Food establishment permit	Conspicuous, in or on the establishment	City of Eagle Pass permit. Fees \$150–\$250/yr by employee count; \$50 re-inspection.	City Health Unit; H&S Code Ch. 437
7	Certified Food Protection Manager certificate	"Posted in a location conspicuous to consumers" — the breakfast/market area, <i>not</i> the back office	The original certificate. A CFPM must be present during all operating hours.	25 TAC §228.31(a), (b)
8	Employee reporting (symptoms & diagnosis) sign	By ALL handwashing sinks , visible to food employees	Notifies food employees to report symptoms and diagnoses of foodborne-transmissible disease.	25 TAC §228.32

#	Notice	Where	Requirement	Citation
9	Handwashing sign	All handwash sinks used by food employees — prep sinks and employee restrooms	<i>"A SIGN or poster that notifies FOOD EMPLOYEES to wash their hands shall be provided at all HANDWASHING SINKS used by FOOD EMPLOYEES and shall be clearly visible."</i>	25 TAC §228.1(b) adopting FDA Food Code 2017 §6-301.14
10	Food Allergen Awareness Poster	"In an area regularly accessible to food service employees" — back of house	Must cover: risk of allergic reaction · symptoms · the major federal allergens · prevention procedures · appropriate responses. Compliance required since 2024-09-01. Local governments may not exceed this.	Tex. H&S Code §437.027 (SB 812, 88th Leg.)
11	Buffet clean-tableware notice	The self-service breakfast bar	<i>"A card, sign, or other effective means of notification shall be displayed to notify consumers that clean tableware is to be used upon return to self-service areas."</i>	25 TAC §228.63
12	Second-portion sign	Self-service displays allowing seconds	Required by the City's own restaurant-requirements checklist.	City of Eagle Pass Health Unit (local)
13	Consumer advisory (raw/undercooked)	Menu/placard	Only if any raw or undercooked animal food is offered — likely N/A for a Home2 breakfast.	FDA Food Code §3-603.11
14	First aid kit (<i>not a sign, but inspected</i>)	The food establishment	<i>"A first aid kit shall be provided in all food establishments."</i>	25 TAC §228.211
15	"Dogs allowed" sign	Outdoor dining area	Only if dogs are permitted in an outdoor patio dining area.	25 TAC §228.172(1)

Records, not signs: food handler certificates within **30 days of hire**, kept on premises (§228.31(d),(e)); Employee Health Reporting Agreement, Form 1-B.

F. Employee poster board — back of house (Employee Breakroom 014)

#	Poster	Requirement	Citation
16	TWC Unemployment Compensation Act & Payday Law (combined)	Conspicuous, accessible to every employee	Tex. Labor Code Ch. 61; TUCA
17	★ Reporting Workplace Violence	The newest Texas requirement and the one most often missed. DPS contact info for anonymously reporting workplace violence or suspicious activity. English AND Spanish. Applies to every Texas employer with one or more employees. Effective 2024-01-08.	Tex. Labor Code Ch. 104A; 40 TAC §800.600
18	Workers' Comp coverage notice — Notice 6 (covered) or Notice 5 (non-subscriber)	Personnel office and where each employee will regularly see it. Exact prescribed text, no changes. Title ≥26-pt bold, subject ≥18-pt bold, body ≥16-pt normal. English, Spanish, and any other language common to the workforce. Separate written notice to each employee at hire.	28 TAC §110.101
19	OIEC Ombudsman notice	Personnel office and workplace. Exact text, title ≥15-pt bold, body ≥14-pt. English + Spanish + any common language.	28 TAC §276.5
20	EEOC "Know Your Rights"	15+ employees	42 U.S.C. §2000e-10(a); 29 CFR §1601.30

#	Poster	Requirement	Citation
2 1	FLSA minimum wage (WHD 1088)	All establishments	29 CFR §516.4
2 2	OSHA 3165 "Job Safety and Health"	Where notices are customarily posted; must not be altered or covered	29 CFR §1903.2(a)(1)
2 3	Employee Polygraph Protection Act	Prominent, readily observable	29 CFR §801.6
2 4	FMLA (WHD 1420)	Only if 50+ employees within 75 miles	29 CFR §825.300(a)
2 5	USERRA	Where notices are customarily placed	38 U.S.C. §4334
2 6	E-Verify Participation + Right to Work	Only if enrolled	E-Verify MOU

 **#27 — EITC notification is NOT satisfied by posting.** It must be delivered **in person, by email to the last known address, as a payroll staffer, or by first-class mail**, no later than **March 1** each year (Tex. Labor Code §104.002; 40 TAC §815.136).

Not applicable: Texas Hazard Communication Act "Worker Right to Know" and Whistleblower Act notices are **public employers only**.

G. Elevator and boiler certificates — TDLR

Elevator Certificate of Compliance — must be posted in **one** of:

1. Inside the car, **7'0" max / 3'0" min** above the finished car floor; or
2. Outside the car in the **main lobby within 10 feet of the call button**, same heights; or
3. In a common-area lobby/hallway publicly accessible without assistance during all operating hours — **and identified by a directional plaque** mounted in the car or within 10 ft of the main-lobby call button, **font ≥18 points**, stating the equipment is **"Regulated by the Texas Department of Licensing and Regulation"** with **1-800-803-9202** and **building management's telephone number**.

Inspection every **12 months**; Category 5 full-load test every 5 years on traction elevators. (H&S Code §754.019(a)(4); 16 TAC §74.67.) **H2SEP has 2 cabs** — see `PROJECT-FINDINGS.md`.

Boiler / water-heater Certificate of Operation — posted **"in a conspicuous place on or near the boiler"** (Mech./Plumb. Room 030 or Mech. 025). Coverage triggers if heat input **exceeds 200,000 BTU/hr**, water temperature exceeds **210 °F**, or nominal capacity **exceeds 120 gallons**.  **The residential exemption in §755.022(b) does NOT apply to a hotel.** Failure to post is a **Class A violation, \$500–\$3,000 first offense**. (H&S Code §755.029(c), §755.001(9),(12),(18); 16 TAC §65.61.)

Action: pull the DHW submittals — input BTU/hr, storage gallons, setpoint. A commercial plant for 115 keys commonly exceeds these thresholds. **Assume required until the submittals prove otherwise.**

H. TABC — all conditional on alcohol service

If H2SEP holds a TABC permit (evening social / beer & wine): **license displayed publicly** (§11.04, §61.01) · **Complaint Sign**, 8.5"×3.5" black ink (§5.53(d); 16 TAC §31.4) · **Health Risks / pregnancy warning**, English+Spanish 8.5"×11", **at each egress of each restroom** (§11.042, §61.111) · **60-Day Sign** outdoors during application, if applicable (§11.391) · **TABC human trafficking sign**, 11"×8.5", **only if no Food and Beverage Certificate** (§104.07).

The "**51%**" **red sign** (Gov't Code §411.204) requires ≥51% of income from on-premises alcohol and no FB certificate — **almost certainly N/A** for a Home2.

A Food and Beverage Certificate switches off both the 51% sign and the TABC HT sign. Confirm whether the hotel will hold one.

I. Checked and found NOT to require signage

- **Smoke detectors** — Tex. H&S Code Ch. 792 imposes maintenance duties only: a working detector in every sleeping room, and **one hearing-impaired detector per 60 rooms or fraction, max 5**. At 115 keys that is **2**. ⚠️ **Do not confuse this with ADA's 12 communication-features rooms** — different law, different count; **ADA governs as the more stringent**. No signage requirement either way.
- **CO alarms** — not required by Texas law in hotel guest rooms.
- **Hotel occupancy tax** — no state posting requirement found in Tax Code Ch. 156.
- **Linen/towel reuse** — no statewide requirement. Some Texas cities require it via a TCEQ-filed drought contingency plan (30 TAC Ch. 288). **Verify Eagle Pass.**
- **HB 2015 / SB 1831 (88th Leg.)** — checked the enrolled text of both; neither creates any hotel signage requirement.

Open items before CO

Item	Verify	Who
Eagle Pass smoke-free ordinance	Chapter/section, whether guest rooms are covered, signage spec	City Secretary / Code Enforcement
Choking poster	Whether the City food ordinance retains the repealed state rule	Health Unit, (830) 773-7781
Linen/towel reuse	Whether the City water conservation plan has a lodging provision	Utilities / Public Works
Boiler certificate	DHW input BTU/hr, gallons, setpoint vs the three thresholds	TDLR Boiler Program; MEP engineer
Local HOT	Any rate-disclosure posting in the City ordinance	City Finance
Employee languages	Any language other than English/Spanish at ≥10% of employees (HT sign) or "common to the employee population" (workers' comp, OIEC). Eagle Pass is a border market — Spanish is a given; check for others.	HR
Alcohol program	Whether a TABC permit and a Food and Beverage Certificate will be held	Ownership / TABC

Sources

Human trafficking — [1 TAC §54.103](#)⁸⁰ · [1 TAC §54.101](#)⁸¹ · [HB 390 \(87R\) text](#)⁸² · [OAG lodging signs](#)⁷⁹

Innkeeper / firearms — [Occ. Code §2155.001](#)⁸³ · [§2155.052](#)⁸⁴ · [§2155.1025](#)⁸⁵ · [§2155.103](#)⁸⁶ · [Penal Code §30.06](#)⁸⁷ · [§30.07](#)⁸⁸ · [§30.05](#)⁸⁹ · [§48.01 smoking](#)⁹⁰

Food — [TFER 25 TAC Ch. 228 \(2021\)](#)⁹¹ · [SB 812 allergen](#)⁹² · [Allergen poster EN](#)⁹³ · [Handwash poster](#)⁹⁴ · [Eagle Pass food establishment info](#)⁹⁵ · [City general food requirements](#)⁹⁶

Labor — [40 TAC §800.600 workplace violence](#)⁹⁷ · [TWC workplace violence poster](#)⁹⁸ · [TWC posters index](#)⁹⁹ · [28 TAC §110.101](#)¹⁰⁰ · [DWC Notice 6](#)¹⁰¹ · [Notice 5](#)¹⁰² · [28 TAC §276.5](#)¹⁰³ · [OSHA 3165](#)¹⁰⁴ · [EEOC Know Your Rights](#)¹⁰⁵ · [DOL WHD posters](#)¹⁰⁶ · [USERRA](#)¹⁰⁷

Elevator / boiler / TABC — [16 TAC §74.67](#)¹⁰⁸ · [H&S §754.019](#)¹⁰⁹ · [H&S §755.029](#)¹¹⁰ · [§755.001 definitions](#)¹¹¹ · [16 TAC §65.61](#)¹¹² · [TABC sign requirements](#)¹¹³ · [H&S §792.002 smoke detectors](#)¹¹⁴

SECTION 7

City of Eagle Pass

Source file: research/signage/CITY-OF-EAGLE-PASS.md

H2SEP · 3386 E. Main Street, Eagle Pass, TX 78852 (Maverick County). Researched 2026-08-20.

1. The adopted code edition is genuinely contested — both answers are sourced

Source	Says	Verified
Codified ordinance (§§ 8-15, 12-147, 13-32, 21-1)	2015 I-Codes · 2014 NEC	Read directly from the eLaws mirror
City's own current permit forms + Fire Marshal plan review (rev. 06/2025)	2018 ICC · 2017 NEC · 2012 TAS	Extracted from the City's PDFs

Ord. No. 2016-13 (2016-03-22) is the omnibus that moved Eagle Pass from 2012 to 2015 I-Codes. **A successor ordinance adopting the 2018 codes very likely exists but could not be located online — do not guess its number.** Municode serves only an empty shell to automated fetching; the eLaws mirror carries the same codified text but its supplement history ends at Supplement 29 / Ord. 2019-08 (2019-04-02), so anything adopted after April 2019 is invisible in the text available.

Practical resolution: build to **2018** — it is what the Fire Marshal's current plan-review document and the June 2025 permit applications say, and it is the more recent cycle. But **get the adopting ordinance number in writing** before anyone cites an edition formally.

Good news for signage: it barely matters. The provisions that drive sign fabrication — IFC 505.1 address characters, Appendix D fire lane signs, IFC 1013/1023 egress marking — are **identical in the 2015 and 2018 editions**. The conflict matters for other trades, not for the sign package.

The City names the 2012 Texas Accessibility Standards on its own permit application — the standard G401 does not cite. See `CBC-vs-TAS-DELTA.md`.

2. Appendix D is adopted — the fire lane sign spec is law here

This closes the fire package's top open question. **Verified verbatim** from § 13-32(Q):

""Appendix A Board of Appeals is not adopted, Appendix B Fire Flow Requirements for Buildings is adopted, Appendix C Fire Hydrant Locations is not adopted, **Appendix D Fire Apparatus Access Roads is adopted**; Appendix E Hazard Categories is adopted, Appendix F Hazard Ranking is adopted... Appendix I Fire Protection Systems; Non-Compliant Conditions is adopted, **Appendix J Building Information Sign is not adopted**..."*

So:

Item	Status
Fire lane signs — 12 in. wide × 18 in. high, red letters on white reflective, "NO PARKING—FIRE LANE"	Enforceable. IFC D103.6, adopted

Item	Status
Both sides of lanes 20–26 ft wide; one side of lanes >26 and <32 ft	Enforceable. D103.6.1, D103.6.2
Sign spacing interval	⚠️ Appendix D sets none. No Eagle Pass standard published. Ask the Fire Marshal
Curb paint color / stenciled curb lettering	⚠️ No Eagle Pass ordinance found. Red curb + white stencil is a neighboring-jurisdiction convention, not an adopted Eagle Pass standard. Ask
NFPA-704-style "Building Information Sign"	Not required — Appendix J expressly not adopted

Local amendment, stricter than base code (§ 13-32(F)(1)(o)): *"Indicate the location of the building address placard, which shall be **legible from both the street and fire lane.**"* Base IFC 505.1 only requires visibility from the street. **Eagle Pass wants it readable from both.**

⚠️ **Correction to our brief.** We assumed **Tex. Transp. Code § 545.3051** was a fire lane signage statute. It is not — it is *"Removal of Personal Property from Roadway or Right-of-way,"* and imposes **no signage duty on a hotel.** The tow-signage statute is **Tex. Occ. Code Ch. 2308** (see [ADA-TAS-REQUIREMENTS.md](#) §2308.301).

3. ⚠️⚠️ The sign ordinance will not fit a standard Home2 package

Appendix A § 15, "Regulations for placement of signs and billboards" — Ord. No. 06-13 (2006), amended Ord. No. 07-15 (2007). There is **no standalone sign chapter**; signage lives entirely in the zoning appendix, and there is **no separate sign permit form** — it is a checkbox on the Commercial Building Permit Application.

Verified verbatim:

*"Each business establishment shall be allowed to erect and maintain **two (2) permanent type signs** for the advertising of its services or products."*

*"Only **one (1) free-standing sign** located adjacent to a public street will be permitted for each legal lot."*

*"The aggregate (total) area of the signs shall not exceed **two hundred fifty (250) feet per legal lot.** Free standing signs shall not exceed an amount equal to **one and one-half (1.5) square feet for each one (1) linear foot of the lot's frontage** abutting the primary street, except that a **minimum of forty-eight (48) square feet** of sign area is allowed regardless of the lot frontage."*

*"In no event shall any portion of any sign extend to a height of more than **thirty-five (35) feet** above the surface of the ground."*

*"No sign or any part thereof shall be located within **ten (10) feet of any property line**"* — with stricter requirements at intersections.

Rule	Limit	Citation
Permanent signs per establishment	2 (+1 more if the establishment fronts two streets, one per street)	§ 15(h)(1), (1)(A)
Free-standing signs	1 per legal lot	§ 15(h)(3)
Aggregate sign area	250 sq ft per legal lot , all signs combined	§ 15(h)(1)(A)

Rule	Limit	Citation
Free-standing area formula	1.5 sq ft per linear ft of primary-street frontage , min 48 sq ft	§ 15(h)(1)(A)
Double-sided panel	Counts as one sign	§ 15(h)(1)(B)
Max height	35 ft	§ 15(h)(B), (h)(1)(C)
Setback — any property line	10 ft	§ 15(h)(C)
Setback — intersecting street	25 ft	§ 15(h)(C)
Setback — right-of-way lines	15 ft — apply the greater of this and the 10 ft rule	§ 15(h)(1)(D)
Signs in ROW	Prohibited , including overhead projections	§ 15(h)(2)
Canopy / porte-cochère signs	May not extend above the roof line by more than 2 ft	§ 15(b)
Where IBC and § 15 conflict	§ 15 controls	§ 15(j)
Permit fee	\$88.00	Commercial permit application, rev. 06/2025
Penalty	Misdemeanor, up to \$200 , each day a separate offense	§ 15(n)
Appeal	ZBAA within 30 days ; variance only where <i>"the unusual shape or topography of the property prevents signage allowable under this chapter from adequately identifying the business"</i>	§ 15(e)

The collision

A standard Home2 exterior package is **two wall signs + one monument = three**. The ordinance allows **two**. The only relief is the two-street exception or a ZBAA variance — and the variance standard is narrow (unusual shape or topography), not "the brand requires it."

And dropping a brand ID sign needs Hilton's written consent as well as the City's — the Franchise Agreement's definition of "Designs" expressly includes signs, and approved plans cannot change without further written consent. **This is a long-lead approval on two fronts, not a field decision.** See [BRAND-AND-PROJECT-RECORD.md](#).

No digital or animated signage

§ 15(k)(J) bans *"visible moving, revolving, or rotating parts... or other apparent visible movement achieved by electrical, electronic, or mechanical means, **except for time/temperature/date signs.**"* § 15(k)(K) bans lights that *"flash, move, rotate, scintillate, blink, flicker, **vary in intensity or color**, or use intermittent electrical pulsations."*

An LED reader board or EMC is effectively prohibited. "Vary in intensity" is broad enough to reach some dimming schemes — confirm any adaptive-brightness driver with the City.

The permit-exemption ambiguity

§ 15(g)(F) exempts from permit: *"Flat signs of solid-face construction that are placed against and attached to the vertical wall of a building... **may not project beyond the wall to which they are attached**, and must be attached at least ten (10) feet above ground level."* But § 15(h)(A) requires a permit for **all** on-premise signs.

Hilton channel letters are stood off the wall, so they likely do project beyond it and the exemption probably does not apply. Genuinely ambiguous — **get the City's answer in writing.**

⚠ The wind-load table is missing from the code

§ 15(h)(D) requires a **certificate signed by the sign owner** that any sign **6 ft or more above grade** will withstand wind-load pressures *"as set out in the following table."* **That table does not appear in the codified text.** Eagle Pass is a high-wind border region. **Ask what PSF value they enforce and whether a sealed engineer's letter is accepted in place of an owner's certificate.**

4. Other local requirements that touch signage

#	Requirement	Spec	Citation
1	No-smoking signs	<i>"appropriate conspicuously posted signs clearly stating smoking is prohibited"</i> , using international symbols , visible to patrons in or entering. Bold lettering not less than 1 inch high ; international no-smoking symbol. Applies to lobbies, hallways, common areas, public restrooms, service lines, elevators. Failure to maintain = \$50–\$200 fine, each day a separate offense	Ch. 16 § 16-93 , Ord. No. 2010-15
2	Outdoor smoking area	≥10 ft from any entrance, ≥5 ft from a door leading to a patio	§ 16-93(a)(2)
3	Building official	The Planning Director is the building official — sign permits go to Planning, not a separate building department	§ 8-16(A)(4)
4	CO inspection includes signs	The Certificate of Occupancy checklist expressly lists "Signs" as an inspected item	CO Application
5	CO timing	⚠ CO must be applied for coincident with the building permit application , not at the end. <i>"No permit for excavation for any building shall be issued before application has been made for certificate of occupancy"</i>	Apx. A § 18(c), (d)
6	Parking-lot directional arrows	<i>"One-way and two-way accesses into required parking areas shall be identified by directional arrows"</i>	Apx. A § 12.1.C.9(c)
7	Private traffic signs on site	No permit required for <i>"Private signs regulating traffic on the property on which the sign is located"</i>	§ 15(g)(E)
8	Prohibited wording	No sign may use STOP, LOOK, DRIVE-IN, DANGER or anything confusingly similar to a traffic control device	§ 15(k)(E)
9	Egress obstruction	No sign may obstruct any door, window, or fire escape ; none attached to a standpipe or fire escape	§ 15(k)(D)
10	Construction signage	Contractor/architect/developer signs ≤64 sq ft , no permit, may not be erected before site-plan approval , removed within 7 days of completion	§ 15(g)(D)
11	Banners	Require city manager approval ; installed with wires/steel cables	§ 15(g)(G)

#	Requirement	Spec	Citation
1 2	Maintenance	No sign may show <i>"peeling, rust, dirt, fading, discoloration, or holes"</i> ; none may advertise a business no longer in existence	§ 15(k)(B), (k)(C)
1 3	Hotel parking ratio	1 space per room + 1 per 200 sq ft of associated restaurant, retail, conference or office. 115 keys → ≥115 plus F&B/meeting. TDLR record shows 127 provided	Apx. A § 12.1.C.4(g)(iii)
1 4	Extinguishers	One 2A-10BC per 3,000 sq ft , max travel 75 ft , locations and sizes on plans	§ 13-32(F)(1)(n)
1 5	Fire plan sets	Two sets of construction documents to the Fire Marshal	§ 13-32(F)

Item 1 closes an open question from `TEXAS-STATUTORY-NOTICES.md` §D — Eagle Pass's smoke-free ordinance is **Ch. 16 § 16-93 (Ord. 2010-15)** and it does specify signage: **1-inch bold lettering plus the international symbol**, with a per-day penalty.

5. Historic district — probably not, but unverified

Eagle Pass has a historic overlay: **Ch. 8 Art. IX**, Ord. No. 2012-35 (2012-11-06), administered by the **Main Street Advisory Board**. A **Certificate of Appropriateness** is required inside the district for *"any new construction of a principal building or accessory building or structure subject to view from a public way."* The City's permit applications list COA as an "Other Required Inspection (when applicable)."

§ 8-184(d) requires the boundary map to be posted on the city website. It is not there. The Main Street district is the downtown corridor near the international bridge (low Main St. numbers); **3386 E. Main is roughly 3 miles east and very probably outside** — but that could not be verified against the actual map. **A COA requirement would add a design-review body over the Home2 exterior signage package, on top of the City and Hilton.** Confirm with the Main Street Manager before finalizing sign design.

6. TxDOT — on-premise signs need no state permit

Main Street in Eagle Pass carries **Business US 277-N**, a TxDOT route (and TxDOT's own Maverick County Maintenance office is at 2440 Main St.). **Whether the designation reaches the 3386 block could not be confirmed** — BU 277-N is only ~3.2 certified miles.

- **On-premise signs need no TxDOT permit.** *"A permit... is not required to erect an on-premise sign"* — 43 TAC § 21.442. TxDOT's Commercial Signs Regulatory Program regulates **off-premise** outdoor advertising only.
- **Nothing may sit in state ROW** — and § 15(h)(2) independently bars any sign or overhead projection in public ROW. Confirm no monument footing or landscape lighting encroaches.
- A **TxDOT access/driveway permit** is required for any connection to a state-maintained highway.

7. Who to call

Role	Name	Phone	Email
Community Development / Planning — <i>sign permits file here</i>	Planning Dept., 3295 Bob Rogers Dr.	(830) 773-7781	planning@eaglepasstx.gov

Role	Name	Phone	Email
Planning Director (= building official)	Vanesa Rosales-Herrera	(830) 773-7781	via planning@
Planner I	Lizeth Vazquez	(830) 773-7781 ext. 1806	via directory
Fire Marshal	Eleazar Cuevas , 32 Foster Maldonado Blvd.	(830) 773-1915	ecuevas@eaglepasstx.gov
Deputy Fire Marshals	Maire K. Aranda · Robert Bazan · Omar J. Amezcua	(830) 773-1915	via directory
Health Inspector (City runs its own health unit — food permits are City, not County or DSHS)	Oscar Acosta · Ismael Castillo	(830) 773-7781	oacosta@eaglepasstx.gov · icastillo@eaglepasstx.gov
Main Street Manager (Certificate of Appropriateness)	Zenaida Rodriguez	(830) 773-1111	zmoreno@eaglepasstx.gov
Public Works / City Engineering	Daniel Ibarra · A. Vara	(830) 773-9408	daniel.ibarra@eaglepasstx.gov
Eagle Pass Water Works (fire flow)	Mike Sanchez	(830) 773-2351	msanchez@epwaterworks.org
City Secretary (ordinance certification)	Erika Rodriguez, 100 S. Monroe St.	(830) 773-1111	via directory
TxDOT Maverick County Maintenance	Charles Fite, 2440 Main St.	(830) 773-2617	—
TxDOT Area Engineer (Del Rio)	Roberto Moya, P.E.	(830) 703-1422	—
TxDOT Commercial Signs	—	—	csrpt@txdot.gov

Online submittal: SmartGov — <https://ci-eaglepass-tx.smartgovcommunity.com/Public/Home> (At least one City source says complete applications are accepted 8 a.m.–noon Mondays — confirm, since SmartGov now exists.)

Fees: sign permit **\$88** · CO **\$50** · plan check, new commercial **\$193** · base permit **\$30** · non-residential **\$2.00 per \$1,000 of value** · **+1% over \$1M valuation** · building without a permit **double fee, \$200 minimum**.

8. What could not be verified — exact questions to ask

Planning — (830) 773-7781 / planning@eaglepasstx.gov

1. **What ordinance adopted the 2018 I-Codes and 2017 NEC?** The codified §§ 8-15, 12-147, 13-32, 21-1 still say 2015/2014, but your 06/2025 permit forms say 2018/2017. **Send the adopting ordinance PDF.** Which edition governs a permit applied for today?
2. **Is Appendix A § 15 still the operative sign ordinance, or amended since April 2019?**
3. **What is the zoning district of the parcel, and is it inside city limits?** The posted zoning map link ([DocumentCenter/View/1768/City-Zoning-Map](#)) returns **404**.
4. **Is 3386 E. Main inside the Historic Preservation District?** § 8-184(d) requires the boundary map be posted; it is not. **If yes, does exterior signage need a COA, and on what schedule?**
5. **Do flush-mounted internally-illuminated channel letters need a sign permit?** § 15(g)(F) vs § 15(h)(A).
6. **Is the \$88 fee per sign or per application?**
7. **How do you count signs against the two-sign limit?** Does a multi-elevation wall package count as one or several? Does the property qualify as fronting two streets? **If we exceed two signs or 250 sq ft, is a ZBAA variance the only**

path — and what is the fee and hearing calendar?

8. **What wind-load table applies?** § 15(h)(D) references a table that is not in the code. Will you accept a sealed engineer's letter instead of an owner's certificate?
9. **What is the lot's linear frontage on the primary street?** Needed for the 1.5 sq ft/ft free-standing allowance.

Fire Marshal — (830) 773-1915 / ecuevas@eaglepasstx.gov

1. **What fire lane sign SPACING interval do you require?** Appendix D sets size, color, wording and which side — but no interval.
2. **Do you require painted curb striping, and if so what color, stencil wording, letter height and interval?** No ordinance specifies it.
3. **Do you want "TOW AWAY ZONE" on the fire lane signs, or is Occ. Code Ch. 2308 signage handled separately at the drive entrances?**
4. **Exact requirements for the address placard "legible from both the street and fire lane" — character height, stroke, contrast, and must it be illuminated?** How many, and where?
5. **Which IFC edition are you enforcing — 2015 or 2018?**
6. Plus the fire package's remaining items — see [FIRE-MARSHAL-SIGNAGE.md](#) §10.

TxDOT — (830) 773-2617

1. **Is E. Main at the 3386 block state-maintained?** If so, where is the ROW line, and does anything in the sign package encroach?

Not verifiable online at all: the § 15(h)(D) wind-load table · the historic district boundary map · the City zoning map (404) · **any 2019–2026 amendments** (the only reachable full-text mirror stops at 2019-04-02) · whether Eagle Pass adopted a pool code newer than the **Standard Swimming Pool Code, 1994 Edition** (§ 8-61, Ord. 95-12) — if the City is on "2018 ICC" that may pull in the 2018 ISPSC with its own pool signage. (*Texas DSHS rules apply independently — see [POOL-SIGNAGE.md](#).*)

Method note

Municode returns HTTP 403 to automated fetching and serves an empty SPA shell. Every ordinance quotation here comes from the **eLaws mirror at eaglepass.elaws.us** — note it is **HTTP only; the https version times out** — cross-checked against the City's own permit applications and permit guide. Where the two disagree, both are shown rather than one being picked. **No ordinance number, phone number, email or citation here was invented.**

Sources

[Eagle Pass Code — eLaws mirror¹¹⁵](#) · [Supplement history¹¹⁶](#) · [§ 13-32 fire code + appendices¹¹⁷](#) · [Apx. A § 15 signs¹¹⁸](#) · [§ 8-15 building codes¹¹⁹](#) · [§ 8-16 amendments¹²⁰](#) · [§ 8-61 pool code¹²¹](#) · [§ 8-184 historic district¹²²](#) · [§ 12-147 NEC¹²³](#) · [§ 16-93 smoking¹²⁴](#) · [Apx. A § 9.1 B-3¹²⁵](#) · [Apx. A § 12.1 parking¹²⁶](#) · [Apx. A § 18 CO¹²⁷](#) · [Ch. 24 HOT¹²⁸](#) · [Municode \(bot-blocked\)¹²⁹](#) · [Commercial permit application¹³⁰](#) · [Commercial Development Permit Guide 2023¹³¹](#) · [CO application¹³²](#) · [City directory¹³³](#) · [TxDOT Laredo District contacts¹³⁴](#) · [43 TAC § 21.442 on-premise signs¹³⁵](#) · [Tex. Transp. Code § 545.3051¹³⁶](#)

SECTION 8

Brand standards and project record

Source file: `research/signage/BRAND-AND-PROJECT-RECORD.md`

H2SEP · researched 2026-08-20. Companion to `ADA-TAS-REQUIREMENTS.md`, `CBC-vs-TAS-DELTA.md`, `PROJECT-FINDINGS.md`.

1. The project record, verified against the State of Texas

Pulled directly from **TDLR Architectural Barriers project TABS2024001033** — the state's own record, and the first external source in this repo that independently corroborates the room map.

Field	Value (verbatim from TDLR)
Project name	"HOME2 Suites by Hilton Hotel"
Address	"3386 East main Street, Eagle Pass, TX 78852" (<i>sic — lowercase "main"</i>)
Owner	"H2EP LLC", 3301 E. Main Street, Eagle Pass, TX 78852
Architect	"MWT Architect", 3827 Billo Road, Alden, New York 14004
Scope of work	"4 Story, 115 Key HOME2 Suites by Hilton Hotel with pool"
Keys	115
Stories	4
Building area	70,796 ft²
Estimated cost	\$12,000,000
Registered	9/15/2023
Plan review	"Review Complete"
Inspection	Not yet assigned — must be requested within 30 days of completion, no later than the first anniversary
Assigned RAS	Landy Perkins, RAS #371

Three independent confirmations of the spine. The state record's **115 keys** and **4 stories** match `room_map.md` (115/115 verified by blind second extraction) and G100 exactly, and "MWT Architect" confirms the firm the repo's conflict register keeps naming as the RFI recipient. The room map is corroborated from outside the drawing set.

⚠️ What "Review Complete" does and does not mean

The TDLR **plan review is finished**. The **RAS inspection has not happened**. Those check different things:

- **Plan review** looks at drawings. A RAS reviews against TAS regardless of what standard the sheet *cites*, so G401's California citations (`conflicts` A10) would not necessarily fail review as long as the dimensions happen to comply.
- **Inspection** looks at what is physically installed — **mounting heights, latch-side placement, 18"×18" clear floor space, Braille grade and dot geometry**. That is exactly where signage built to G401-as-drawn gets written up.

Plan review passing is not evidence the signage is right. The exposure is entirely downstream, and it lands on the owner: Gov't Code §469.101/§469.105 make the **owner**, not the architect or GC, legally responsible for obtaining the inspection.

Action: get the sign schedule in front of **Landy Perkins (RAS #371)** *before* installation, not after. Signage mounting height and latch-side placement are among the most common RAS punch items, and re-hanging signs across 115 keys plus 55 rooms is pure rework.

2. Accessible parking — now computable

A third-party project abstract lists **127 parking spaces** (not stated on the TDLR record — treat as **MEDIUM** confidence until G001's parking matrix is pulled).

At 127 spaces, **2010 ADA / TAS Table 208.2** (101–150 band) gives:

Item	Count
Accessible spaces required	5
Van spaces ($[5 \div 6]$, §208.2.4)	1
Standard accessible	4
TAS 502.6 ISA identification signs	5
"Van Accessible" designation	1
16 TAC §68.104 "Violators Subject to Fine and Towing" plaques	5
§68.104 pavement ISA (painted, contrasting)	5
§68.104 "NO PARKING" aisle stencil (12" caps, 2" stroke)	one per access aisle
Occ. Code §2308.301 tow sign	one at each driveway/curb cut

⚠️ §208.2 Advisory: the count is computed separately for each parking facility, not off the site total. If the 127 spaces read as two lots, each is calculated independently and the total goes **up**. This is a frequent RAS citation. **Pull G001's parking matrix** (see `PROJECT-FINDINGS.md §1`) before locking the count.

3. Brand standards — what is public, and what to request

Nobody outside the Hilton owner ecosystem can read the Home2 signage standard. What *is* public is **Exhibit H of the 2026 US Home2 Franchise Disclosure Document**, which reproduces the complete **table of contents** of the brand standards manual with real section and page numbers, effective **05 January 2026**. That lets us name the section precisely without inventing its content.

Section	Title	Page
2519.00	SIGNAGE AND GRAPHICS	2500-334
2501.00	EXTERIOR	2500-5
2509.00	CIRCULATION	2500-91

Section	Title	Page
2513.00	BACK-OF-HOUSE	2500-144
2516.00	FIRE PROTECTION AND LIFE SAFETY	2500-291
2517.00	ACCESSIBILITY GUIDELINES	2500-318
726.00	SIGNAGE (operations volume)	700-36
801–803.00	HILTON TRADEMARKS AND LOGOS / BRAND IDENTITY	800-2

None of these sections has been read. We know they exist, their titles and their page ranges. Anyone quoting a requirement "per 2519.00" without the manual in hand is guessing.

Request from the franchisee (H2EP LLC) via the Hilton Owner's Portal → Design Information Site, which MWT and the GC also have access to:

1. **\$2519.00 SIGNAGE AND GRAPHICS** (vol. 2500, p. 2500-334ff) — the single most important document for this scope.
2. \$2501.00 EXTERIOR and \$2509.00 CIRCULATION — prototype plans in these sections usually carry the sign locations.
3. \$726.00 SIGNAGE from the operations volume.
4. **Hilton's current list of licensed exterior sign vendors** for South Texas.
5. **Which of the two design packages was approved** — the sign catalog mirrors them as **"Neutral"** (H2SN-...) and **"Wood."** Every interior SKU is finish-specific and non-interchangeable, so this gates every order.

4. Two procurement rules that constrain the scope

Exterior signage is a closed list. FDD Item 8, verbatim: *"You must purchase exterior signage from a vendor currently licensed by us. You may contact us for a current list in your area."* Interior is open **provided the standards are met**, except anything bearing a Hilton or Home2 mark, which must come from an approved and licensed supplier. Getting a new supplier approved takes **60–90 days**.

Sign changes still need Hilton's written consent. The Franchise Agreement's definition of "Designs" expressly includes **signs**, and approved plans cannot be changed without further written consent. TDLR shows plan review complete, so the design-review gate has been passed — **any sign change now needs Hilton's sign-off, not just the City's**. That matters directly because of the two-sign problem in §6.

5. Budget, from published figures

Line	Amount	Source
FDD Item 7 "Signage"	\$45,800 – \$66,500 (107-suite prototype)	2026 US Home2 FDD
What it covers, verbatim (Note 9)	<i>"Signs include freestanding signs and primary identification for the building. The amount includes installation, freight, foundation and wiring."</i>	FDD Note 9
What it does not cover	Interior wayfinding, ADA, amenity graphics, BOH and regulatory signage — those sit inside FF&E , \$1.91M–\$2.77M	FDD Item 7

Line	Amount	Source
ADA consultant	\$2,500 – \$10,000 (separate line)	FDD Item 7 Note 12

Practical read for 115 keys: roughly **\$50–70k exterior** (brand-licensed vendor, installed) plus **\$35–70k interior**. Catalog unit pricing supports the interior figure — room number plaques $\approx \$38 \times 115 \approx \4.4k , directionals \$29–\$84, pool rules sign \$227, elevator changeable display \$196.

⚠ Note the prototype mismatch: the FDD's cost basis is a **107-suite** Home2 with **7 accessible suites**. H2SEP is **115 keys**. The accessible count coincidentally also lands at 7 (ADA Table 224.2), but **do not carry prototype quantities across** — compute from the actual 115. See `ADA-TAS-REQUIREMENTS.md`.

6. ⚠ Eagle Pass allows two signs. A Home2 package is three.

Eagle Pass Zoning Ordinance, Appendix A §15 (Regulations for placement of signs and billboards): *"Each business establishment shall be allowed to erect and maintain two (2) permanent type signs."* A permit from the Building Department is required with plans and specs, and a **wind-load certificate signed by the sign owner is required for any new sign 6 ft or more above grade**.

A standard Home2 exterior package is **two wall signs + one monument = three**. Something has to give: a variance, or dropping a sign. **And dropping a brand ID sign needs Hilton's written consent as well as the City's** (§4 above). Raise this with both sides now — it is a long-lead approval, not a field decision.

(City rules are covered in depth in the city research file; flagged here because it collides directly with the brand package.)

7. Nomenclature — do not spec retired language

Use	Not
"Home2 Breakfast" (std. 428.00)	~~"Inspired Table"~~ — survives only in Hilton marketing copy and the vendor's retired "H2S" package
"Home2 MKT" (std. 415.00)	—
"Neutral" / "Wood" finish families	~~"Home2 Suites V3"~~ and ~~"H2S"~~ — both explicitly Retired ; must not be used on a new build
Spin2Cycle — one room, but split across 502.00 FITNESS CENTER and 716.00 GUEST LAUNDRY	—

H2SEP's space list matches the current nomenclature: **005 Market, 006 Breakfast, 009 Servery, 023 Fitness Room, 024 Guest Laundry**.

8. Vendors

Vendor	Evidence	Contact	Confidence
HOTELSIGN S.com (Intersign Corp.)	Strongest. Operates a Home2 Suites Sign Store carrying the full current catalog in both finish families, with Hilton part-number conventions (H2SN-... , HH-...), retired-package flagging, and Honors/Diamond/EV SKUs. Displays a "vendor approved" badge.	2156 Amnicola Hwy, Chattanooga TN · 888-273-8726 · emailus@hotelsigns.com	High for interior. Does not publish exterior building ID or monument fabrication.
Identity Group	Hilton-brand product categories confirmed; no Home2-specific catalog visible	800-325-7409 · dailyorders@identitygroup.com	Medium
ADAHotelSigns.com	Sells a Home2 Guarantee Sign (HM2-1917). Claims "approved," does not state formal licensure	800-742-5507 · hiltonbrands@adahotelsgns.com	Medium
Ortwein Sign	Full exterior capability (pylon, monument, channel letters, porte-cochère). No Hilton licensure claim	1-866-867-9208 · sales@ortweinsign.com	Medium capability / Unverified license
Comet Signs	San Antonio — nearest major sign plant to Eagle Pass. No Hilton license claim found	cometsigns.com	Medium logistics / Unverified
National Signs (Aria)	Texas hospitality exterior + interior, handles permitting	713-863-0600	Medium / Unverified
 "Hilton Displays"	NOT affiliated with Hilton Hotels — an independent sign company in Greenville SC	—	Flagged to avoid confusion

Could not substantiate a Hilton or Home2 approval claim for ASI, Best Sign Systems, Cornerstone, Gemini, ImageWorks or Jones Sign. **Do not represent any of them as Hilton-approved without the official list.**

The procurement path that actually works

1. **Get Hilton's licensed exterior vendor list** for South Texas. This is the gating item.
2. **Interior: use HOTELSIGNED's free SignSpec service.** Send the floor plans; they return a sign list with location numbers, a signage location plan and a quote package built against NFPA/ICC/ADA. Free, and it produces the sign schedule the GC needs to coordinate blocking, power and mounting heights — which matters here because **the blocking is already committed and carries an unresolved dimension conflict** (PROJECT-FINDINGS.md §4). Lead time: ships 10–15 business days after order acceptance; individual SKUs 2–4 weeks.
3. **Lock Neutral vs Wood before ordering anything.**
4. **Route any sign change through Hilton, not just the City.**

9. Brand SKUs worth knowing (current catalog, "Neutral" family)

Item	SKU	Size	~Price
Guest room number	H2SN-RN73	7" × 3.625"	\$38
Guest room number w/ no-smoking symbol	H2SN-RN73-SYM	same	\$39
Guest room evacuation map	H2SN-EVP79	7.75" × 9.25"	\$19

Item	SKU	Size	~Price
Elevator changeable display — "Required"	H2SN-MH2114	21.5" × 14.625"	\$196
Elevator door-jamb floor designation	GSS-EDJ32 / EDJ34	3.75" × 2.25" / 4"	\$20 / \$21
"In Case of Fire — Use Stairs"	H2SN-IC0F108 / IFE108	10.375" × 8.5"	\$42
Restroom ID w/ ISA (unisex / women / men)	H2SN-RG62 / RG31 / RG32	7.75" × 6.875"	\$40
Common room ID (BOH workhorse, 2–8 line)	H2SN-CR36 ... CR1011-2	3.75"×6.875" up	\$35–\$133
Custom regulatory sign	H2SN-RGCC / RGCC2	7.75" × 6.875"	\$43 / \$50
Directional (2–8 line)	H2SN-D36 ... D1011	—	\$29–\$84
Accessible-route directional	H2SN-DA96 (-DYN)	9.5" × 6.875"	\$40
Meeting room sign w/ sliding panel	H2SN-MR168	16.5" × 8.5"	\$154
Pool rules w/ hours	H2SN-PR2935	29.5" × 35"	\$227
No Diving / No Lifeguard	H2SN-DV2335	—	\$175
Recreation area emergency telephone	H2SN-G1111eo / -EX	11.875" sq	\$66 / \$31
Fitness Center w/ accent (ext + int rated)	H2SN-FC2925	29.5" × 25.75"	\$187
Hilton Honors front desk block	HH-HC610	6" × 10.5" × 2.75"	\$110

⚠ Choose one ISA style property-wide. Both the standard symbol and the Dynamic/"active" ISA (-DYN) are catalogued. **Specify the standard Figure 703.7.2.1 symbol** — neither the Access Board nor TDLR has adopted the Dynamic icon, and mixing them reads as an error. See [ADA-TAS-REQUIREMENTS.md](#).

10. Open questions for the franchisee and Hilton

Blocking a quote:

1. **Neutral or Wood?** Everything downstream depends on it.
2. **Hilton's licensed exterior vendor list** for South Texas.
3. **\$2519.00 SIGNAGE AND GRAPHICS**, plus 2501.00, 2509.00 and 726.00.
4. **Was the exterior sign package inside the Plans and Designs Hilton already consented to?** If so, that exhibit fixes letter heights, elevations and monument dimensions.
5. **Confirm the final accessible / communication-features key mix at 115.**

Brand scope:

1. **Is a porte-cochère sign required, permitted, or prohibited?** Could not be sourced — the largest unverified exterior item.
2. Is the "Owned & operated under license from Hilton" plaque required at Home2?
3. Written confirmation of **"Home2 Breakfast"** on signage, so nothing is fabricated in retired language.
4. Standard vs Dynamic ISA — one choice, property-wide.

5. Nursing room (717.00)? Premium Experience rooms (317.00)?
6. **Who supplies CleanStay door seals, DND devices and conservation cards** — sign vendor, HSM, or operations?
These routinely fall between scopes.
7. EV charging: how many stalls, which layout from the Diamond/EV family?

Local:

1. **The two-sign limit vs the three-sign package** (§6). Variance or reduction — and Hilton must consent either way.
2. **Wind-load certificate** for the monument and any sign ≥ 6 ft above grade; confirm the exterior vendor will produce sealed calcs for the Maverick County wind zone.
3. **Get the sign schedule to RAS #371 before installation.**

Sources

[TDLR TABS2024001033¹³⁷](#) · [2026 US Home2 FDD¹³⁸](#) · [2025 FDD¹³⁹](#) · [Hilton — Home2 Eagle Pass¹⁴⁰](#) · [EP Business Journal groundbreaking¹⁴¹](#) · [MWT Architect¹⁴²](#) · [HOTELSIGNS Home2 store¹⁴³](#) · [SignSpec¹⁴⁴](#) · [Eagle Pass Code of Ordinances¹⁴⁵](#) · [Dublin OH Home2 Master Sign Plan 17-006¹⁴⁶](#) · [Hilton Owner's Portal — Design Information Site¹⁴⁷](#)

SECTION 9

Sign schedule by space

Source file: research/signage/sign-schedule.md

Generated by `tools/gen_sign_schedule.py` from `data/project.sqlite`. Quantities are counted off the room map spine (115/115 keys verified by blind second extraction), never estimated. Edit the generator, not this file.

69 spaces — 66 from the `spaces` table plus 3 pool-building rooms carried off the A600 door schedule — plus **115 guest rooms** scheduled separately.

Floor	Space	Name	Class	Signs required	Source
1	001	Vestibule	Public / guest-facing	Room ID (tactile+Braille)	spaces table
1	003	Lobby	Public / guest-facing	Room ID (tactile+Braille) · Premises address · Occupant load	spaces table
1	004	Reception	Public / guest-facing	Room ID (tactile+Braille)	spaces table
1	005	Market	Public / guest-facing	Room ID (tactile+Braille)	spaces table
1	006	Breakfast	Public / guest-facing	Room ID (tactile+Braille) · Occupant load	spaces table
1	007	Food Prep	Back-of-house	Room ID (tactile+Braille) · Restricted access · Handwash notice · Food permit · Allergen poster · Choking poster	spaces table
1	008	Dry Storage	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	009	Servery	Public / guest-facing	Room ID (tactile+Braille) · Handwash notice · Occupant load	spaces table
1	010	Work Stations	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	011	Managers Office	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	012	Closet	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	013	Laundry Discharge	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	014	Employee Breakroom	Back-of-house	Room ID (tactile+Braille) · Restricted access · Labor law posters	spaces table
1	015	Laundry	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	016	Dryer Room	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table

Floor	Space	Name	Class	Signs required	Source
1	017	Open Storage	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	018	Meeting Room	Public / guest-facing	Room ID (tactile+Braille) · Occupant load	spaces table
1	019	WOMENS	Public restroom	Room ID (tactile+Braille) · Restroom door symbol · Handwash notice	spaces table
1	020	MEN'S	Public restroom	Room ID (tactile+Braille) · Restroom door symbol · Handwash notice	spaces table
1	021	Engineer	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	022	Sales	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	023	Fitness Room	Public / guest-facing	Room ID (tactile+Braille) · Occupant load	spaces table
1	024	Guest Laundry	Public / guest-facing	Room ID (tactile+Braille)	spaces table
1	025	Mech.	Back-of-house	Room ID (tactile+Braille) · Restricted access · Mechanical room ID	spaces table
1	027	Unisex	Public restroom	Room ID (tactile+Braille) · Restroom door symbol · Handwash notice	spaces table
1	028	Elev. Eq.	Back-of-house	Room ID (tactile+Braille) · Restricted access · Elevator machine room ID	spaces table
1	029	Meeting Rm. Sto.	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	030	Mech. / Plumb. Room	Back-of-house	Room ID (tactile+Braille) · Restricted access · Mechanical room ID	spaces table
1	031	PBX	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	032	Housekeeping	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	033	Electrical	Back-of-house	Room ID (tactile+Braille) · Restricted access · Electrical room ID · Arc-flash label	spaces table
1	034	Pool Storage 2	Back-of-house	Room ID (tactile+Braille) · Restricted access	⚠ A600 door schedule only — no space record
1	035	Pool Equipment	Back-of-house	Room ID (tactile+Braille) · Restricted access · NFPA 704 placard · SDS / chemical hazard	⚠ A600 door schedule only — no space record
1	036	Pool Storage 1	Back-of-house	Room ID (tactile+Braille) · Restricted access	⚠ A600 door schedule only — no space record
1	100	Stair 1	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table

Floor	Space	Name	Class	Signs required	Source
1	121	Guest Corridor	Public / guest-facing	Room ID (tactile+Braille)	spaces table
1	137	Elev. Lobby	Public / guest-facing	Room ID (tactile+Braille)	spaces table
1	139	Ice Machine	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
1	140	Elev.	Elevator / hoistway	Hoistway floor designation · Elevator fire-service	spaces table
1	141	Stair 2	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table
1	ZONE-A	Entry / Porte-Cochere Outdoor Lounge	Exterior zone	<i>(scheduled separately)</i>	spaces table
1	ZONE-B	Pool Deck / Patio	Exterior zone	Occupant load	spaces table
2	200	Stair 1	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table
2	219	Electrical	Back-of-house	Room ID (tactile+Braille) · Restricted access · Electrical room ID · Arc-flash label	spaces table
2	220	Storage	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
2	221	Guest Corridor	Public / guest-facing	Room ID (tactile+Braille)	spaces table
2	235	House Keeping	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
2	237	Elevator Lobby	Public / guest-facing	Room ID (tactile+Braille)	spaces table
2	239	Ice Machine	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
2	240	Elev.	Elevator / hoistway	Hoistway floor designation · Elevator fire-service	spaces table
2	241	Stair 2	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table
3	300	Stair 1	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table
3	319	Electrical	Back-of-house	Room ID (tactile+Braille) · Restricted access · Electrical room ID · Arc-flash label	spaces table
3	320	Storage	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table

Floor	Space	Name	Class	Signs required	Source
3	321	Guest Corridor	Public / guest-facing	Room ID (tactile+Braille)	spaces table
3	335	House Keeping	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
3	337	Elevator Lobby	Public / guest-facing	Room ID (tactile+Braille)	spaces table
3	339	Ice Machine	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
3	340	Elev.	Elevator / hoistway	Hoistway floor designation · Elevator fire-service	spaces table
3	341	Stair 2	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table
4	400	Stair 1	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table
4	419	Electrical	Back-of-house	Room ID (tactile+Braille) · Restricted access · Electrical room ID · Arc-flash label	spaces table
4	420	Storage	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
4	421	Guest Corridor	Public / guest-facing	Room ID (tactile+Braille)	spaces table
4	435	House Keeping	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
4	437	Elevator Lobby	Public / guest-facing	Room ID (tactile+Braille)	spaces table
4	439	Ice Machine	Back-of-house	Room ID (tactile+Braille) · Restricted access	spaces table
4	440	Elev.	Elevator / hoistway	Hoistway floor designation · Elevator fire-service	spaces table
4	441	Stair 2	Exit stair enclosure	Stair identification · Tactile EXIT · Floor level	spaces table

APPENDIX

References

Every source cited in this report, numbered in order of first appearance. Superscript numbers in the text point here.

1 Table 224.2

<https://www.corada.com/documents/2010ADASTStandards/224-2>

2 224.2 + 224.4

<https://up.codes/s/transient-lodging-guest-rooms>

3 Fire Marshal's Office

<https://www.eaglepasstx.gov/171/Fire-Marshall>

4 Building Construction Plan Review

<https://www.eaglepasstx.gov/DocumentCenter/View/144/Construction-Plan-Review-Requirements-PDF>

5 Fire Sprinkler Plan Submittal

<https://www.eaglepasstx.gov/DocumentCenter/View/1224/Fire-Sprinkler-Plan-Submittal>

6 Fire Alarm Plan Submittal

<https://www.eaglepasstx.gov/DocumentCenter/View/1222/Fire-Alarm-Plan-Submittal-Requirements>

7 Commercial Permit Application

<https://www.eaglepasstx.gov/DocumentCenter/View/3359/Building-Permit-Application-Commercial->

8 Residential Permit Application (full code list)

<https://www.eaglepasstx.gov/DocumentCenter/View/1927/Building-Permit-Application-Residential-PDF>

9 Commercial Development Permit Guide 2023

<https://www.eaglepasstx.gov/DocumentCenter/View/2497/Commercial-Development-Permit-Guide-2023>

10 Code of Ordinances Ch. 13

https://library.municode.com/TX/eagle_pass/codes/code_of_ordinances?nodeId=PTIIC00R_CH13FIPRPR

11 2018 IFC (ICC)

<https://codes.iccsafe.org/content/IFC2018>

12 2018 IBC (ICC)

<https://codes.iccsafe.org/content/IBC2018>

13 up.codes IFC-2018

<https://up.codes/viewer/wyoming/ifc-2018>

14 up.codes IBC-2018

<https://up.codes/viewer/wyoming/ibc-2018>

15 Texas State Law Library — Building Codes<https://guides.sll.texas.gov/building-codes/texas>**16 Gov't Code §419.909**<https://codes.findlaw.com/tx/government-code/gov-t-sect-419-909/>**17 H&S Code §792.002**<https://codes.findlaw.com/tx/health-and-safety-code/health-safety-sect-792-002/>**18 TDI/SFMO adopted codes — NFPA 1 & 101 2021, eff. 9/1/2023**<https://www.tdi.texas.gov/fire/fmfsinotices.html>**19 TDI/SFMO rules and statutes**<https://www.tdi.texas.gov/fire/fmfsirules.html>**20 28 TAC Ch. 34**http://txrules.elaws.us/rule/title28_chapter34**21 NFPA 101 §7.10.8.3 "No Exit"**<https://up.codes/s/no-exit>**22 §7.10.8 Special Signs**<https://up.codes/s/special-signs>**23 §28.7.4 Emergency Instructions**<https://up.codes/s/emergency-instructions-for-residents-or-guests>**24 NFPA 13 signage guide**<https://www.sprinklerage.com/here-is-your-sign/>**25 QRFS sprinkler sign guide**<https://blog.qrfs.com/87-complete-guide-to-fire-sprinkler-signs-and-system-marking/>**26 2010 ADA Standards (Access Board)**<https://www.access-board.gov/ada/>**27 2012 TAS complete PDF**<https://www.tdlr.texas.gov/ab/2012TAS/2012tascomplete.pdf>**28 Ch. 1 Definitions**<https://www.tdlr.texas.gov/ab/2012abtas1.htm>**29 Ch. 2 Scoping**<https://www.tdlr.texas.gov/ab/2012abtas2.htm>**30 Ch. 4 Accessible Routes**<https://www.tdlr.texas.gov/ab/2012abtas4.htm>**31 Ch. 5 Site Elements**<https://www.tdlr.texas.gov/ab/2012abtas5.htm>

32 Ch. 7 Communication Elements<https://www.tdlr.texas.gov/ab/2012abtas7.htm>**33 Ch. 8 Special Rooms**<https://www.tdlr.texas.gov/ab/2012abtas8.htm>**34 1994 TAS §4.30**<https://www.tdlr.texas.gov/ab/1994abtas4d.htm>**35 Gov't Code Ch. 469**<https://statutes.capitol.texas.gov/Docs/GV/htm/GV.469.htm>**36 Transp. Code Ch. 681**<https://statutes.capitol.texas.gov/Docs/TN/htm/TN.681.htm>**37 Occ. Code §2308.301**https://texas.public.law/statutes/tex._occ._code_section_2308.301**38 16 TAC §68.104**<https://law.cornell.edu/regulations/texas/16-Tex-Admin-Code-SS-68-104>**39 TDLR AB Laws & Rules**<https://www.tdlr.texas.gov/ab/laws-rules.htm>**40 TDLR AB FAQ**<https://www.tdlr.texas.gov/ab/abfaq.htm>**41 TDLR Fee Schedule**<https://www.tdlr.texas.gov/ab/abfees.htm>**42 TDLR Technical Memoranda**<https://www.tdlr.texas.gov/ab/Techmemos.htm>**43 TDLR rule-change bulletin, eff. 8/1/2020**<https://content.govdelivery.com/accounts/TXGOV/bulletins/298bc79>**44 28 CFR §36.302 (reservations)**<https://www.ecfr.gov/current/title-28/chapter-I/part-36/subpart-C/section-36.302>**45 Access Board Guide Ch. 7: Signs**<https://www.access-board.gov/ada/guides/chapter-7-signs/>**46 Ch. 4: Accessible Means of Egress**<https://www.access-board.gov/ada/guides/chapter-4-accessible-means-of-egress/>**47 IBC 1013.4**<https://up.codes/s/raised-character-and-braille-exit-signs>**48 IBC 1023.9**<https://up.codes/s/stairway-identification-signs>

49 IBC 1009

<https://www.corada.com/documents/2022CBCPG/section-1009-accessible-means-of-egress>

50 IBC 3002.3

<https://up.codes/viewer/phoenix/ibc-2018/chapter/30/elevators-and-conveying-systems>

51 2012 TAS — complete PDF (TDLR, official)

<https://www.tdlr.texas.gov/ab/2012tas/2012tascomplete.pdf>

52 1994 TAS — complete PDF

<https://www.tdlr.texas.gov/ab/tas/tascomplete.pdf>

53 TDLR — Elimination of Architectural Barriers at a Glance

<https://www.tdlr.texas.gov/media/pdf/EAB%20at%20a%20Glance.pdf>

54 CBC 11B-703.7.2.6 geometric symbols

<https://www.corada.com/documents/2019CBCPG/11b-703-7-2-6-toilet-and-bathing-facilities-geometric-symbols>

55 11B-216.8.1

<https://up.codes/s/geometric-symbols>

56 11B-216.8.2

<https://up.codes/s/identification-for-all-gender-multi-user-toilet-facilities>

57 CBC 11B-502.6 Identification

<https://www.corada.com/documents/2019CBCPG/11b-502-6-identification>

58 11B-502.8 Additional Signs

<https://up.codes/s/additional-signs>

59 CBC 11B-703.4 Height and Location

<https://www.corada.com/documents/2019CBCPG/11b-703-4-installation-height-and-location>

60 11B-703.3 Braille

<https://www.corada.com/documents/2019CBCPG/11b-703-3-braille>

61 CBC Section 1013 Exit Signs

<https://www.corada.com/documents/2025CBCPG/section-1013-exit-signs>

62 Tex. Transp. Code §681.009

https://texas.public.law/statutes/tex._transp._code_section_681.009

63 §681.011

https://texas.public.law/statutes/tex._transp._code_section_681.011

64 IBC 1009.3.3 Area of Refuge

<https://codes.iccsafe.org/s/IBC2021P2/chapter-10-means-of-egress/IBC2021P2-Ch10-Sec1009.3.3>

65 TxDOT — TDLR RAS Program

<https://ftp.txdot.gov/pub/txdot/des/pse/preparation/tdlr-ras-program.pdf>

66 DSHS — Sign Requirements for Public Swimming Pools and Spas

https://www.dshs.texas.gov/sites/default/files/poolspa/pdf/Signs_for_Pools_and_Spas_with_Logo_Jan2021.pdf

67 25 TAC Ch. 265 Subch. L — full rule PDF

<https://www.dshs.texas.gov/sites/default/files/poolspa/pdf/25%20TAC%20Chapter%20265%20Subchapter%20L.pdf>

68 25 TAC §265.190 — Cornell LII (current)

<https://www.law.cornell.edu/regulations/texas/25-Tex-Admin-Code-SS-265-190>

69 DSHS 2023 Pool/Spa inspection checklist (EH-12)

https://www.dshs.texas.gov/sites/default/files/poolspa/pdf/2023%20Pool_Spa%20Checklist%20for%20Local%20Health%20Department-%2023SV.pdf

70 ISPSC 2021 Ch. 4

<https://up.codes/viewer/pennsylvania/ispSC-2021/chapter/4/public-swimming-pools>

71 ISPSC 2021 Ch. 5

<https://up.codes/viewer/pennsylvania/ispSC-2021/chapter/5/public-spas-and-public-exercise-spas>

72 HSC §757.001

https://texas.public.law/statutes/tex._health_and_safety_code_section_757.001

73 HSC §341.0645

https://texas.public.law/statutes/tex._health_and_safety_code_section_341.0645

74 IFC 2021 Ch. 50

<https://up.codes/viewer/dallas/ifc-2021/chapter/50/hazardous-materials-general-provisions>

75 ADA.gov — pool accessibility Q&A

<https://www.ada.gov/resources/q&a-accessibility-requirements-pools-public/>

76 CPSC — pool and spa drain covers

<https://www.cpsc.gov/Business--Manufacturing/Business-Education/Business-Guidance/Pool-and-Spa-Drain-Covers>

77 EN 11x17

<https://www.texasattorneygeneral.gov/sites/default/files/files/divisions/human-trafficking/HumanTraffickingHotelSign11x17Color.pdf>

78 ES 11x17

<https://www.texasattorneygeneral.gov/sites/default/files/files/divisions/human-trafficking/HumanTraffickingHotelSign11x17SpanishColor.pdf>

79 OAG lodging resources

<https://www.texasattorneygeneral.gov/human-trafficking-section/human-trafficking-training-and-signage/commercial-lodging-training-resources/signs>

80 1 TAC §54.103

<https://www.law.cornell.edu/regulations/texas/1-Tex-Admin-Code-SS-54-103>

81 1 TAC §54.101

<https://www.law.cornell.edu/regulations/texas/1-Tex-Admin-Code-SS-54-101>

82 HB 390 (87R) text

<https://capitol.texas.gov/tlodocs/87R/billtext/html/HB00390F.htm>

83 Occ. Code §2155.001

<https://law.onecle.com/texas/occupations/2155.001.html>

84 §2155.052

<https://law.onecle.com/texas/occupations/2155.052.html>

85 §2155.1025

https://texas.public.law/statutes/tex._occ._code_section_2155.1025

86 §2155.103

<https://law.onecle.com/texas/occupations/2155.103.html>

87 Penal Code §30.06

https://texas.public.law/statutes/tex._penal_code_section_30.06

88 §30.07

https://texas.public.law/statutes/tex._penal_code_section_30.07

89 §30.05

https://texas.public.law/statutes/tex._penal_code_section_30.05

90 §48.01 smoking

<https://law.onecle.com/texas/penal/48.01.html>

91 TFER 25 TAC Ch. 228 (2021)

https://www.dshs.texas.gov/sites/default/files/foodestablishments/pdf/GuidanceDocs/TFER-2021_TAC-228_August-2021.pdf

92 SB 812 allergen

<https://capitol.texas.gov/tlodocs/88R/billtext/html/SB00812F.htm>

93 Allergen poster EN

https://www.dshs.texas.gov/sites/default/files/foodestablishments/pdf/GuidanceDocs/SB%20812--DHS-Food%20Service%20Employee%20Allergen%20Awareness-SamplePoster_FINAL_20240213.pdf

94 Handwash poster

<https://www.dshs.texas.gov/sites/default/files/foodestablishments/pdf/bwhandwash.pdf>

95 Eagle Pass food establishment info

<https://www.eaglepasstx.gov/332/PUBLIC-HEALTH-FOOD-ESTABLISHMENT-INFORMA>

96 City general food requirements

<https://www.eaglepasstx.gov/DocumentCenter/View/2908/General-Food-Establishment-Requirements>

97 40 TAC §800.600 workplace violence<https://www.law.cornell.edu/regulations/texas/40-Tex-Admin-Code-SS-800-600>**98 TWC workplace violence poster**<https://www.twc.texas.gov/sites/default/files/fdcm/docs/workplace-violence-poster-twc.pdf>**99 TWC posters index**<https://www.twc.texas.gov/programs/unemployment-tax/posters-workplace>**100 28 TAC §110.101**<https://www.law.cornell.edu/regulations/texas/28-Tex-Admin-Code-SS-110-101>**101 DWC Notice 6**<https://www.tdi.texas.gov/forms/dwc/notice6.pdf>**102 Notice 5**<https://www.tdi.texas.gov/forms/dwc/notice5.pdf>**103 28 TAC §276.5**<https://www.law.cornell.edu/regulations/texas/28-Tex-Admin-Code-SS-276-5>**104 OSHA 3165**<https://www.osha.gov/sites/default/files/publications/osha3165.pdf>**105 EEOC Know Your Rights**https://www.eeoc.gov/sites/default/files/2022-10/22-088_EEOC_KnowYourRights_10_20.pdf**106 DOL WHD posters**<https://www.dol.gov/agencies/whd/posters>**107 USERRA**<https://www.dol.gov/sites/dolgov/files/VETS/files/USERRA-Poster.pdf>**108 16 TAC §74.67**<https://www.law.cornell.edu/regulations/texas/16-Tex-Admin-Code-SS-74-67>**109 H&S §754.019**https://texas.public.law/statutes/tex._health_and_safety_code_section_754.019**110 H&S §755.029**https://texas.public.law/statutes/tex._health_and_safety_code_section_755.029**111 §755.001 definitions**https://texas.public.law/statutes/tex._health_and_safety_code_section_755.001**112 16 TAC §65.61**<https://www.law.cornell.edu/regulations/texas/16-Tex-Admin-Code-SS-65-61>**113 TABC sign requirements**<https://www.tabc.texas.gov/texas-alcohol-laws-regulations/sign-requirements/>

114 H&S §792.002 smoke detectorshttps://texas.public.law/statutes/tex._health_and_safety_code_section_792.002**115 Eagle Pass Code — eLaws mirror**<http://eaglepass.elaws.us/code>**116 Supplement history**http://eaglepass.elaws.us/code/coor_suhita**117 § 13-32 fire code + appendices**http://eaglepass.elaws.us/code/coor_ch13_artiii_sec13-32**118 Apx. A § 15 signs**http://eaglepass.elaws.us/code/coor_apxa_sec15**119 § 8-15 building codes**http://eaglepass.elaws.us/code/coor_ch8_artii_sec8-15**120 § 8-16 amendments**http://eaglepass.elaws.us/code/coor_ch8_artii_sec8-16**121 § 8-61 pool code**http://eaglepass.elaws.us/code/coor_ch8_artv_sec8-61**122 § 8-184 historic district**http://eaglepass.elaws.us/code/coor_ch8_artix_sec8-184**123 § 12-147 NEC**http://eaglepass.elaws.us/code/coor_ch12_artvi_sec12-147**124 § 16-93 smoking**http://eaglepass.elaws.us/code/coor_ch16_artiii_sec16-93**125 Apx. A § 9.1 B-3**http://eaglepass.elaws.us/code/coor_apxa_sec9.1**126 Apx. A § 12.1 parking**http://eaglepass.elaws.us/code/coor_apxa_sec12.1**127 Apx. A § 18 CO**http://eaglepass.elaws.us/code/coor_apxa_sec18**128 Ch. 24 HOT**http://eaglepass.elaws.us/code/coor_ch24_artii_sec24-22**129 Municode (bot-blocked)**https://library.municode.com/tx/eagle_pass**130 Commercial permit application**<https://www.eaglepasstx.gov/DocumentCenter/View/3359/>

131 Commercial Development Permit Guide 2023<https://www.eaglepasstx.gov/DocumentCenter/View/2497/>**132 CO application**<https://www.eaglepasstx.gov/DocumentCenter/View/845/>**133 City directory**<https://www.eaglepasstx.gov/directory.aspx?did=8>**134 TxDOT Laredo District contacts**<https://www.txdot.gov/about/districts/laredo-district/laredo-district-contact.html>**135 43 TAC § 21.442 on-premise signs**<https://www.law.cornell.edu/regulations/texas/43-Tex-Admin-Code-SS-21-442>**136 Tex. Transp. Code § 545.3051**https://texas.public.law/statutes/tex._transp._code_section_545.3051**137 TDLR TABS2024001033**<https://www.tdlr.texas.gov/TABS/Search/Print/TABS2024001033>**138 2026 US Home2 FDD**<https://hmd-wp.go-vip.net/wp-content/uploads/2026/03/2026-US-FDD-Home2.pdf>**139 2025 FDD**<https://hmd-wp.go-vip.net/wp-content/uploads/2025/03/2025-US-FDD-Home2.pdf>**140 Hilton — Home2 Eagle Pass**<https://www.hilton.com/en/hotels/eglmtht-home2-suites-eagle-pass/>**141 EP Business Journal groundbreaking**<https://www.epbusinessjournal.com/2024/07/creative-ventures-holds-groundbreaking-ceremony-for-new-home-2-suite-s-by-hilton/>**142 MWT Architect**<https://www.hotelarchitect.com/hilton-architect/>**143 HOTELSIGNS Home2 store**<https://www.hotelsigns.com/home2suites/>**144 SignSpec**<https://www.hotelsigns.com/signspec>**145 Eagle Pass Code of Ordinances**https://library.municode.com/tx/eagle_pass/codes/code_of_ordinances?nodeId=PTIIC00R_APXAZ00R**146 Dublin OH Home2 Master Sign Plan 17-006**<https://dublinohiousa.gov/dev/dev/wp-content/uploads/2017/01/17-006-Master-Sign-Plan-Statement.pdf>

147 Hilton Owner's Portal — Design Information Site

<https://hilton.my.site.com/s/article/Design-Information-Site>
