
## 7 launches with affected O-rings prior to the Challenger



55°

0

25°

30°

35°

40°

45°

50°

Temperature (°F) of field joints at time of launch

65°

70°

75°

85°

80°

60°