

Incident Report INC-2022-014

Incident / Near-miss - Prayag Petro Refinery - Unit 2

Prayag Petro Refinery - Unit 2

Incident ID

INC-2022-014

Date

2021-11-30

Severity

near-miss

Equipment

P-101A

Description

Mechanical seal on feed charge pump P-101A failed releasing a small quantity of hot hydrocarbon onto the baseplate. No ignition. Operators had reported high bearing vibration on P-101A three weeks earlier.