

PESA-EL-11 Electrical Isolation and Lock-Out Guidance

Regulatory standard (synthetic) - PlantCortex demo corpus

SYNTHETIC / representative text prepared for the PlantCortex demo. This is NOT the official published standard text.

Clause 3.2

All electrical energy sources shall be isolated, locked and tagged, and verified at zero energy before work on rotating machinery.

Applicability (demo annotation)

Referenced equipment: P-101A, P-101B, C-501