

SOP-12 Hot Work Permit Procedure (Rev 1)

Standard Operating Procedure - Prayag Petro Refinery - Unit 2

Prayag Petro Refinery - Unit 2

1. Scope

Welding/grinding in Unit 2 process areas

2. Applicable Equipment

E-301, V-201

3. Referenced Standards

OISD-STD-105 clause 6.2

4. Procedure

1. Raise hot work permit per OISD-STD-105 clause 6.2.
2. Post trained fire watch with extinguisher for the job duration.
3. Gas test the area for flammable atmosphere before ignition source use.
4. Cordon area and remove combustibles within 15 m.