

भारतीय राष्ट्रीय राजमार्ग प्राधिकरण

(सड़क परिवहन और राजमार्ग मंत्रालय, भारत सरकार) National Highways Authority of India

(Ministry of Road Transport and Highways, Govt. of India) परियोजना कार्यान्यवयन इकाई, सासाराम ग्राम+पोस्ट- मोरसराय (नियर सत्यम् सर्विस, सेन्टर)

जिला-रोहतास(सासाराम),पिन कोड-821113 (बिहार) Village+Post.- Moresaral,(Near Satyam Service Centre) District.- Rohtas, Sasaram (Bihar),Pin No : 821113 E-mall :- plusasaram@nhal.org nhalsasaram@gmall.com



Date: 20.03.2024

NHAI/PIU-SSM/Soma/2024/ 8965

Team Leader

M/s LN Malviya Infra Project Pvt. SP Jain Collage Road, Sasaram, Sasaram.

Sub: Six laning of Varanasi-Aurangabad Sanction of NH-2 from Km 786.00 to Km978.400 In the state of UP and Bihar on DBFOT (Toll) Basis under NHDP Phase-V- Repairing and Maintenance of damaged road surface on LHS & RHS both near Mohania check post.

Ref: DM, Kaimoor letter no. 702 dated 15.03.2024

Sir,

Please find enclosed herewith the above referred letter on the subject matter, vide which DM Kaimoor has complained about not taking up the repairing & maintenance of damaged road surface on both side of highway near Mohania check post, even after repeated request made by him in the meeting of District Road Safety Committee.

In view of above, it is requested to take necessary action on priority.

(Ashvini Rai)

GM(Tech.)/Project Director

Copy to: Authorized Signatory, M/s SIVATPL, Varanasi.