TI DSP, MCU 및 Xilinx Zynq FPGA 프로그래밍 전문가 과정

강사 - Innova Lee(이상훈)


gcccompil3r@gmail.com


학생 - 문한나


mhn97@naver.com


I2C_Lidar

HCG 설정









ccs 코드

```
#include <HL_hal_stdtypes.h>
#include <HL_i2c.h>
#include <HL_reg_sci.h>
#include <HL_sci.h>
#include <HL_sys_core.h>
#include <stdbool.h>
#include <stdio.h>
#include <string.h>
#define UART sciREG1
#define LIDAR_SLAVE_ADDR 0x62
#define ACQ_COMMAND 0x00
#define STATUS 0x01
#define SIG_COUNT_VAL 0x02
#define ACQ_CONFIG_REG 0x04
#define THRESHOLD BYPASS 0x1C
#define READ_FROM 0x8f
#define FULL_DELAY_HIGH 0x0f
uint8 receives[2];
volatile int g_acc_flag;
uint8 bias_cnt = 0;
void sciDisplayText(sciBASE_t *sci, uint8 *text, uint32 len);
void pwmSet(void);
void wait(uint32 delay);
void Lidar_without_bias(void);
void Lidar_bias(void);
void Get_Data(void);
void Lidar_enable(void);
void wait(uint32 delay)
   int i;
    for (i = 0; i < delay; i++)</pre>
       ;
}
void sciDisplayText(sciBASE_t *sci, uint8 *text, uint32 len)
   while (len--)
       while ((UART->FLR & 0x4) == 4)
       sciSendByte(UART, *text++);
void disp_set(char *str)
   char txt_buf[256] = { 0 };
   unsigned int buf_len;
   sprintf(txt buf, str);
   buf_len = strlen(txt_buf);
   sciDisplayText(sciREG1, (uint8 *) txt_buf, buf_len);
   wait(100000);
}
int main(void)
   char txt_buf[256] = { 0 };
   unsigned int buf_len;
   volatile int i ;
   int cnt = 1;
```

```
uint16 ave[2] = { 0 };
   sciInit();
   disp_set("SCI Configuration Success!!\n\r\0");
   i2cInit();
   wait(10000000);
   disp_set("I2C Init Success!!\n\r\0");
   Lidar_enable();
   disp_set("Lidar Enable Success!!\n\r\0");
   wait(1000000);
   for (;;)
       Get_Data();
       if (g_acc_flag) //1이 되었을 때 동작
       {
          uint16 tmp;
          tmp = receives[0] << 8; //8비트 두개를 합쳐서 2바이트로 저장
          tmp |= receives[1];
              if (cnt % 3 == 0)
                 tmp = (ave[0] + ave[1]) / 2; //FIR필터
                 sprintf(txt_buf, "Distance = %d\n\r\0", tmp);
                 buf_len = strlen(txt_buf);
                 sciDisplayText(sciREG1, (uint8 *) txt_buf, buf_len);
                 i = 0;
                 cnt++;
                 g_acc_flag = 0;
              }
              else
                 ave[i] = tmp; //필터를 위해 값을 저장
                 i++;
                 cnt++;
                 g_acc_flag = 0;
              }
       Lidar_without_bias(); //99번은 ACQ_COMMAND에 0x03 세팅
       bias_cnt++;
       if(bias_cnt == 100){
          Lidar_bias(); //100번째에 ACQ_COMMAND에 0x04 세팅
          bias_cnt = 0;
       }
   }
   return 0;
void Lidar_enable(void)
```

```
uint8 tmp[4] = { 0x80, 0x08, 0x00, 0x04 };
   volatile unsigned int cnt = 7;
   i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR); //LIDAR_SLAVE_ADDR 0x62
   i2cSetDirection(i2cREG2, I2C_TRANSMITTER); //전송모드
   /* 마스터 모드에서만 사용가능 전송값*/
   i2cSetCount(i2cREG2, cnt + 1);
   i2cSetMode(i2cREG2, I2C_MASTER); //마스터모드
   i2cSetStop(i2cREG2); //안정성을 위해 스탑부터
   i2cSetStart(i2cREG2); //시작
   i2cSendByte(i2cREG2, SIG_COUNT_VAL);
   i2cSend(i2cREG2, 1, &tmp[0]); //0x80
   i2cSendByte(i2cREG2, ACQ_CONFIG_REG);
   i2cSend(i2cREG2, 1, &tmp[1]); //0x08
   i2cSendByte(i2cREG2, THRESHOLD_BYPASS);
   i2cSend(i2cREG2, 1, &tmp[2]); //0x00
   i2cSendByte(i2cREG2, ACQ_COMMAND);
   i2cSend(i2cREG2, 1, &tmp[3]); //0x04
   disp_set("Lidar tmp 1 Enable Success!!\n\r\0");
   while (i2cIsBusBusy(i2cREG2) == true)
      ; //데이터가 오고 있는지
   while (i2cIsStopDetected(i2cREG2) == 0)
      ; //데이터가 다 왔는지
   i2cClearSCD(i2cREG2); //초기화
   wait(100000);
}
void Get Data()
   i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR); //LIDAR_SLAVE_ADDR 0x62
   i2cSetDirection(i2cREG2, I2C_TRANSMITTER); //전송
   i2cSetCount(i2cREG2, 1);
   i2cSetMode(i2cREG2, I2C_MASTER); //마스터모드
   i2cSetStop(i2cREG2); //스탑부터(안정성)
   i2cSetStart(i2cREG2); //시작
   i2cSendByte(i2cREG2, READ_FROM); //0x8f
   while (i2cIsBusBusy(i2cREG2) == true)
      //데이터가 오고 있는지
   while (i2cIsStopDetected(i2cREG2) == 0)
      //데이터가 다 왔는지
   i2cClearSCD(i2cREG2); //초기화
   i2cSetDirection(i2cREG2, I2C_RECEIVER); //데이터 받음
   i2cSetCount(i2cREG2, 2);
   i2cSetMode(i2cREG2, I2C_MASTER); //마스터모드
   i2cSetStart(i2cREG2); //시작
   i2cReceive(i2cREG2, 2, (unsigned char *) receives);
   while (i2cIsBusBusy(i2cREG2) == true)
//데이터가 오고 있는지
      ;
```

```
while (i2cIsStopDetected(i2cREG2) == 0)
//데이터가 다 왔는지
   i2cClearSCD(i2cREG2); //초기화
   g_acc_flag = 1; //다시 값을 받기 위하여
}
void Lidar_bias(void)
   volatile unsigned int cnt = 1;
   unsigned char data[1] = { 0x04U };
i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR);
   i2cSetDirection(i2cREG2, I2C_TRANSMITTER);
   i2cSetCount(i2cREG2, cnt + 1);
   i2cSetMode(i2cREG2, I2C_MASTER);
   i2cSetStop(i2cREG2);
   i2cSetStart(i2cREG2);
   i2cSendByte(i2cREG2, ACQ_COMMAND);
   i2cSend(i2cREG2, cnt, data);
   i2cSetStop(i2cREG2);
   while (i2cIsBusBusy(i2cREG2) == true)
   while (i2cIsStopDetected(i2cREG2) == 0)
   i2cClearSCD(i2cREG2);
   wait(1000000);
}
void Lidar_without_bias(void)
   volatile unsigned int cnt = 1;
   unsigned char data[1] = { 0x03U };
   i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR);
   i2cSetDirection(i2cREG2, I2C_TRANSMITTER);
   i2cSetCount(i2cREG2, cnt + 1);
   i2cSetMode(i2cREG2, I2C_MASTER);
   i2cSetStop(i2cREG2);
   i2cSetStart(i2cREG2);
   i2cSendByte(i2cREG2, ACQ_COMMAND);
   i2cSend(i2cREG2, cnt, data);
   i2cSetStop(i2cREG2);
   while (i2cIsBusBusy(i2cREG2) == true)
   while (i2cIsStopDetected(i2cREG2) == 0)
   i2cClearSCD(i2cREG2);
   wait(1000000);
}
```

추가설명

Lidar 기본정보

I2C Protocol Information

This device has a 2-wire, I2C-compatible serial interface (refer to I2C-Bus Specification, Version 2.1, January 2000, available from Philips Semiconductor). It can be connected to an I2C bus as a slave device, under the control of an I2C master device. It supports standard 400 kHz data transfer mode. Support is not provided for 10-bit addressing.

The Sensor module has a 7-bit slave address with a default value of 0x62 in hexadecimal notation. The effective 8 bit 12C address is: 0xC4 write, 0xC5 read. The device will not presently respond to a general call.

LIDAR_SLAVE_ADDR : 0x62 (7bit mode)

Data Baudrate: 400kHz

데이터를 얻는 방법

The simplest method of obtaining measurement results from the I2C interface is as follows:

- 1 Write 0x04 to register 0x00.
- 2 Read register 0x01. Repeat until bit 0 (LSB) goes low.
- 3 Read two bytes from 0x8f (High byte 0x0f then low byte 0x10) to obtain the 16-bit measured distance in certimeters.
 - 1. 0x00레지스터인 ACQ_COMMAND에 0x04를 세팅한다.
 - 2. 0x8f레지스터에서 데이터를 얻어온다. (2바이트)

주의사항

Receiver Bias Correction

Address	Name	Description	Initial Value		
0x00	ACQ_COMMAND	Device command			

- Write 0x00: Reset device, all registers return to default values
- Write 0x03: Take distance measurement without receiver bias correction.
- Write 0x04: Take distance measurement with receiver bias correction


Faster distance measurements can be performed by omitting the receiver bias correction routine. Measurement accuracy and sensitivity are adversely affected if conditions change (e.g. target distance, device temperature, and optical noise). To achieve good performance at high measurement rates receiver bias correction must be performed periodically. The recommended method is to do so at the beginning of every 100 sequential measurement commands.


99번까지는 ACQ_COMMAND에 0x03 세팅하고, 100번째에 ACQ_COMMAND에 0x04를 세팅하는 것을 권장


I2C – Lidar(rti 방식)


HCG 설정


TMS570L	C4357ZWT	PINMUX	RTI GI	O ESM	SCI1	SCI2	SCI3	SCI4	LIN1		
General	Driver Ena	ble R5-N	IPU-PMU	Interrupt	s VIIV	1 Genera	l VIV	1 RAM	VIM Ch		
_	ole Driver Compilation Click and mark the required modules for driver compilation from below:										
	Enable RTI of Enable GIO of Enable SCI of Enable SCI of Enable	driver **			1	■ Mark/	Unmark	all driver	3		
Enable SCI4 driver ** Enable LIN drivers Enable LIN1 driver ** / Enable SCI1 driver ** Enable LIN2 driver ** / Enable SCI2 driver **											
	 ✓ Enable I2C driver ** ✓ Enable I2C1 driver ** ✓ Enable I2C2 driver ** 										
Enable EMAC driver **											
	Enable EMIF driver **										
	Enable POM driver										
		driver CRC1 driver CRC2 driver									
		P driver EQEP1 driv EQEP2 driv									
☑ Enable ETPWM driver											

















ccs 코드

```
#include <HL_etpwm.h>
#include <HL_gio.h>
#include <HL_hal_stdtypes.h>
#include <HL_i2c.h>
#include <HL_reg_etpwm.h>
#include <HL_reg_i2c.h>
#include <HL_reg_rti.h>
#include <HL_reg_sci.h>
#include <HL_rti.h>
#include <HL_sci.h>
#include <HL_sys_core.h>
#include <stdbool.h>
#include <stdio.h>
#include <string.h>
#define UART sciREG1
#define LIDAR_SLAVE_ADDR 0x62
#define ACQ_COMMAND 0x00
#define STATUS 0x01
#define SIG_COUNT_VAL 0x02
#define ACQ_CONFIG_REG 0x04
#define THRESHOLD BYPASS 0x1C
#define READ_FROM 0x8f
#define FULL_DELAY_HIGH 0x0f
uint8 receives[2];
volatile int g_acc_flag;
void sciDisplayText(sciBASE_t *sci, uint8 *text, uint32 len);
void pwmSet(void);
void wait(uint32 delay);
void Lidar_without_bias(void);
void Lidar_enable(void);
void wait(uint32 delay)
{
   int i;
   for (i = 0; i < delay; i++)</pre>
}
void sciDisplayText(sciBASE_t *sci, uint8 *text, uint32 len)
   while (len--)
       while ((UART->FLR & 0x4) == 4)
       sciSendByte(UART, *text++);
   }
}
void disp_set(char *str)
   char txt_buf[256] = { 0 };
   unsigned int buf_len;
   sprintf(txt_buf, str);
   buf_len = strlen(txt_buf);
   sciDisplayText(sciREG1, (uint8 *) txt_buf, buf_len);
   wait(100000);
}
int main(void)
   char txt_buf[256] = { 0 };
   unsigned int buf_len;
```

```
volatile int i ;
int cnt = 1;
uint16 ave[2] = { 0 };
sciInit();
disp_set("SCI Configuration Success!!\n\r\0");
gioInit();
disp_set("GIO Init Success!!\n\r\0");
i2cInit();
wait(10000000);
disp_set("I2C <u>Init</u> Success!!\n\r\0");
Lidar_enable();
disp_set("Lidar Enable Success!!\n\r\0");
rtiInit();
rtiEnableNotification(rtiREG1, rtiNOTIFICATION_COMPARE0);
enable IRQ interrupt ();
rtiStartCounter(rtiREG1, rtiCOUNTER_BLOCK0);
disp_set("RTI <u>Init</u> Success!!\n\r\0");
etpwmInit();
disp_set("ETPWM Configuration Success!!\n\r\0");
etpwmStartTBCLK();
wait(1000000);
for (;;)
   if (g_acc_flag)
   {
       uint16 tmp;
       tmp = receives[0] << 8;</pre>
       tmp |= receives[1];
           if (cnt % 3 == 0)
           {
               tmp = (ave[0] + ave[1]) / 2;
               sprintf(txt_buf, "Distance = %d\n\r\0", tmp);
               buf_len = strlen(txt_buf);
               sciDisplayText(sciREG1, (uint8 *) txt_buf, buf_len);
              i = 0;
              cnt++; //4
               g_acc_flag = 0;
           else
               ave[i] = tmp; //0 1
              i++; //1 2
               cnt++; //2 3
               g_acc_flag = 0;
           }
   Lidar_without_bias();
```

```
return 0;
void Lidar_enable(void)
   uint8 tmp[4] = { 0x80, 0x08, 0x00, 0x04 };
   volatile unsigned int cnt = 7;
   i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR);
i2cSetDirection(i2cREG2, I2C_TRANSMITTER);
   i2cSetCount(i2cREG2, cnt + 1);
   i2cSetMode(i2cREG2, I2C_MASTER);
   i2cSetStop(i2cREG2);
   i2cSetStart(i2cREG2);
   i2cSendByte(i2cREG2, SIG_COUNT_VAL);
   i2cSend(i2cREG2, 1, &tmp[0]); //0x80
   i2cSendByte(i2cREG2, ACQ_CONFIG_REG);
   i2cSend(i2cREG2, 1, &tmp[1]); //0x08
   i2cSendByte(i2cREG2, THRESHOLD_BYPASS);
   i2cSend(i2cREG2, 1, &tmp[2]); //0x00
   i2cSendByte(i2cREG2, ACQ_COMMAND);
   i2cSend(i2cREG2, 1, &tmp[3]); //0x04
   disp_set("Lidar tmp 1 Enable Success!!\n\r\0");
   while (i2cIsBusBusy(i2cREG2) == true)
   while (i2cIsStopDetected(i2cREG2) == 0)
   i2cClearSCD(i2cREG2);
   wait(100000);
}
void rtiNotification(rtiBASE_t *rtiREG, uint32 notification)
{
   i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR);
   i2cSetDirection(i2cREG2, I2C_TRANSMITTER);
   i2cSetCount(i2cREG2, 1);
   i2cSetMode(i2cREG2, I2C_MASTER);
   i2cSetStop(i2cREG2);
   i2cSetStart(i2cREG2);
   i2cSendByte(i2cREG2, READ_FROM);
   while (i2cIsBusBusy(i2cREG2) == true)
   while (i2cIsStopDetected(i2cREG2) == 0)
   i2cClearSCD(i2cREG2);
   i2cSetDirection(i2cREG2, I2C_RECEIVER);
   i2cSetCount(i2cREG2, 2);
   i2cSetMode(i2cREG2, I2C_MASTER);
   i2cSetStart(i2cREG2);
   i2cReceive(i2cREG2, 2, (unsigned char *) receives);
   i2cSetStop(i2cREG2);
   while (i2cIsBusBusy(i2cREG2) == true)
   while (i2cIsStopDetected(i2cREG2) == 0)
   i2cClearSCD(i2cREG2);
   g_acc_flag = 1;
```

```
void Lidar_without_bias(void)
{
   volatile unsigned int cnt = 1;
   unsigned char data[1] = { 0x03U };
   i2cSetSlaveAdd(i2cREG2, LIDAR_SLAVE_ADDR);
   i2cSetDirection(i2cREG2, I2C_TRANSMITTER);
   i2cSetCount(i2cREG2, cnt + 1);
   i2cSetStop(i2cREG2, I2C_MASTER);
   i2cSetStop(i2cREG2);
   i2cSetStart(i2cREG2);
   i2cSendByte(i2cREG2);
   i2cSend(i2cREG2, cnt, data);
   i2cSetStop(i2cREG2);

   while (i2cIsBusBusy(i2cREG2) == true)
    ;
   while (i2cIsStopDetected(i2cREG2) == 0)
   ;
   i2cClearSCD(i2cREG2);
   wait(1000000);
}
```